

Douglas County Surveyor's Record of
Government Corners Renewed

T 30 S. T. S. R. 9 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Byron and
Crew
Dec. 4, 1962
C.S. File
49/100

Section Corner to Sections 15 - 16 - 21 - 22.
Found - Orig. 12"; now 30" Fir Stump N.30 $\frac{1}{2}$ °W. 34.3 ft. We open & find
Good Scribing.
Orig. 18", now 36" Cedar N.21°E. 27.1ft. No other BT's. found.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
S16 | S15 T30S R9W
S21 | S22
New BT's: 8" R.Fir bears N.24°W. 7.4 ft. scribed S16 T30S R9W CS BT.
7" R.Fir bears N.55°E. 6.4 ft. scribed S15 T30S R9W CS BT.
6" Chinquapin bears S.85°W. 3.4 ft. scribed S21 CS BT.
6" R.Fir bears S.47°E. 39.6 ft. scribed S22 CS BT.

25

James W.
Byron and
Crew
March 15,
1963
C.S. File
No. 49/100

$\frac{1}{2}$ Corner to Sections 4 and 3.
Found - 4" x 4" scribed Post at corner & both BT's. as recorded
by B.B. Irving, 1927. *Ren. 11/27
28", now down Fir Stump S.36°W. 10.4 ft.
22", now 24" Fir Stump N.26°E. 11.8 ft., shows scribing.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
 $\frac{1}{2}$ S4/S3 T30S R4W.
New BT's: 15" Hemlock bears N.76°E. 28.0 ft. scribed $\frac{1}{2}$ S3 CS BT.
7" Hemlock bears N.27°W. 42.1 ft. scribed $\frac{1}{2}$ S 4 CS BT.
Note - Corner is 75 ft. North of Road.

26

SEE M 85-17
FOR CONDITION
REPORT.

Corner to Sec. 31, T29-9W. & Sec. 36, T29-10W.
Wright's Corner North Boundary of T30-10W.
Found - 2' x 1 $\frac{1}{2}$ ' x 6" Rock with "29 CC", six notches & an "X" from which a:
60" D.Fir Snag, with scribes "36 BT" visible, bears N.55°W. 92.4 ft.
Old Cedar Snag, with scribes "BT 3-T29-R9" vis., bears
N.21°E. D. 5 ft. (record - 66.0 ft.)
D. Fir Stump bears S.22°E. 4.6 feet.
Scribed - 16" D.Fir, I scribed "S36 BT", bears N.24°W. 19.5 feet.
12" D.Fir, I scribed "S31 BT", bears N.29°E. 8.3 feet.

27

Bruce A. Shaner
For Evans Products
Jan. - April 1963
Map File R. M. 1 - 36

North East Corner Section 1, T30S R10W.
Porter's Corner: Found a rock with 6 notches on S. side & 7 notches
on W. side; I Set a Nail, from which a:
6" Ching. BT (record Myrtle) bears S.64°W. 9.9 ft.
(old face is all rotted out)
18" D.Fir, I scribed "S1 T30S R10W BT" bears S.38°W. 34.0 feet.

28

Northwest corner Section 6, T30-9W.
Hathorn's Corner - Found - 32" x 32" x 18" Stone marked "CO" with
6 notches on both S. & E. sides;
I set a nail from which an
"X" on a 2' x 1' x 3" Rock bears S.70°E. 14.7 ft. (record 13.2 ft.)
"X" on a 4' x 5" Rock, (also scribed "BO") bears N.68°E. 18.5 ft.

29

$\frac{1}{2}$ Corner Common to Sec. 6, T30-9W. & Sec. 1, T30-10W.
Found - No evidence of any earlier surveys, so as per instructions by letter
from the Area Cad. Eng., Mr. Tillman, dated March 29, 1963, I
Set the $\frac{1}{2}$ corner by proportional measurement, using Bushey's 1893
retracement figures and the Hathorn Township Corner.
Set 5/8" x 36" Iron Rod from which a:
8" Hemlock, I scribed " $\frac{1}{2}$ S S1 BT", bears N.80°W. 55.4 feet.
16" P. Orford Cedar, I scribed " $\frac{1}{2}$ S S6 BT", bears N.34°E. 60.4 feet.

30

James W. Byron
& Crew.
May 10, 1963
C.S. File
No. 49/100

$\frac{1}{2}$ Corner to Sections 15 and 14.
Found - Base Section of down & rotted Fir, shows good scribing "BT2".
Down Cedars to N.E.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
 $\frac{1}{2}$ S15/S14 T30S R9W
New BT's: 7" Fir bears S.25°E. 11.8 ft. scribed $\frac{1}{2}$ S14 CS BT.
5" Fir bears S.52°W. 34.5 ft. scribed $\frac{1}{2}$ S15 CS BT.

31

FD OK
10/2001
K. Hoffine
M138-79

SE Fir
2nd Snag