

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T.S. R. 9 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Sec. Cor. to Sections 27 - 28 - 33 - 34.

Found - 48", now 52" Fir N. $74\frac{1}{2}^\circ$ E. 28 $\frac{1}{2}$ lks., good scar on tree.
10", now 20" Cedar S. 9° E. 42 $\frac{1}{2}$ lks., good scar on tree.
30", now 35" Cedar S. $55\frac{1}{2}^\circ$ W. 57 $\frac{1}{2}$ lks., good scar on tree.
30" Cedar Stump N. 25° W. 99 lks., opened for BT. scribe.
12 x 10 x 10 Stone at corner 1 notch on S. -3 notches on E.

Set - Set Brass Cap at Cor. Mkd: County Surveyor's Office, 1965
T30SR9W S 28 | S 27
S 33 | S 34

New BT: 14" Cedar bears N. 79° W. 17.8 ft. scribed T30S R9W S28 CS BT.

FD OK
4/95
K. W. HOFFMAN
M 119-59
72
Fd. CC. 7/51
BLM ADMIN. FILE
SEE GSS
FILE

$\frac{1}{4}$ Corner to Sections 33 and 34.

Found - 11", now 15" Cedar for Corner Tree, " $\frac{1}{4}$ S" scribed on West Side.
15", now 27" D. Fir N. $86\frac{1}{2}^\circ$ W. 24 lks.
12", Fir S.E., no trace of this tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965
T30S R9W $\frac{1}{4}$ S 33/S 34

Cap is set very close to 15" Cedar Tree on the West Side.

New BT's: 27" D. Fir N. $86\frac{1}{2}^\circ$ W. 15.8 ft. scribed $\frac{1}{4}$ S33 CS BT.
22" D. Fir N. 80° E. 38.0 ft. scribed $\frac{1}{4}$ S34 CS BT.

Note - This corner is about 66 ft. on the north side of ridge top.

$\frac{1}{4}$ Corner to Sections 26 and 27.

Found - Stone marked " $\frac{1}{4}$ " on West Face for Corner. 212007 M 152-35
10", now 29" Fir N. $71\frac{1}{2}^\circ$ W. 94 $\frac{1}{2}$ lks., found scribing "S".
8" Fir N. $48\frac{1}{2}^\circ$ E. 57 lks. (no trace of tree, fell in fire trail.)

Set - Brass Cap at $\frac{1}{4}$ Cor. Mkd: County Surveyor's Office, 1965
T30S R9W $\frac{1}{4}$ S 27/S 26

New BT's: 11" D. Fir bears S. $37\frac{1}{2}^\circ$ E. 15.0 ft. mkd: $\frac{1}{4}$ S26 CS BT.
13" D. Fir bears S. 10° W. 11.0 ft. mkd: $\frac{1}{4}$ S27 CS BT.

Note - This corner is about 80 ft. from the ridge top on the South Slope.

$\frac{1}{4}$ Corner to Sections 6 and 7.

Found - Brass Cap at Corner mkd: T30S R9W $\frac{1}{4}$ S 6 | U.S. Dept.
1962 S 7 | of Interior

22" D. Fir S. $42\frac{1}{2}^\circ$ E. 8 lks. $\frac{1}{4}$ S6 BT.

13" D. Fir N. 35° W. 42 lks. $\frac{1}{4}$ S7 BT. This tree rotten in trunk and cracked. Also in area of a lot of blowdown.

Orig. 5" Fir S. 46° E. 78.5 ft., tree opened, no scribe visible.
Do not find NE BT. 5.46° E per C.S. 53/53... 7/3/84 Bill S.

New BT: 20" D. Fir N. 44° E. 16.7 ft. scribed $\frac{1}{4}$ S6 CS BT.

FD OK
6/84
E. GEINER
M 97-9

Section Corner to Secs. 29 - 30 - 31 - 32.

Found - Broken Stone at Sec. Corner.
16" Hemlock N. $77\frac{3}{4}^\circ$ E. 50 $\frac{1}{2}$ lks., rotten stump.
6" Cedar, now 16", S. $32\frac{1}{2}^\circ$ W. 7 lks., open & find scribe "30S".
18" Cedar, now 34" S. $79\frac{1}{2}^\circ$ E. 44 lks., shows good scar.
14" Cedar, now 23", N. $19\frac{1}{4}^\circ$ W. 38 lks., shows good scar.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965
T30S R9W S 30 | S 29
S 31 | S 32

New BT's: 17" Cedar S. 73° W. 4.4 ft. scribed T30S R9W S31 CS BT.
42" Hemlock N. 72° E. 50.0 ft. " T30S R9W S29 CS BT.

$\frac{1}{4}$ Corner to Sections 16 and 15.

Found - 36" Cedar, now 60", N. 70° E. 29 lks., open & find scribing "4".
12" Live Oak S. 45° W. 11 lks., no trace of this tree.

Set - Brass Cap at $\frac{1}{4}$ Cor. Mkd: County Surveyor's Office, 1965
T30S R9W $\frac{1}{4}$ S 16/S 15

New BT's: 60" Cedar N. 70° E. 22.2 ft. scribed $\frac{1}{4}$ S15 CS BT.
26" Live Oak N. 19° W. 43.4 ft. scribed $\frac{1}{4}$ S16 CS BT.

$\frac{1}{4}$ Corner to Sections 8 and 9.

John M. Powell
Frank Jones and Joe Brady
October 1965
C. S. File No. 53/53

FD OK 2/94 BY SMALLER M 119-18
76

176