

Douglas County Surveyor's Record of  
Government Corners Renewed

30 S T. S. 9W R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

119

1/4 Corner for Sections 29 and 32

Found: Original BT, 17" fir, now a snag, bears S.7°W (S.3°W.) 23.1 feet with visible scribe "1/4S".  
Original BT, 40" fir, now a stump, bears N.58°E., (N.54°E.) 9.6 feet with visible scribe "1/4 S BT".  
Set: 1 1/2" Iron pipe with brass cap.  
New BT's: 6" D. Fir bears N.13°E., 26.3 feet scribed 1/4 S29BT.  
50" D. Fir bears S.14°E., 29.8 feet scribed 1/4 S32 BT.

Eugene A. Bloom LS#492  
For: Roseburg Lumber Co.  
March 6, 1980  
M 79 - 23

120

1/4 Corner for Sections 31 and 32.

Found: Original 33" Fir, now a stump, bears S.42°W., 17.8 feet with visible scribe "BT".  
No trace of S32 BT, but did find large root hole.  
Set: 1 1/2" iron pipe with brass cap.  
New BT's: 6" Madrone bears S.39°W., 50.6 feet scribed "1/4 S31BT".  
6" Chinquapin bears N.68°E., 56.0 feet scribed "1/4 S32BT".

Donald Bentz  
For: Roseburg Lumber  
April 1980  
M 82 - 79

1/4 Corner for Sections 15 and 22.

Set - 5/8" Iron rod with alum. cap  
BT's 18" Cedar bears N.70°W., 23.0 ft. scribed "1/4 S 15 BT".  
8" Douglas Fir bears S.80°E., 9.2 ft. scribed "1/4 S15 BT".  
#190 4/80

FD OK K. Hoffmeier  
10/2001  
M 138-79

121

R.M.

1/4 Corner for Secs. 5 and 6.

Found - 1962 GLO Reference monument brass cap iron pipe from which 1/4 S 6/S5 bears N.45°E., 50 lks. (33.0 ft.)  
12" Hemlock bears S.24°W., 45 lks. (29.7 ft.)  
Orig. Fir, now down with visible opened face bears S.36 1/2°E., 38.7 lks.  
Set 3" Boat spike in bedrock at corner location.

Ronald Stuntzner  
For: Dept. of the Interior (BLM)  
Aug. 8, 1980  
M 85 - 18

122

Center 1/4 Corner for Section 5.

Set - 2" x 2" x 36" Cedar hub from which:  
26" Hemlock bears S.35°W., 19.9 ft. to spike, 21.2 ft. @ tree.  
12" Hemlock bears N.23°E., 13.2 ft. to spike, 14.2 ft. @ tree.  
8/8/80

123

Ronald Stuntzner  
For: Dept. of the Interior (BLM)  
8/8/80  
M 85 - 17

Center 1/4 Corner for Section 4.

Set - 2" x 2" x 36" Cedar hub  
From which:  
28" D. Fir bears S.18°W., 6.9 ft. to spike, 8.0 ft. @ tree;  
24" POC bears S.89°E., 37.0 ft. to spike, 38.3 ft. @ tree.

SEE CORNER NO. 156

124

1/4 Corner for Secs. 17 and 16.

Found - 34" stump, (orig. 30" Fir BT) bears N.63°W., 24 lks. which has plain scribes.  
34" stump, (orig. 30" Fir BT) bears N.48 1/2°E., 42 1/2 lks. with plain scribes.  
Set - 3/4" brass cap pipe marked "GP 1/4 Cor 17/16 T30 R9 1979"  
New BT's- 16" Hemlock, N.43°45'E., 59.7 ft. scribed "1/4 S 16 BT 378".  
16" Oak, N.29°45'W., 59.7 ft. scribed "1/4S 17 BT" in the bark.  
4/19/79

Jack LaFlamme  
For: Georgia Pacific  
April 19, 1979  
C.S. 58/249

125

Section corner for Secs. 31 and 32; and 6 & 5 of T.31-9

Found - A 1965 County brass cap properly marked on a 1" I.P. firmly set protrudes 18 1/2" above ground. Ren. #91  
A 1 1/4" I.P. protrudes 18" from the ground on the south edge of brass cap. Ren. #33  
A 14"x10"x8" stone is set on the west side of the brass cap. Stone is mkd. with 5 notches on its east edge, no marks fd. on the west edge (broken). (Rec. 5 notches on east, 1 notch on west) 1893 retracement.  
An iron fence post protrudes 42" from ground on the southwest edge of the brass cap.

S. J. Flause, Deputy  
Douglas Co. Surveyor  
T. Plouff; K. Mosely  
April 7, 1981  
C.S. 61/19

126

147