

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 30 T. S. R. 9 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

C O N T. - - - - -

Douglas County
Surveyors Office
Randall Smith
Ed Monrean
Sept. 21, 1992
C.S. 64/32

10" Oak now 15" dia. Chinquapin w/small healed blaze
5 ft. above ground & a rotted out center bears S.51°E., 20.4 ft.
(agrees w/Rec.) Ren. No. 33
New BTs - 6" dia. Chinquapin double blazed and scribed "T31S R9W S5 CS BT"
bears S.30°E., 15.4 ft.
5" dia. Chinquapin double blazed and scribed "X BT" bears
N.42°E., 19.8 ft.

9/21/92

Section corner for Secs. 19 & 30; 24 & 25 T. 30-10
Found - 1965 County BCIP out of the ground. Reset from bearing
trees. See renewal # 85.

BTs - 14" Fir, N.52 1/2°W., 19.8 ft. snag, orig. BT.
30" Cedar, N.30°E., 24.8 ft. healed face.
12" Fir, N.84°E., 46.2 ft. found scribe.
30" Fir, S.51 1/4°E., 31.0 ft. rotten stump, orig. BT.
32" Fir, S.22°W., 22.0 ft. rotten stump, orig. BT.
34" Fir, N.27°E., 12.2 ft. rotten stump, orig. BT.
Scribed-12" Fir, N.83°W., 8.3 ft. "S24BT"
8" Cedar, S.6°E., 20.1 ft. "S30BT"
6" Cedar, S.6°W., 23.4 ft. "S25BT"

1/4 Corner for Sections 19 & 30.

Found - Original stone, 8'x7'x6' marked 1/4 on north, and 'X' on top.
BTs - 38" Cedar, N.17 1/2°E., 32.7 ft. stump, orig. BT.
Scribed-8" Fir, N.4°W., 13.4 ft. "1/4 BT"
14" Fir, N.41°E., 15.5 ft. "1/4 BT"
12" Fir, EAST, 13.0 ft. "1/4 BT"
10" Fir, S.54°W., 14.8 ft. "1/4 BT"

Section Corner for Sections 19, 20, 29 & 30.

FO. OK BY G. SMITHER JAN. 2001
M 136-54 150

Found - 1965 County Brass cap/iron pipe. See renewal # 65.
BTs - 38" Fir, N.71 1/4°W., 42.2 ft. healed face, orig. BT.
22" Fir, N.23 3/4°E., 38.9 ft. healed face, orig. BT.
40" Fir, S.54°E., 49.2 ft. healed face, orig. BT.
54" Fir, S.82°W., 67.8 ft. healed face.
14" Cedar, N.46°E., 26.0 ft. "X" blazed on tree.

1/4 Corner for Section 30; Section 25 T. 30-10

Found - Original stone, broken, marked "1/4"
BTs - 48" Fir, N.50 1/2°W., 30.4 ft. snag, orig. BT.
Scribed-17" Fir, N.88°W., 16.6 ft. "1/4 S25 BT"
17" Fir, N.2°E., 8.1 ft. "1/4 S30 BT"
11" Fir, S.20°E., 22.3 ft. "1/4 S30 BT"
14" Fir, S.19°W., 18.9 ft. "1/4 S25 BT"

1/4 Corner for Sections 30|29

Found - County Brass cap/iron pipe. See renewal # 79.
BTs - 48" Fir stump, S.67 1/2°E., 117.5 ft. scribe visible, orig. BT
8" Fir, S.18 1/2°E., 10.7 ft. healed face.
32" Cedar stump, S.32 3/4°W., 20.8 ft. scribe visible, orig.
BT.
10" Fir, S.30°W., 13.9 ft. healed face.
Scribed-8" Fir, N.19°W., 8.3 ft. "1/4 S30 BT"
11" Fir, N.55°E., 19.0 ft. "1/4 S29 BT"

Section Corner for Sec's 30 & 31; 25 & 36 T.30-10

Found - 1965 County Brass cap/iron pipe. See renewal # 82.
BTs - 45" Cedar, N.68°W., 9.9 ft. stump, orig. BT.
24" Cedar, N.68°E., 20.5 ft. stump, scribe vis. orig. BT.
40" Fir, S.50°E., 16.3 ft. stump, scribe visible.
Scribed-9" Fir, N.56°E., 28.6 ft. "S30 BT"
7" Fir, S.4°W., 10.7 ft. "S36 BT"
7" Fir, S.55°W., 7.9 ft. "S36 BT"

Mark Smalley
For: Roseburg Forest Products
M 119 - 18
Feb. 1994

153