

Douglas County Surveyor's Record of
Government Corners Renewed

30

T.S.

9

R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Gary
Smithers

Mar. 16 2001

C.S. File
65/37-3

East 1/4 Corner *Sec 8*

2004/2005 BLM
Resurvey Pg 21277 *FOok* 173

Found - 1965 County Brass cap on iron pipe firmly set
alongside orig. stone monument. (Ren. #78)
33" D.Fir N.80°E., 26 lks. w/healed face & alum tag
18" D.Fir N.19 3/4°W., 22 3/4 lks. has fallen down.
New BTs - 15" Maple, S.67°W., 14.8 ft. to spike driven in
side center, mkd. "¼ S8 BT" with BT tag.
57" D.Fir, S.36°W., 17.4 ft. to spike driven in
side center, mkd. "¼ S9 BT" with BT tag.
13" D.Fir, N.48°E., 32.9 ft. to spike driven in
side center, mkd. "¼ S9 BT" with BT tag.

NE Corner Sec. 8

174

Found - 1962 BLM brass cap on iron pipe firmly set alongside
orig. stone monument.
All record BTs gone.
New BTs - 10" D.Fir, S.85°W., 15.7 ft. to spike driven in side
center, mkd. "T30 R9 S8 BT" with BT tag.
7" D.Fir, S.71°E., 5.4 ft. to spike driven in side
center, mkd. "X" @ breast height & "BT" at base,
with BT tag.
12" D.Fir, N.68°E., 25.1 ft. to spike driven in side
center, mkd. "T30 R9 S4 BT" with BT tag.
11" D.Fir, S.20°E., 18.8 ft. to spike driven in side
center, mkd. "T30 R9 S4 BT" with BT tag.
Nothing was suitable for BT in Sec. 5.

C.S. File
65/37-4

Cor. Secs. 14, 15, 22, & 23

175

Found - 1963 Douglas Co. cap 1.2 ft above ground. (Ren. #32)
21" Grand Fir bears S.17 1/4°W., 66.3 ft. (rec. S.18°W.,
66.1 ft.) well healed face & tag.
10" Port Orford Cedar bears S.74°W., 14.3 ft. (no
rec.) BT tag that reads S.74°E. 14.4 ft. No face
25" Port Orford Cedar bears N.69°E., 5.7 ft. (no rec)
chopped out face with visible scribing.
18" Grand Fir bears S.63°W., 21.4 ft. as per rec.
Down Fir rootwad in SW quadrant (Rec. S.65°W., 15.8
ft.)
Corner lies on gentle NE slope in second growth conifer stand.

Ken Hoffine
For: Lone Rock
Timber Co.
10/2001
M138-79

1/4 Cor. Secs. 15 & 16

#189

176

Found - Coos County brass cap 1.2 ft. above ground. *ren #77*
60" broken down Cedar snag bears N.70°E., 22.2 ft.
(rec. N.70°E. 19.14 ft) chopped out face visible
scribing & BT tag.
Stump remains of 26" Live Oak bears N.19°W., 43.4 ft.
as per rec.
No trace of 12" Live Oak S.45°W., 7.3 ft.
16" D.Fir bears S.15°E., 24.3 ft. I tag tree.
Corner lies on 40% south slope in extremely heavy brush &
scattered young D.Fir timber.

1/4 Secs. 1 & 12

SEE BLM Resurvey
V.54 Pg. 20795

177

Found - 2002 BLM Brass cap (not of rec. as of 8/2003)
16" DF with visible scribes - bears N.63 1/2°W., 30.8'
19" DF with visible scribes - bears S.4°W., 24.1'
Scribed- "¼ SS BT" on 8" GF - bears N.1°W., 3.0 ft.
"¼ S12 BT" on 10" DF - bears S.53°E., 26.9 ft.
Note - Per narrative - *some* corners established on M101-44 were
set incorrect. The N 1/4 S12 monument was pulled
per Roseburg Resources request. (Ren. #144)

Tony Hostetter
For: Rsbj Resources
May/July 2003
M142-67