

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 31 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31881

Section Corner to Sections 33 & 34, T30-1W. 42  
Found - G. L. O. Brass Cap, properly marked in 1923.  
Orig. 38" D. Fir, now dead, N. 59° W. 21.8 ft., scribe visible, "T30 RW BT".  
Orig. 30" D. Fir, now down, S. 35° E. 11.9 ft.  
Orig. 40" D. Fir, now stump, N. 72° E. 58.7 ft.  
No trace of S.W. BT.  
New BT's: 5" S. Fir N. 21° W. 6.8 ft. mkd. T30S RLW S33 CS BT.  
12" S. Fir N. 24° E. 21.5 ft. mkd. T30S RLW S34 CS BT.

Dec. 26, 1967

Sec. Cor. to Section 1, T31-1W. & Sec. 36, T30-1W only. 43  
Found - Corner Stone, no marks.  
30" D. Fir, now 40" Stump, S. 30° W. 16.5 ft., opened & fd. scribe.  
26" D. Fir, now 28" Snag, N. 2° W. 16.5 ft., opened & fd. scribe.  
Set - Brass Cap at Sec. Cor. Mkd: County Surveyor's R T 30 S R  
Office 1 S 36 | S31 1  
W S 1 | E  
T 31 S

New BT's: 6" Cedar S. 60° W. 10.4 ft. scribed T31S RLW S1 CS BT.  
36" D. Fir N. 18° W. 15.2 ft. scribed T30S RLW S36 CS BT.  
Note -  $\frac{1}{4}$  Corner to section 31 only is D.K. & lies N. 236.3 ft., both corners on steep, west slope.

Jan. 1968

Sec. Cor. to Secs. 32 & 33, T30-1W. & Secs. 4 & 5, T31-1W. 44  
Found - GLO Brass Cap, 1923, properly marked.  
15", now 28" D. Fir, S. 88° W. 9.2 ft., shows good scar.  
20", now 34" D. Fir N. 40° E. 9.9 ft., shows good scar.  
12", now 18" Laurel, S. 75° E. 10.6 ft., shows scar. #203  
18" Pine, now stump, N. 84° W. 30.3 ft.  
New BT: 12" D. Fir N. 59° W. 36.3 ft. mkd. T30S RLW S32 CS BT.  
Note - This corner lies approx. 65.0 ft. S. of spring bank.

2/5/68

$\frac{1}{4}$  Corner to Sec. 32, T30-1W. and Sec. 5, T31-1W. 45  
Found - 50" S. Pine S. 87° E. 115.5 ft., scribe visible " $\frac{1}{4}$ S".  
No trace of N.W. BT., falls in old skid road.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S  
Office, 1968 T 31 S RLW S 32  
S 5  
New BT's: 14" D. Fir N. 57° E. 23.6 ft. mkd.  $\frac{1}{4}$  S32 CS BT.  
15" D. Fir S. 22° E. 35.2 ft. mkd.  $\frac{1}{4}$  S 5 CS BT.

$\frac{1}{4}$  Corner to Section 4 only. 46  
Found - GLO Brass Cap, 1923, properly marked.  
28" D. Fir, now stump, S. 66° E. (Rec. S. 69 $\frac{1}{2}$ ° E.) 16.5 ft., opened for scribe  
No trace of N.E. Bearing Tree.  
New BT's: 11" R. Fir S. 83° E. 29.2 ft. mkd.  $\frac{1}{4}$  S 4 CS BT.  
10" Yew N. 11° E. 22.1 ft. mkd.  $\frac{1}{4}$  S4 CS BT.  
Note - This corner lies 26.4 ft. south of  $\frac{1}{4}$  Corner Section 5 only, below.

$\frac{1}{4}$  Corner to Section 5 only. 47  
Found - GLO Brass Cap, 1923, properly marked.  
28" D. Fir, now down, S. 51° W. 9.9 ft., shows good scar.  
14" Cedar, now dead, N. 26° W. (Rec. N. 23° W.) 19.8 ft., shows parts  
No trace of N.E. BT. of bark scribe.  
New BT's: 10" R. Fir S. 50 $\frac{1}{2}$ ° W. 30.3 ft. mkd.  $\frac{1}{4}$  S 5 CS BT.  
12" D. Fir N. 76° W. 39.0 ft. mkd.  $\frac{1}{4}$  S 5 CS BT.  
Note - This corner lies 26.4 ft. north of  $\frac{1}{4}$  Cor. Sec. 4 only, see above.

Section Corner to Sections 34 and 35, T30-1W. 48  
Found - G.L.O. Brass Cap at corner, properly marked in 1923.  
14", now 16" W. Oak, N. 45° E. 33.7 ft., scribe visible, "35".  
18", now 36" D. Fir, S. 40° E. 4.0 ft., shows good scar.  
18", now down, D. Fir, N. 80° W. 17.8 ft.  
New BT: 12" D. Fir N. 24° W. 15.6 ft. mkd. T30S RLW S34 CS BT.  
N.E. and S.E. Bearing Trees, O.K. and Tagged.  
Note - This cor. is on W. slope 207.5 ft. E. of Cor. Secs. 3 & 2, T31-1W.  
7/5/68

John M. Powell  
Frank Jones & W. Penly  
February, 1968  
C. S. File No. 54/59

RE-RENEWED SEE CORNER NO. #203

SEE CORNER NO. #185