

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 1 W. R.W.W.M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 4 and 9 only. 73
 Found - 14" D.Fir, now burnt stob, N. 39° W. 15.2 ft., faint scribe visible, "T31S RLW".
 14" D.Fir, now burnt stob, S. 41° W. 36.3 ft., found scribing.
 GLO Brass Cap, properly marked in 1923.
 New BT's: 9" D.Fir N. 68° W. 18.9 ft. mkd: T31S RLW S 4 CS BT.
 9" D.Fir S. 66° W. 9.7 ft. mkd. T31S RLW S9 CS BT.
 11" D.Fir East 7.3 ft. mkd: T31S RLW S3 CS BT.

Section Corner to Sections 3 and 10 only. 74
 Found - 14" Yew S. 45° E. 38.3 ft., scribe visible, T31S RLW S10 BT.
 26" D.Fir, now down, N. 56° E. 15.2 ft.
 No trace of 1923 GLO Brass Cap, area logged. Used metal finder to look for cap with no results.
 Set - Brass Cap at Cor. Mk'd: County Surveyor's Office T 31 S R 1 W
 1968 S 9 S 3
 S 10
 New BT's: 11" Cedar N. 37° W. 96.3 ft. mkd: T31S RLW S9 CS BT.
 10" D.Fir N. 36° E. 105.3 ft. mkd. T31S RLW S3 CS BT.
 Note - This corner lies on east edge of swampy area.
 I could not chain between corners because of water.

¼ Corner to Section 3 only. 75
 Found - GLO Brass Cap for ¼ Corner, properly marked in 1923.
 24", now 28" D.Fir, N. 69° E. 11.2 ft., shows good scar.
 36" D.Fir, now stump, S. 52° E. 29.0 ft., opened for scribe "BT".
 New BT: 6" Hemlock S. 15° E. 56.4 ft. mkd. ¼ S3 CS BT.
 Note - This corner lies 267.9 ft. south of ¼ Cor. Sec. 4 only, which was found in good condition, 1923 Brass Cap and BT's. O. K.

¼ Corner to Section 16 only. 76
 Found - 1923 GLO Brass Cap in place.
 20" Fir, now 26" Stump, S. 51° W. 29.0 ft., shows scar.
 16" Fir, now 16" Stump, N. 17° W. 32.2 ft., shows scar.
 New BT's: 12" Red Fir N. 30° W. 7.2 ft. mkd: ¼ S16 CS BT".
 7" Red Fir S. 26° W. 18.0 ft. mkd: ¼ S16 CS BT".
 This corner lies on westerly slope 87.8 ft. N. of ¼ Cor. Sec. 15.

Section Corner to Sections 9 and 16 only. 77
 Found - 1922 Brass Cap (GLO) in place.
 20" D.Fir, now stob, S. 51° W. 30.4 ft., shows scribing "SW".
 18", now 30" D.Fir, N. 1° W. 39.6 ft., shows good face.
 New BT: 24" D.Fir S. 89½° W. 5.7 ft. scribed "T31S RLW S16 CS BT".
 This corner lies 129.6 ft. north of Sec. Cor. 10 & 15 only, and lies on top of a flat ridge.

Closing Corner to Sections 10 and 15. 78
 Found - 1922 GLO Brass Cap in place.
 16" D.Fir, now stump hole, N. 84° E. 27.1 ft., found no scribing.
 No trace of S. E. Bearing Tree.
 New BT's: 5" D.Fir N. 85½° E. 17.7 ft. scribed "S10 CC CS BT".
 7" D.Fir S. 66° E. 19.0 ft. scribed "T31S RLW S15 CC CS BT".
 Note - This corner lies 129.6 ft. S. of Sec. Cor. 9 & 16, which is the record, and lies on top of a flat ridge.

¼ Corner to Section 9 only. 79
 Found - 1923 GLO Brass Cap at ¼ corner, in place.
 36", now 39" D.Fir, S. 75° W. 24.4 ft., shows good scar.
 36", now 39" D.Fir, N. 30° W. 25.1 ft., shows good scar.
 New BT's: 9" Cedar S. 72° W. 5.6 ft. scribed "¼ S9 CS BT".
 This corner lies 129.4 ft. north of ¼ corner Sec. 10 only. All Trees Tagged.

John M. Powell
 Frank Jones & W. Penley
 August, 1968
 C. S. File No. 54/71