

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

114

Section Corner to Sections 4 - 5 - 8 - 9.
Found - G.L.O. Brass Cap, properly marked in 1923.
30", now 38" D. Fir, N. 83* E. 19.8 ft., shows good scar.
14", now 17" Hemlock, S. 57* E. 33.0 ft., shows good scar.
18", now 22" Hemlock, S. 57* W. 27.7 ft., shows good scar.
18", now down Hemlock, N. 12* W. 23.1 ft.
New BT: 8" Hemlock N. 43* W. 44.0 ft. scribed T31S R1W S5 CS BT.

115

$\frac{1}{4}$ Corner to Section 4 and 9.
Found - G.L.O. Brass Cap, properly marked in 1923.
30" D. Fir, now burnt stob, N. 31* W. 27.7 ft., burnt face with
paint scribe marks.
30", now 37" D. Fir S. 1* W. 23.1 ft., shows good scar.
New BT's: 6" D. Fir N. 41* W. 10.8 ft. scribed " $\frac{1}{4}$ " S4 CS BT.
8" D. Fir S. 59* E. 20.8 ft. scribed " $\frac{1}{4}$ " S9 CS BT.
Note - This corner lies on a flat bench E. of ridge top about
15 chains, just E. of green timber.

116

$\frac{1}{4}$ Corner to Section 27 only.
Found - G.L.O. Brass Cap, properly marked in 1922.
7", now 14" D. Fir, N. 19* W. 11.2 ft., shows good scar.
No trace of N. E. Bearing Tree.
New BT: 24" D. Fir N. 65* W. 35.3 ft. scribed " $\frac{1}{4}$ " S27 CS BT".
Note - $\frac{1}{4}$ Corner of Section 34 only bears west 49.5 ft.
Also fence bears North 11.0 ft.

117

$\frac{1}{4}$ Corner to Section 34 only.
Found - G.L.O. Brass Cap, properly marked in 1922.
10", now 17" D. Fir, S. 36* W. 17.8 ft., shows good scar.
8", now D. Fir burnt stob, S. 75* E. 34.3 ft.
New BT: 6" W. Fir S. 50 $\frac{1}{2}$ * E. 60.0 ft. scribed " $\frac{1}{4}$ " S34 CS BT.
Note - $\frac{1}{4}$ Corner of Section 27, above, bears E. 49.5 ft.
Also fence bears North 5.0 ft.

118

$\frac{1}{4}$ Corner to Sections 33 and 34.
Found - Unrecorded $\frac{1}{2}$ " Iron Pipe at $\frac{1}{4}$ Corner.
40", now 48" D. Fir, S. 80* E. 45.5 ft., faint bark scribe " $\frac{1}{2}$ " S".
30" Oak, now down, S. 10* W. 11.9 ft., face rotten.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 31 S R 1 W
Office, 1968 $\frac{1}{4}$ S 33 | S 34
New BT's: 14" B. Oak N. 52* W. 9.8 ft. mkd: " $\frac{1}{4}$ " S33 CS BT.
6" D. Fir S. 44* E. 12.2 ft. mkd: " $\frac{1}{4}$ " S34 CS BT.
Note - Fence line bears West 12.6 ft. and North 4.5 ft.

119

$\frac{1}{4}$ Corner to Sections 34 and 35.
Found - G.L.O. Brass Cap, properly marked in 1922.
14" B. Oak, now rotten stump, S. 71* E. 27.7 ft. (Rec. S66E 27.7')
48" B. Oak, now down & rotten, S. 20* W. 48.2 ft. (Rec. S24W 48.2)
(Dug through rotten parts, no scribe found)
New BT's: 14" D. Fir N. 43* E. 14.2 ft. mkd: " $\frac{1}{4}$ " S35 CS BT.
13" D. Fir S. 10* W. 7.4 ft. mkd: " $\frac{1}{4}$ " S34 CS BT.

120

$\frac{1}{4}$ Corner to Section 3 and 2.
Found - G.L.O. Brass Cap at $\frac{1}{4}$ Cor. Mkd. properly in 1923.
10" D. Fir, now burnt stump, S. 83* E. 17.6 ft., scribe visible.
No trace of S. W. Bearing Tree.
New BT's: 7" Laurel S. 46* E. 9.0 ft. mkd: " $\frac{1}{4}$ " S2 CS BT".
5" Laurel S. 55* W. 17.1 ft. mkd: " $\frac{1}{4}$ " S3 CS BT".
Note - This corner lies in old unit on steep E. slope about 150 Ft.
west of draw & 70' south of open rocky slope.

John M. Powell
Frank Jones & W. Penley
September, 1968
C. S. File No. 54/71