

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 31 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21961

$\frac{1}{4}$  Corner to Section 21 only.

128

Found - G.L.O. Brass Cap. However, the brass caps for this  $\frac{1}{4}$  corner and the  $\frac{1}{4}$  corner to section 22 only were originally placed in the wrong location & facing south. We dig up and replace them in the right places, facing north. The caps now refer to the right sections.

Orig. 34", now 44" D. Fir, S. 10\*E. 15.8 ft., shows good face. (This BT is reference as BT to  $\frac{1}{4}$  Cor. Sec. 22 only by GLO Field Notes.

Orig. 34", now 39" D. Fir, N. 54\*W. 38.9 ft., shows good face.

20", now 26" D. Fir, S. 68\*W. 23.5 ft., opened & fd. scribing. (This BT is same age as others, but is not recorded in field notes.

Reset - G.L.O. Brass Cap for  $\frac{1}{4}$  Corner of Section 21 only.

Rescribed BT: 26" D. Fir S. 68\* W. 23.5 ft. mkd:  $\frac{1}{4}$  S21 CS BT.

Note - This  $\frac{1}{4}$  corner of Sec. 21 only lies 7.9 ft. N. of  $\frac{1}{4}$  Cor. Sec. 22 only.

$\frac{1}{4}$  Corner to Section 22 only.

129

Found - Brass Cap, however, B. C. for  $\frac{1}{4}$  corner of Sec. 22 only and  $\frac{1}{4}$  cor. Sec. 21 only switched. We change the Brass Caps around so they are in the right places.

Rescribed BT: 24" Cedar N. 44\*E. 49.9 ft. rescribed:  $\frac{1}{4}$  S22 CS BT.

Note - This  $\frac{1}{4}$  cor. of S. 22 only lies 7.9 ft. S. of  $\frac{1}{4}$  Cor. Sec. 21 only.

Section Corner to Sections 21 - 22 - 27 - 28.

130

Found - GLO Brass Cap, properly marked in 1922.

18", now 20" D. Fir, N. 88\* E. 9.9 ft., shows good face.

24", now 28" D. Fir, S. 88\* E. 13.2 ft., shows good face.

36", now 40" D. Fir, N. 42\* W. 13.2 ft., shows good face.

18", now 19" D. Fir windfall, S. 30\* W. 11.9 ft., shows good face.

New BT: 6" W. Fir S. 47\* W. 5.3 ft. mkd: T31S R1W S28 CS BT.

This corner lies on steep west slope.

$\frac{1}{4}$  Corner to Sections 22 and 27.

131

Found - GLO Brass Cap properly marked in 1922.

12", now 16" D. Fir, N. 48\* E. 7.9 ft., shows good face.

9", now 12" D. Fir, S. 39\* W. 10.5 ft., shows face.

Rescribed: 16" D. Fir N. 48\*E. 7.9 ft. mkd:  $\frac{1}{4}$  S22 CS BT.

12" D. Fir S. 39\*W. 10.5 ft. mkd:  $\frac{1}{4}$  S27 CS BT.

Note - No other trees as good as these for scribing.

This cor. lies 60 ft. south of E.-W. blazed line & 20' W. of creek.

Section Corner to Sections 22 - 23 - 26 - 27.

132

Found - GLO Brass Cap, properly marked in 1923.

24", now 28" D. Fir, N. 18\* E. 33.6 ft., shows good scar.

30", now 36" D. Fir, S. 33\* E. 20.4 ft., shows good scar.

28", now 34" D. Fir, N. 33\* W. 15.2 ft., shows good scar.

36", now D. Fir Stob, S. 41\* W. 21.0 ft., shows good scar.

New BT: 7" D. Fir S. 54\* W. 16.3 ft. mkd: T31S R1W S27 CS BT.

All other bearing trees tagged.

$\frac{1}{4}$  Corner to Sections 31 and 32.

133

Found - GLO Brass Cap properly marked in 1922.

50" D. Fir, now 54" Stob, S. 85\*E. 7.9 ft., shows good bark scribing, and good BT, face.

6", now 10" Live Oak, N. 55\*W. 21.1 ft., shows scribing.

New BT's: 11" D. Fir S. 5\* E. 2.2 ft. mkd:  $\frac{1}{4}$  S32 CS BT.

14" R. Fir N. 57 $\frac{1}{2}$ \* W. 10.6 ft. mkd:  $\frac{1}{4}$  S31 CS BT.

Note - This  $\frac{1}{4}$  corner lies 65 ft. N. of a ravine, large boulders around.

Section Corner to Sections 29 - 30 - 31 - 32.

134

Found - GLO Brass Cap properly marked in 1922.

20", now 25" Cedar, N. 12\*E. 42.9 ft., scribe visible.

18", now 30" D. Fir, S. 80\*E. 2.0 ft., shows good scar.

18", now 25" Cedar, N. 8\* W. 13.2 ft., scribe visible.

30" D. Fir, now stump, S. 53\* W. 18.5 ft., shows good scar.

New BT: 9" Cedar S. 44\* W. 15.0 ft. mkd: T31S R1W S31 CS BT.

All other bearing trees O. K. and Tagged.

10/8/68

John M. Powell  
Frank Jones & W. Penley  
October, 1968  
C. S. File No. 54/71