

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 31 S. T. S. R. 1 W. R.W.W.M.

KOKE-CHARMAN CO., EUGENE, ORE. 21891

135

$\frac{1}{4}$ Corner to Sections 30 and 29.
Found - GLO Brass Cap properly marked in 1922.
18", now 28" D.Fir, S. 22* E. 16.5 ft., shows good scar.
No trace of N.W. BT., falls in old skid trail
New BT: 6" Maple N. 81* W. 30.4 ft. mkd: $\frac{1}{4}$ S30 CS BT.

136

$\frac{1}{4}$ Corner to Section 30 only, T31S-R1E.
Found - GLO Brass Cap properly marked in 1923.
16" D.Fir, now dead, S.56*E. 26.4'(Rec.93.1'), shows good scar
34", now 32" D.Fir, N.32*E. 29.7 ft.(Rec.N14E), shows good scar.
New BT: 30" D.Fir S. 8 $\frac{1}{2}$ * E. 36.7 ft. scribed $\frac{1}{4}$ S30 CS BT.
Note - Trees face toward corner. After search, I did not find any other trees to go with record bearings and distance.

137

$\frac{1}{4}$ Corner to Section 36 only, T31-1W.
Found - Stone at $\frac{1}{4}$ Corner, faint " $\frac{1}{4}$ ".
Orig. 30", now 36" D.Fir, S. 55* W. 21.8 ft., shows good scar.
10", now 13" W.Fir, N. 87* W. 23.8 ft., shows good scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968
R T 31 S R
1 S 36 1
W $\frac{1}{4}$ E
All bearing trees O. K. and Tagged.

138

Sec. Cor. to Sections 30 and 31 only, T31 - 1 E.
Found - 28", now 34" D.Fir, N.59*E. 67.3 ft., shows good scar.
8", now 10" W.Fir, S.59*E. 53.5 ft., shows good scar.
G.L.O. Brass Cap at corner, properly marked in 1923.
New BT: 34" D.Fir N. 5* W. 28.2 ft. scribed T31S R1W S36 CS BT.

139

$\frac{1}{4}$ Corner to Section 12 only, T31-1W.
Found - 14", now 14" Maple, S.16*W. 37.0 ft. scribe visible.
12", now 28" D.Fir, N.84*W. 40.9 ft., shows scar.
Stone at $\frac{1}{4}$ corner marked " $\frac{1}{4}$ ".
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968
R T 31 S R
1 S 12 1
W $\frac{1}{4}$ E
All Bearing Trees O. K. and Tagged.

140

$\frac{1}{4}$ Corner to Section 1 only, T31 - 1 W.
Found - No trace of Corner Stone nor S. W. Orig. BT.
Orig. 50" Fir, now 54" sawed stump, N.70*E. 14.5 ft., shows good scar.
64", now 66" Fir Sawed Stump, N.40*W. 12.5 ft., open & find scribe.(1923 BT
Set - Brass Cap at Cor. Mkd: County Surveyor;s Office 1968
R T 31 S R
1 S 1 1
W $\frac{1}{4}$ E
No live trees or suitable stumps close for Bearing Trees.
Set - 5/8" Iron Rod 10 ft. south of $\frac{1}{4}$ corner.
5/8" Iron Rod 15 ft. south of $\frac{1}{4}$ corner.
This corner lies approx. 100 ft. N. of ridge top, course E. & W. on moderate north slope.

141

Section Corner to Sections 6 and 7 only, T31 - 1E.
Found - G.L.O. Brass Cap at corner, properly marked in 1923.
24", now 27" D.Fir, S.35*E. 36.3 ft. shows good scar.
9", now 9" D.Fir, N.51*E. 23.1 ft., shows good scar.
New BT: 24" Cedar N.85*W. 30.5 ft. scribed T31S R1W S12 CS BT.
All other bearing trees tagged.

142

$\frac{1}{4}$ Corner to Sections 13 and 24.
Found - G.L.O. Brass Cap at $\frac{1}{4}$ corner, properly marked in 1922.
26", now 30" D.Fir, S. 18* E. 18.5 ft., shows good scar.
16" D.Fir, now stump, N. 52* W. 14.5 ft., scribe visible on log by stump, "BT" on stump.
New BT: 15" R.Fir N. 21* W. 32.3 ft. scribed $\frac{1}{4}$ S13 CS BT.

John M. Powell
 Frank Jones & W. Penley
 October, 1968
 C. S. File No. 54/71