

Douglas County Surveyor's Record of
Government Corners Renewed

31 T.S. 2 R.W.W.M.

H. L. Eppstein, Co. Sur.
Witnesses.
N. E. Richardson, C. A. Bachman, Harry Dourney
October 5, 1926.
See Vol. 3, Page 287.

Ben B. Irving, D.C.S.
Jan 12, 21, 1931.
Witnesses
N. E. Richardson, B. A. Lane
F. L. Thomas.

M 1-38

- 1 ✓ $\frac{1}{4}$ CORNER BETWEEN SECTION 10 and 11. 1
Set corner by placing same half way between section corner on line. This corner was gone. Old Witness trees having been burned. Set stake and mound of rocks. Marked new witness trees as follows.
A 14" Fir S.35°E., 55 ft.
A 14" Cedar S.33°W., 36 ft. **CORNER NO. 101**
- 2 ✓ CORNER BETWEEN 10, 11, 14 and 15. 2
Set Oak post and iron off stove, mound of rock from old Cedar Witness tree, scribe marks plain. Pine gone, fir stump in evidence. Marked new B.T.s
A 36" Fir N.22°E., 51 lks. **SEPT. 1966 - SEARCHED FOR, NOT FOUND. J.M.P.**
A 15" Fir S.80°E., 59 lks. **SEE NOTES 2-5, 7/50**
A 12" Pine S.28°W., 86 lks.
A 7" Cedar N.11°W., 1 lks.
- 3 ✓ CORNER BETWEEN 10, 11, 3 and 2. 3
Set corner where California Oregon Power Co. had driven stake, which tallied out with oak tree on which I. S. Bannon said had seen scribe marks but were burnt out at this time. Pine Southeast was in evidence and also Oak S.W. Set for corner 4" x 4" x 4" Oak Post and marked new Witness trees
A 20" Fir N.15°W., 88 lks.
A 12" Fir S.79°E., 81 lks.
A 5" W. Oak N.58°E., 45 lks.
A 15" Fir S.31°W., 133 lks. **CORNER NO. 99**
- 4 ✓ $\frac{1}{4}$ CORNER BETWEEN 11 and 12. 4
Set stone with $\frac{1}{4}$ S. Old Bearing trees still standing but scribe marks rotted out. Marked new B.T.
A 18" Fir S.64°W., 82 lks. **CORNER NO. 53**
A 8" Fir S.36°E., 53 lks.
- 5 ✓ $\frac{1}{4}$ CORNER BETWEEN 2 and 11. 5
Found of Pine tree as corner and one Witness tree N.W. Set post and marked New B.T.
A 24" Fir N.71°W., 24 lks. **CORNER NO. 100**
A 10" Fir S.36°E., 44 lks.
- 6 ✓ $\frac{1}{4}$ CORNER BETWEEN 11 and 14. 6
Set Yewwood post from old Bearing tree and marked one new bearing tree, **SEE CORNER NO. 84**
A 14" Fir N.51°E. 10 lks., White Fir.
- 7 ✓ CORNER BETWEEN 11, 12, 13 and 14. 7
Renewed from three O.B.T.s in good condition. Conglomerate rock 6 x 8 x 16", 8" in ground. New B.T.
A 8" Fir N.37°50'W., 33 lks. scribed T.313., R.2W., C.S.B.T. S.11.
O.B.T.s as recorded in original Government Field Notes **54**
A 24" Pine S.24°W., 72 lks.
A 15" Oak (now 20") S.75°E., 7 lks. remarked
A 24" Fir (now 30") N.45°E., 44 lks. remarked
- 8 ✓ $\frac{1}{4}$ SECTION CORNER BETWEEN 13 and 14. 8
Position identified from one O.B.T. badly rotted scribe marks still visible. Position of other O.B.T. identified by rotted stump. Set Sandstone 6" x 12" x 14" long, 12" in ground for corner, chisled $\frac{1}{2}$ on top.
Fir 14" dia. N.48°E., 14 lks. marked $\frac{1}{2}$ S.13 C.S.B.T.
Fir 26" dia. N.62°W., 25 lks. marked $\frac{1}{2}$ S.14 C.S.B.T. **CORNER NO. 51**