

Douglas County Surveyor's Record of  
Government Corners Renewed

31 T. S. 2 R. W. W. M.

✓  $\frac{1}{4}$  SECTION CORNER BETWEEN 12 and 13. 9  
Position identified by one O.B.T. in good shape which was  
chopped out. Scribe marks legible and will be preserved, 3.38 E.,  
83 lks.  
Set Sandstone 8" x 8" x 16", 14" in ground for corner 55  
marked  $\frac{1}{4}$   
A 12" Fir S.2°40'W., 43 lks.  $\frac{1}{4}$  S.13 C.S.B.T.  
A 14" Fir N.21°20'E., 50 lks.  $\frac{1}{4}$  S.12 C.S.B.T.

✓  $\frac{1}{4}$  CORNER BETWEEN SECTIONS 16 and 24. 71 10  
Position identified by mound of rock and both original  
B.T.s. Set a Sandstone chiseled  $\frac{1}{4}$  for corner and surrounded  
with mound of rock remarked O.B.T.s.

✓ SECTION CORNER BETWEEN 13, 18, 24 and 19. T.31 R.1 and 2. 11  
Position identified from O.B.T. oak N.77°W., 114 lks.  
and stump of pine N.40°E., 82 lks. Original notes call  
for 2 Ash B.T.s. One is Oak mentioned above and other must  
have been an Oak as there has never been ash on spur.  
Set Rock 6" x 10" x 18", 16" in ground for corner. 43  
A 14" Black Oak N.42°E., 131 lks. T.31S.R.1W. S.18  
C.S.B.T.  
A 20" Black Oak N.65 $\frac{1}{2}$ °W., 67 lks. T.31S.R.2W. S.13  
C.S.B.T.  
A 20" Madronna S.56°W., 27 lks. T.31S.R.2W. S.24 C.S.B.T.  
A 18" Fir S.10°E., 150 lks. T.31S.R.1W. S.19 C.S.B.T.

✓ SECTION CORNER BETWEEN 12, 13, 7 and 18. (R.2 + R.1) 12  
Position identified from one O.B.T. 20" White Oak S.57°E.  
87 lks. which I remark T.31S.R.1W. S.18 C.S.B.T.  
Blaze 4 sides and scribe a 4" White Oak for corner  
T.31 S.7 on N.E.--R.1 W. S. 18 on S.E.--R.2 W. S.13 on S.W.--  
S.12 C.S. on N.W. faces.  
Set a Sandstone 3" x 6" x 14", 14" in ground alongside  
tree.  
A 8" White Oak S.42°W., 13 lks. marked T.31S.R.2W. 42  
S.13 C.S.B.T.  
A 10" Pine N.55°W., 63 lks. marked T.31S.R.2W. S.12  
C.S.B.T.  
A 6" White Oak N.28°E., 18 lks. marked T.31S.R.1W.  
S.7 C.S.B.T.

✓  $\frac{1}{4}$  SECTION CORNER BETWEEN 13 and 18. 13  
Position identified by proportional distances between  
section corners. Checked with holes where probable O.B.T.s  
stood. Fire had burned all traces of original corner. Set  
a sandstone 8" x 18" x 18" long, 14" in ground marked  $\frac{1}{4}$  46  
A 10" Fir N.32°E., 91 lks. marked  $\frac{1}{4}$  S.18 C.S.B.T.  
A 14" Fir N.32°W., 74 lks. marked  $\frac{1}{4}$  S.13 C.S.B.T.

✓  $\frac{1}{4}$  CORNER BETWEEN SECTIONS 14 and 15. 14  
Start at N.W. Corner of S.14-31-27 and 40.30 S. Set  $\frac{1}{4}$   
Miel Post, from which 83  
A 18" Fir bears N.68°30'W., 8 lks.

N.W. CORNER SECTION 26 ONLY 15  
Both old B.Ts. standing and in good shape.  
At corner point found stone and drove Iron Pipe. 57

Jno. H. Markham  
Mar. 26, 1952

Center  $\frac{1}{4}$  Section 13. 15-A

Established by Subd. of Section.  
Set - Truck Axle from which:  
14" Fir N. 2° E. 10 lks.  
16" Fir S. 2° E. 20 lks.

Jan. 1931

Ben B. Irving, Deputy County Surveyor  
January 12-21, 1931  
Witnesses  
N. E. Richardson, B. A. Lane, F. L. Thomas.

J. E. Roberts  
Wit.  
Jim Short  
Chas. Peterson  
Joe Renville  
1902.

Ben B. Irving,  
Deputy  
C.S. 37/27  
Map File  
M 1 - 38

RE-RENEWED, SEE CORNER NO. #175