

Douglas County Surveyor's Record of
Government Corners Renewed

31 T. S. 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 97196

Jno. H Markham Jr,
Mar. 26, 1952

S.W. CORNER SECTION 23 ONLY
List of O.B.Ts. as found,

16

- 12" Fir N 27 E 15 lks. (not found)
12" Fir S 40 W 12 lks. (dead snag fallen)
12" Fir S 50 E 30 lks. (dead snag standing)
30" Pine N 62 W 22 lks. (logged - scribe on stump)
20" Fir N 11 E 71 lks. (good shape)

56

SECTION CORNER 22, 23, 14 and 15 as det. by O.B Ts.

17

- A Fir stump 23" in diam. logged, bears S 75°W, 4.0 feet dist. O.B.T
A W. Fir 26" in diam bears S 89°E, 32.4 feet dist. O.B.T
A Fir stump 22" in diam. logged, bears N 16°E, 15.7 ft. dist. O.B.T

At corner point set a 4 x 15" Iron Pipe from which

89

- A Yew 8" in diam. bears N 70°W, 40.5 ft. dist. mkd. S 15, B.T.
A White Fir 14" in diam. bears S 77°W, 26.2 ft. dist. mkd.
S 22, B.T.
A White Fir 12" in diam. bears S 24°E, 33.0 ft. dist. mkd. Ss23 B.T
A Cedar 8" in diam. bears N 42°E, 40.0 ft. dist mkd. S14, B.T.
Creek bears east 150.0 feet

C.S. 41/1

Jno. H. Markham Jr.
Wit. Elmer Sutton
Mar. 26, 1952

H. L. Eppstein, Co.
Surveyor
October 5, 1928.
C. S. File Vol. 3,
Page 287.

Center 1/4 corner of section 11.
Set a stake at the intersection of the true centerlines though section 11.
From which:
10 inch Fir, N. 76°W., 27 links, mkd. C. S. Cen. S. B. T.

18

#205

John H. Markham Jr.
Work done for
Stomar Lumber Co.
July 29, 1955.
C. S. File 42/23

West 1/4 sec. corner to sec. 31. (only)
At corner point set a 1 inch x 30 inch Iron Pipe
from which
A 13 inch Fir bears N. 75°E., 21.5 feet dist., mkd. 1/4 S 31 B. T.
A 5 inch Hemlock bears S. 51°E., 7.0 feet dist., mkd. 1/4 S 31 B. T.
East 1/4 corner Sec. 36, T 31 S, R 3 W., bears South 435.0 feet.

19

115

John H. Markham, Jr.
Witness: J. R. Markham
For Stomar Lumber Co.
October 29, 1958
C. S. File No. 42/392

S. W. Corner Section 31.
as determined by O.B.T.'s:
36" Fir bears N. 43°E. 23.0 ft. O.B.T.
24" Fir Stump (logged) bears S. 43°E. 23.8 ft. dist. O.B.T.
At Corner Point Set 1" x 30" Iron Pipe from which:
8" Hemlock bears S. 44°E. 28.0 ft. dist. mkd. S1 T32S B.T.
13" W. Fir bears N. 49°E. 45.0 ft. dist. mkd. S31 T31S R2W B.T.
16" Fir bears S. 6°30'E. 15.4 ft. dist. mkd. S1 T32S R2W B.T.
Road bears East 75.0 ft. dist.
S. E. Corner Section 36 bears South 441.0 ft.

20

120

South 1/4 Section Corner to Section 31 (only).
as determined by O.B.T.'s:
26" Fir Windfall bears N. 79°W. 34.4 ft. dist. O.B.T., fd. scribe.
22" Alder N. 14°E. 61.4 ft. O. B. T.
At Corner Point Set 1" x 30" Iron Pipe from which:
10" Hemlock bears N. 27°W. 8.2 ft. dist. mkd. 1/4 S31 B. T.
12" Alder bears S. 55°W. 3.0 ft. dist. mkd. 1/4 S31 B. T.
Corner lies in Creek.
Twp. Corner bears West 575.0 ft.
Road bears East 295.0 ft.
N. W. Corner Section 6 bears East 366.0 ft.

21

121