

Douglas County Surveyor's Record of
Government Corners Renewed

31 T. S. 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

S. W. Corner of Section 7, as det. by O.B.T.'s:
35" Cedar bears S.45°E. 3.3 ft. O.B.T. I rescribe
S18 R2W B.T.
42" Fir N.68°E. 42.8 ft. O.B.T.
At Corner Point Set $\frac{1}{2}$ " x 30" Iron Pipe from which:
4" Fir N.80°E. 19.0 ft. S1 R2W B.T.
12" Fir S.11°W. 11.6 ft. S12 R3W B.T.
10" Fir S.87°W. 12.4 ft. S12 R3W B.T.
S. E. Corner 12 bears South 118.0 feet.

22

John H. Markham, Jr.
R.G. Boyd & O.A.
Keatley
For Stomar Ibr. Co.
C.S. File No. 42/392

RE-NEWED, SEE CORNER NO. 191

Section Corner to Sections 1 - 2 - 11 - 12, as det. by O.B.T.'s:
20" W. O. bears N.72°E. 27.0 ft., fd. scribe, O.B.T.
15" W. O. bears N.64°W. 21.0 ft. O.B.T. (uproot)
At Corner Point found Stone & Set $1\frac{1}{2}$ " x 36" Truck axle with flange
up from which:
10" Fir N.80°E. 25.6 ft. mkd. S1 R2W B.T.
14" Cedar S.55°E. 20.5 ft. mkd. S12 X B.T.
15" Cedar S.55°W. 36.6 ft. mkd. S11 R2W B.T.
8" Fir N.34°W. 27.2 ft. mkd. S2 R2W B.T.
Road bears South 40.0 feet.

23

John H. Markham, Jr.
C.S. File No. 42/392

Closing Corner Sections 17 and 21.
Found - 6" Fir S.6°W. 46.9 ft., down & rotting, fd. good
scribing "BT".
Shattered Remnants of 36" Fir S.15°E. 17.8 ft. No
scribing found on this tree.
Set - Brass Cap Mkd: County Surveyor's Office, S16
1961 T31S R2W S17/S21
New BT's: 10" W. Fir S.15 $\frac{1}{2}$ °W. 13.7 ft. Mkd: T31S R2WS17 CS BT.
13" Hemlock S.64°E. 25.1 ft. Mkd: T31S R2W S21 CS BT.
SEC. 16 STAMPED ON CAP JAN. 1975 by BAUGHMAN

24

Closing Corner to Section 17 and 20.
Found - Fir, now 40", S.64°W. 38.9 ft. Opened old blaze &
found good scribing.
Portion of rotted stump of 5" Fir N.42 $\frac{1}{2}$ °W. 16.5 ft.
No scribing found.
Set - Brass Cap Mkd: County Surveyor's Office, 1961 T31S R2W S17/S21
S20/S21
New BT's: 9" W. Fir N.33 $\frac{1}{2}$ °W. 18.1 ft. Mkd: T31S R2W S17 CS BT.
7" W. Fir S.79°W. 12.2 ft. Mkd: T31S R2W S20 CS BT.
SEC. 21 STAMPED ON CAP JAN 1975 by BAUGHMAN

25

James W. Byron & Mile E. Godfrey
Clete Putnam
June 9 - 12, 1961
C. S. File No. 52/81

$\frac{1}{2}$ Corner to Sections ~~15~~ 16. SEE REN. #137 26
Found - Rock set by Mensch in 1908, no marking found on rock.
Fir Stump, now 22", S.32 $\frac{1}{2}$ °E. 23.1 ft. Bottom of lower
scar showing.
Fir Stump, now 36", S.21°W. 17.8 ft. Opened Scar &
fd. partial scribe marks. These stumps are both
cut low. Appear to have been cut about 3 yrs. ago.
Alongside Rock at Corner Set Brass Cap Mkd: County Surveyor's
Office, 1961 T31S R2W $\frac{1}{4}$ S17/S16.
New BT's: 9" Hemlock N.20 $\frac{1}{2}$ °W. 17.1 ft. Mkd: $\frac{1}{4}$ S17 CS BT. I
11" I. Cedar N.30°E. 35.1 ft. Mkd: $\frac{1}{4}$ S16 CS BT.

26

SouthWest Corner to Section 16 Only.
Found - Granite Rock with 4 notches as called for in Gov't Field Notes.
W. Fir, now 30", N.35 $\frac{1}{2}$ °E. 39.6 ft., showing 2 good scars,
did not chop open.
Alongside Rock Set Iron Pipe with Brass Cap Mkd: County Surveyor's
Office, 1961 T31S R2W S16 S.W. Corner of Sec. 16.
New BT: Doug. Fir, 15", N.82°E. 65.2 ft. Mkd: T31S R2W S16 CS BT.

27

$\frac{1}{4}$ Corner to Sections 3 and 10.
Found - Orig. 18", now 24" Pine N.6°E. 24.4 ft., previously opened,
shows good scribing "18". We also find Stump Hole & Remains
of an Oak that checks bearing & distance for Orig. SW. BT.

28

CONT. NEXT

RE-NEWED, SEE CORNER NO. #197

RE-NEWED, SEE CORNER NO. #137

RE-NEWED, SEE CORNER NO. #180