

Douglas County Surveyor's Record of
Government Corners Renewed

31 T. S. 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21801

CONT.
FROM
PREV.
PG.

RE-RENEWED, SEE CORNER NO. #180
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961 $\frac{S 3}{S 10}$ T31S R2W
New BT: 9" R.Fir bears S.31°W. 14.2 ft. scribed S10 CS BT.

#28

Corner to Section 8 and 17 only, Closing Corner. 30
Found - Both BT's. recorded by Mensch, each shows good scars,
distance check O.K. S.W. BT. should be S.59°W. not S.52°W.
Bearing to N.W. BT. is Ok.

Corner Stone is not found.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961 $\frac{S 8}{S 17}$ 16C,C. T31S R2W
New BT's: 16" R.Fir bears N.76°W. 72.7 ft. scribed S 8 T31S R2W CS BT.
36" Cedar bears S.75°E. 6.6 ft. scribed CC S8 & 17 T31S R2W CS BT.

Corner to Sections 9 and 16 only. 31
Found - Both BT's. recorded by Mensch. Each shows old scars, centers
rotted, no scribing found. Each checks record bear., dist., & size.

Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1961 $\frac{S 9}{S 16}$ T31S R2W
New BT's: 6" R.Fir bears S.31°E. 12.0 ft. scribed S16 CS BT.
6" R.Fir bears N.34°E. 31.9 ft. scribed S 9 CS BT.

James W. Byron & Milo E. Godfrey
Clete Putnam
June 9 - 12, 1961
C. S. File No. 52/81

CLOSING Corner to Sections 5 and 8. 32
Found - Both BT's. recorded by Mensch show good scars. We do not open.
Also find Corner Stone which shows notches.

Set - Brass Cap alongside Corner Stone Mkd: County Surveyor's Office, 1961 T31S R2W $\frac{S 5}{S 8}$ S 9
New BT: 22" Cedar bears S.64°W. 31.4 ft. scribed S 8 T31S R2W CS BT.

Corner to Sections 4 and 9 only. 33
Found - Both BT's, now stumps, as recorded by Mensch. We also
find notched Corner Stone under N.S. Fence.

Set - Brass Cap at Corner and alongside Corner Stone Mkd: $\frac{S 5}{S 9}$ S 4 T31S R2W #202
New BT's: 6" Cedar bears S.23°E. 16.5 ft. scribed S 9 CS BT.
8" R.Fir bears N.25°E. 10.5 ft. scribed S 4 T31S R2W CSBT.

Corner to Sections 24 & 25, T31-3W, only. 34
(West Bdry. Sec. 30, T31-2W.)
Found - No trace of Original Stone.
9" Fir Stump N.42°E. 16.5 ft., opened stump for scribe "BT".
15" D.Fir, now 28", N.59½°W. 23.1 ft., opened tree, badly burned
face, no scribing.
35" D. Fir, now 40", S.35½°W. 57.4 ft., shows good scar.
No trace of 10" Cedar, falls in road.

Set - Brass Cap at Sec. Cor. Mkd: County Surveyor's Office, 1965
T31S $\frac{S 24}{S 25}$ S 30 R2W
R3W
New BT's: 7" Cedar N. 47° W. 5.3 ft. scribed T31S R3W S24 CS BT.
28" D.Fir N.59½°W. 23.1 ft. rescribed T31S R3W S24 CS BT.

John M. Powell
Frank Jone, & Joe Brady
Dec. 23, 1965
C. S. File No. 52/63

Corner to Sections 19 and 30 only, T31-2W. 35
Found - 20", now 23" Fir N. 26° E. 4.0 ft., shows good scar.
20", now 24" Cedar S. 10° E. 16.5 ft. Tree opened & some
scribing visible "S30".

Set - Brass Cap at Sec. Cor. Mkd: County Surveyor's Office, 1965
T 31 S $\frac{S 19}{S 30}$ R2W
R3W S 24
BT's. in good shape, no need for new trees.