

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21881

Section Corner to Sections 1 - 2 - 11 - 12.

52

Found - Truck Axle with flange at corner. See Ren. #23

10" Fir N. 80° E. 25.6 ft., pitched over scribing.

14" Cedar S. 55° E. 20.5 ft. scribe visible "S2"

15" Cedar S. 55° W. 36.6 ft., scribe visible "S2 R2W"

6" D. Fir, now dead, N. 34° W. 20.2 ft.

New BT: 9" D. Fir N. 47° W. 13.6 ft. mkd. T31S R2W S2 CS BT.

Note - As noted in renewal, road bears south 40.0 ft.

July, 1966

1/4 Corner to Sections 11 and 12.

53

Found - 15" Fir, now 26", S. 64° W. 54.1 ft., bark scribed "S BT".

8" Fir, now 17", S. 38° E. 35.0 ft., shows good scar.

No trace of Stone at 1/4 Corner. See Ren. #4

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

T 31 S	R 2 W
1/4 S 11/S 12	

Reblzd. & Rescrid: 26" D. Fir S. 64° W. 59.1 ft. mkd. 1/4 S11 CS BT.

Note - This corner is in fence corner, fences running N.-S. & W.

Sec. Corner to Sections 11 - 12 - 13 - 14.

54

Found - Stone at Sec. Cor., and 3/4" Iron Pipe, See Ren. #7.

Orig. 24" Pine, now 28", S. 24° W. 47.5 ft., shows good scar.

Orig. 20" Oak, now dead, S. 75° E. 4.6 ft., faint scribe mks. visible.

Orig. 30", now 45" Fir, N. 45° E. 29.0 ft., bark scribed.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

T 31 S	R2W
S 11	S 12
S 14	S 13

New BT's: 9" D. Fir S. 5° E. 22.5 ft. mkd. T31S R2W S13 CS BT.

12" D. Fir N. 28° W. 8.0 ft. mkd. T31S R2W S11 CS BT.

Note - This corner is 2.0 ft. north of fence corner, running E-W & S.

1/4 Corner to Sections 12 and 13.

55

Found - Sandstone at 1/4 Corner, faint "4". Ren. #9.

12" Fir, now 18", S. 2° 40' W. 28.7 ft. Opened for scribe "B".

14" Fir, now 21", N. 21° 20' E. 33.0 ft., shows good scar.

Set - Brass Cap at 1/4 Cor. Mkd: County Surveyor's Office, 1966

T31S R2W	1/4 S 12
	S 13

New BT: 9" Laurel S. 51° W. 26.2 ft. mkd. 1/4 S13 CS BT.

FND OK 5/91
J. ARTMAN
M113-61

Sec. Corner to Sections 22 and 23 only.

56

Found - 30" Pine Stump N. 62° W. 14.5 ft., scribe visible. Ren. #16

20" Fir, now 21", N. 11° E. 46.9 ft., shows good scar.

(Tree burned & looks unhealthy in general.)

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

T 31 S	R 2 W
S 22 / S 23	
S 26	

Note - This corner lies in fence corner.

New BT's: 9" Cedar N. 46° E. 27.7 ft. mkd. T31S R2W S23 CS BT.

9" W. Fir West 48.0 ft. mkd. T31S R2W S22 CS BT.

Corner to Sections 27 and 26 only.

57

Found - 3/4" Iron Pipe, 1.0 ft. long. See Ren. #15.

This corner lies about 90.0 ft. east of corner to S. 22 & 23 only, above.

Orig. 36" D. Fir, now 45", S. 74° E. 17.2 ft. Tree opened for scribe.

Orig. 36" D. Fir, now 45", S. 27° W. 33.7 ft. Tree shows good scar.

Set - Brass Cap alongside I.P. mkd: County Surveyor's Office, 1966

T 31 S	R2 W
S 23	
S 27 / S 26	

No New BT's., all trees in good condition.

3/16/70 - Found 1966 Brass Cap & Mkd. New Bearing Trees:

14" W. Fir S. 77° W. 33.3 ft. scribed "T31S R2W S27 BT".

10" D. Fir S. 46 1/2° E. 89.6 ft. scribed "T31S R2W S26 CS BT".

The Sec. Cor. of Sec. 26 & 27, lies 50.0 ft. W. of logging road.

FND OK
J. ARTMAN 5/91
M113-61

John M. Powell
Frank Jones & Terry Connell
June and July 1966
C. S. File No. 54/28