

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 31 S. T. S. R. 2 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21881

John M. Powell  
F. Jones & W. Penley  
March 16, 1970  
C.S. File 54/28

135

$\frac{1}{4}$  Corner to Section 22, South Boundary.  
Found - 1966 Co. Surveyor's Brass Cap, See Ren. #78.  
Alongside 12" Corner Tree.  
30" Laurel N.30°W. 15.8 ft. scribed " $\frac{1}{4}$  S22 CS BT".  
12" D.Fir S.25°W. 30.5 ft. scribed " $\frac{1}{4}$  S27 CS BT". (Destroyed Scribing)  
Remarked: Brass Cap to Refer to Section 22 only.  
County Surveyor's Office, 1966 T 31 S R 2 W S 22  
New BT: 14" D.Fir N. 42° E. 39.7 ft. scribed " $\frac{1}{4}$  S22 CSBT".

136

$\frac{1}{4}$  Corner to Section 9 only, west boundary.  
Found - 1966 Co. Surveyor Brass Cap, See Ren. #113.  
I now destroy everything that refers to Sec. 8, so Brass Cap now reads:  
County Surveyor's Office, 1966 T 31 S R 2 W  $\frac{1}{4}$  S 9  
Both old Bearing Trees are dead.  
Renewed BT's: 17" Cedar S.74°E. 76.2 ft. mkd: " $\frac{1}{4}$  S9 CS BT".  
30" Bull Pine N.23°E. 159.7 ft. mkd: " $\frac{1}{4}$  S9 CS BT".  
This corner lies on rock, east slope next to edge of timber.

2/27/70

137

$\frac{1}{4}$  Corner to Section 16 only, west boundary.  
Found - 1961 Co. Surveyor's Brass Cap, Ren. #26.  
I now destroy everything that refers to Sec. 10, so Brass Cap now reads:  
County Surveyor's Office, 1961 T 31 S R 2 W  $\frac{1}{4}$  S 16  
Renewed BT: 11" I. Cedar N.30°E. 35.1 ft. mkd: " $\frac{1}{4}$  S16 CS BT".  
New BT: 21" D.Fir S.83°E. 31.4 ft. mkd: " $\frac{1}{4}$  S16 CS BT".

2/27/70

138

$\frac{1}{4}$  Corner to Sections 4 only, west boundary.  
Found - 1966 Co. Surveyor's Brass Cap, Ren. #117.  
I now destroy everything that refers to Sec. 5, so it now reads:  
County Surveyor's Office, 1966 T 31 S R 2 W S 4  
Old BT: 18" D.Fir, now 25", S.25°E. 20.4 ft., tree had been opened and shows scribe "S4 BT".  
New BT: 6" D.Fir N.83 $\frac{1}{2}$ °E. 13.6 ft. mkd: " $\frac{1}{4}$  S 4 CS BT".

2/27/70

139

$\frac{1}{4}$  Corner to Section 21 only, south boundary.  
Found - 1966 Co. Surveyor's Brass Cap, Ren. #80.  
9" W.Fir S.17°W. 17.6 ft. mkd: " $\frac{1}{4}$  S28 CS BT".  
6" W.Fir N.88°W. 12.1 ft. mkd: " $\frac{1}{4}$  S21 CS BT".  
I now destroy everything that refers to Sec. 28, so it now reads:  
County Surveyor's Office, 1966 T 31 S R 2 W S 21  
New BT: 10" Hemlock N.55°E. 61.7 ft. scribed " $\frac{1}{4}$  S21 CS BT".  
Destroyed scribing on 9" Fir S.17°W. 17.6 ft.

3/16/70

140

$\frac{1}{4}$  Corner to Section 23 only, south boundary.  
Found - 1966 Co. Surv. Brass Cap, Ren. #58., alongside Corner Stone.  
27" W.Fir S.32°E. 25.1 ft. mkd: "S26 BT".  
11" Cedar N.48°E. 14.3 ft. mkd: " $\frac{1}{4}$  S23 CS BT".  
I now destroy everything that refers to Sec. 26, so Brass Cap now reads:  
County Surveyor's Office, 1966 T 31 S R 2 W  $\frac{1}{4}$  S 23  
New BT: 6" Cedar N.41°W. 7.9 ft. mkd: " $\frac{1}{4}$  S23 CS BT".  
Destroyed scribing on 27" W.Fir S.32°E. 25.1 ft. - SEE LETTER IN C.S. 54/28

3/16/70

141

Section Corner to Sections 1 & 12 only, T31-3W.  
Found - No trace of I. Pipe, See Ren. #55., falls in skid road.  
Orig. 32" D.Fir N.24°E. 50.8 ft., shows good scar.  
Orig. 29" D.Fir S.16°E. 76.0 ft., shows good scar.  
Orig. 31" Laurel N.11°W. 25.0 ft., scribe visible.

(continued over)

John M. Powell  
Frank Jones & W. Penley  
March, 1970 C. S. File No. 54/28

RE-RENEWED SEE CORNER NO. #227  
CORNER NO. #199