

Douglas County Surveyor's Record of
Government Corners Renewed

31 T. S. 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97199

Wenderoth
Dep. Cnty. Surv.
Nov. 1948

1/4 COR. BET. SECS. 26-35
Found both trees in good shape, Drive 1" I. Pipe for corner.
24" Fir S 11° 30' W 21.1 ft.
14" Madrona N 6° 45' E 19.8 ft.
Stone for corner gone.

23

J. H. Markham, Jr.
Reg. Eng.
Geo. Vaughn, Mit.
8-8-51
C.S. #0/363
for Joe Ritter

N.E. COR. SECTION 5.
Determined by Old Bearing Trees
A Fir 15" diam. bears N. 11° W. 24.4 ft. distant, I chopped
out and found the scribe.
A 36" Fir wind fall bears S. 12° E, 50.0 ft. distant,
Old B.T.
At corner point found large stone and drove 1" x 30" Iron Pipe
from which:
A Laruel 8" in diam. bears S. 23° W, 12.0 ft. distant
marked B 5, T 31 S, R 3 W, B. T.

24

Geo. Wenderoth
File 45/226

Section corner to secs 33, 34 (T31S, R3W) and 3, 4 (T32S, R3W).
1" iron pipe.
30" Fir S. 42° 55' E., 15.2.
10" Chinquapin S. 26° 42' W., 14.1.
12" Fir N. 75° 05' E., 20.7.
12" Hemlock N. 59° 18' E., 29.4.

25

Geo Wenderoth
File 45/229

Section corner to secs. to 33, 34 (T31S, R3W) and 3, 4 (T32S, R3W).
1" iron pipe.
30" Fir S. 42° 55' E., 15.2.
10" Chinquapin S. 26° 42' W., 14.1.
12" Fir N. 75° 05' E., 20.7.
12" Hemlock N. 59° 18' E., 29.4.

26

Geo. Wenderoth
File 45/230

Center 1/4 corner section 34.
1" iron pipe.
18" Fir N. 42° 45' W., 18.8.
14" Fir S. 71° 14' E., 28.9.

Section corner to secs. 25, 26, 35 and 36.
1" iron pipe.
18" Fir N. 38° 30' W., 23.4.
28" Fir N. 59° 20' E., 31.3.
12" Fir S. 2° 45' W., 10.5.
30" Fir S. 75° 50' E., 24.0.

27

Norman D. Price R. S. No. 33.
Corner re-habilitated for
Dollar and Patterson Co. Inc.
Glendale, Oregon
Surveyed April, 1955.
C. S. File No. 41/374.

George Wenderoth
Dep. Co.
Surveyor
May, 1955.
C. S. File
46/134.

1/4 sec. corner to secs. 20 and 21.
At the corner, a basalt stone is set, 12x6x5 ins. above ground, firmly
set, mkd. 1/4 on W. face; from which the remains of original
bearing trees:
A burnt hemlock, 16 ins. diam., bears S. 54 1/2° E., 44 1/2 lks.
dist., on which no marks remain.
A burnt yew, 12 ins. diam., bears S. 74 1/2° W., 31 lks.
dist., on which no marks remain.
And new bearing trees:
A hemlock, 15 ins. diam., bears S. 72 1/2° E., 60 lks.
dist., mkd. 1/4 S21 R33 BT.
A yew, 12 ins. diam., bears N. 89° W., 76 lks.
dist., mkd. 1/4 S20 R33 BT.
Against N. side of stone, set an iron pipe, 3 ft. long, 1 1/2 ins.
diam., 28 ins. in the ground, mkd. R333.

28

Township corner to sec. 31, T 31 S, R 3 W., sec. 36, T 31 S, R 4 W., sec.
1, T 32 S, R 4 W., and sec. 6, T 32 S, R 3 W.
1 1/2 inch iron pipe.
8" Thorn, S. 77° E., 48.8 feet.
10" Hemlock, S. 33° 40' W., 185.5 feet.
24" Fir, N. 12° 20' W., 142.0 feet.

29

File ok
9/85
By Howard Johnson
See M99-36

DUPLICATES

SEE CORNER NO. 86

SEE CORNER NO. 122

SEE CORNER NO. 167

SEE CORNER NO. 167

FOUND O.K. - Dec. 1965 - JMP
C.S. File No. 52/63
SEE CORNER NO. 177

SEE CORNER NO. 140