

Douglas County Surveyor's Record of
Government Corners Renewed

T 31 S T. S. R 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21681

John H. Markhama, Jr.
Wit. R. G. Boyd.
For Stomar Lumber Co.
C. S. File No. 42/392

74
1/4 Corner Section 4 and 5., as det. by O.B.T.'s:
Gov't notes had East & West turned around on both O.B.T.'s.
12" La. S.72°E. 19.8 ft. O.B.T. - I rescribed 1/4 S4 T31S R3W B.T.
15" Fir S.15°W. 10.6 ft. O.B.T.
At Corner Point found Original Stone from which:
38" Fir N.68°W. 25.7 ft. dist. mkd. 1/4 S B.T.
3" Chip. bears N.61°W. 12.2 ft. dist. mkd. 1/4 S B.T.
6" La. bears N. 6°W. 5.5 ft. dist. mkd. 1/4 S B.T.

1/4 Corner Section 3 and 4, as det. by O.B.T.'s:
30" Fir N.40°E. 11.2 ft. O.B.T.
24" Cedar N.35°W. 25.7 ft. O.B.T.
At Corner Point Set 2" x 30" I. P. from which:
9" La. bears S.51°W. 14.0 ft. dist. mkd. 1/4 S4 T31S B.T.
10" La. bears S.16°W. 30.5 ft. dist. mkd. 1/4 S4 T31S B.T.
30" Fir S.2°E. 14.0 ft. dist. mkd. 1/4 S3 B.T. on bark.

X Section Corner to Sections 5 - 6 - 7 - 8, as det. by O.B.T.'s:
35" Fir N.6°E. 60.7 ft. O.B.T.
30" Fir S.37°W. 80.5 ft. O.B.T.
18" Fir N.40°W. 26.7 ft. O.B.T.
At Corner Point found Stone & Set Axle with flange up from which:
7" Fir N.50°E. 5.3 ft. mkd. S 5 B.T.
6" Fir S.47°E. 6.7 ft. mkd. S 8 X B.T.
20" Fir S.16°W. 8.8 ft. mkd. S 7 B.T.
15" Fir N.88°W. 26.0 ft. mkd. S 6 B.T.
Main ridge Top and Jeep Road bears North 50.0 ft.

X Center of Section 4.
At Corner Point Set 2" x 30" Iron Pipe from which:
30" Fir bears S.74°E. 17.0 ft. mkd. 1/4 S 4 C. C. B. T.
20" Fir bears N.25°E. 12.0 ft. dist. Mkd. 1/4 S 4 C.C.B.T.
Top of ridge bears West 120.0 ft.
West 1/4 Corner bears West 2667.2 ft.
East 1/4 Corner bears East 2415.8 ft.

+ North 1/4 Corner Section 6, only.
At corner point Set 2" x 30" I. P. from which:
8" Chip. N.18°E. 20.0 ft. 1/4 S6 BT.
6" Chip. S.74°E. 25.0 ft. 1/4 S6 BT.
4" Fir S.43°E. 23.8 ft. 1/4 S6 BT.

+ 1/4 Corner Sec. 6, T31S R3W & Sec. 1, T31S R4W.
as determined by O. B. T.'s:
40" Fir Snag S.57°W. 16.8 ft. O.B.T.
22" Fir N.61°E. 15.2 ft. O. B. T.
At Corner Point found Stone Mkd: 1/4 & Set 2" x 30" I. P. from which:
12" Maple N.44°E. 10.0 ft. mkd. 1/4 S 6 B.T.
4" Fir N.75°E. 11.8 ft. mkd. 1/4 S 6 B.T.
7" Fir S.58°E. 19.0 ft. mkd. 1/4 S 6 B.T.
10" Laurel S.58°W. 18.5 ft. mkd. 1/4 S 1 R4W B.T.
2" Fir N.49°W. 6.2 ft. mkd. 1/4 S 1 B.T.

+ Sec. Cor. to Secs. 6 & 7, T31S R3W., & Sec. 1 & 12, T31S R4W.
as determined by O. B.T.'s:
40" Fir S.73°E. 57.4 ft. O.B.T.
22" Fir Snag S.68°W. 23.1 ft. O.B.T.
40" Fir N.85°W. 40.2 ft. O.B.T.
At Corner Point Found Stone & Set 2" x 30" I. P. from which:
4" La. S.87°W. 11.3 ft. mkd. S12 T31S R4W B.T.
5" La. N.53°W. 7.7 ft. Mkd. S 1 T31S R4W B.T.
5" La. N.12°E. 7.1 ft. mkd. S 6 T31S R3W B.T.
5" La. S.10°W. 11.0 ft. mkd. S12 T31S R4W B.T.
5 1/2" La. East 17.2 ft. mkd. S 7 T31S R3W B.T.
1/4 Corner Sections 6/7 bears N.82 1/2°E.

John H. Markham, Jr.
For Stomar Lumber Co.
Wit: R. G. Boyd
August 2, 1960
C. S. File No. 42/392

74

146

75

145

76

144

77

RE-ENTERED

251

78

119

79

80