

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

124

South
 $\frac{1}{4}$ Corner to Section 32, only, T30-3W.
 Found - I. Pipe at $\frac{1}{4}$ Cor., See Ren. #23, T30-3W.
 Orig. 36" D. Fir N. 71° E. 10.0 ft., shows good scar.
 9" Laurel, now 11" N. 50° E. 52.0 ft. (S.B. 48.8 ft),
 scribed $\frac{1}{4}$ S32 BT.
 10" Live Oak, now 13" S. 46° E. 41.0 ft. (S.B. 34.4 ft.)
 scribed $\frac{1}{4}$ S32 BT.
 23" D. Fir, now 25", S. 7° E. 38.0 ft., bark scribed $\frac{1}{4}$ S32 BT.
 Set - Brass Cap alongside I. Pipe at $\frac{1}{4}$ Cor. Mkd: T30S R3W
 County Surveyor's $\frac{1}{4}$ S 32
 Office, 1966 T31S R3W
 All Trees in good condition.

125

Sec. Cor. to Sections 34 & 35 only, T30-3W.
 Found - I. Pipe at Sec. Cor., See Ren. #72, T30-3W.
 Orig. 42" Fir N. 74 $\frac{1}{2}$ ° E. 45.2 ft., shows scar.
 10" Fir, now 13" N. 69° E. 35.7 ft., shows good scar.
 7" Laurel, now 10" N. 79° W. 10.5 ft. scribed T30S R3W.
 20" Laurel S. 8° W. 22.5 ft. "BT" in wood, bark scribe.
 24" Laurel S. 36° E. 18.0 ft., "BT" in wood, " "
 Set - Brass Cap at Cor. Alongside Iron Pipe Mkd: T30S R3W
 County Surveyor's S 34 / S 35
 Office, 1965 S 3
 Reblazed & Scribed: T31S R3W
 24" Laurel S. 36° E. 18.0 ft., Mkd: T31S R3W S3 CS BT.
 As Noted Corner lies on top of ridge.

126

Sec. Cor. to Sections 33 & 34 only, T30-3W.
 Found - Iron Pipe at Sec. Cor., See Ren. #83.
 Orig. 40" Fir, now 41" S. 71° E. 19.8 ft., shows good scar.
 30" Laurel, S. 34° E. 18.0 ft. scribed "S4" & bark scribed.
 20" D. Fir, now 17" N. 88° W. 11.4 ft. scribed "S33" visible.
 15" D. Fir, now 18" S. 62° W. 15.8 ft., rotten scribe visible.
 28" D. Fir, now 29" S. 84° W. 26.8 ft., bark scribed.
 Set - Brass Cap at Cor. alongside Iron Pipe Mkd: T30S R3W
 County Surveyor's S 33 / S 34
 Office, 1966 S 4
 New BT's; reblazed & scribed. T31S R3W
 29" D. Fir S. 84° W. 27.5 ft. scribed T31S R3W S4 CS BT.
 18" D. Fir S. 62° W. 15.8 ft. scribed S 4 CS BT.

127

South $\frac{1}{4}$ Corner to Section 34 only, T30-3W.
 Found - I. Pipe at Corner, See Ren. #71, T30-3W.
 Orig. 13" Maple, now 25", S. 66 $\frac{1}{2}$ ° E. 5.9 ft., had been opened for scribe.
 Orig. 5" Fir, now 20", N. 54 $\frac{1}{2}$ ° E. 31.0 ft., shows scar.
 19" Fir S. 73° W. 16.0 ft., shows parts of scribing.
 18" Maple N. 77° E. 53.0 ft. scribed $\frac{1}{4}$ S34 BT.
 Set - Brass Cap alongside I. Pipe at Corner Mkd: T30S R3W
 County Surveyor's S 34
 Office, 1965 $\frac{1}{4}$ T31S R3W

128

South $\frac{1}{4}$ Corner to Section 33 only, T30-3W.
 Found - No trace of 4' x 4' Stone, See Ren. #40, T30-3W.
 4" Alder, now 6" S. 57° E. 12.0 ft. Opened tree for scribe,
 found some but tree was too rotten to identify.
 (Also, found bearing to be S. 37° E.)
 8" Fir, now 15" S. 49° W. 25.0 ft., shows good scars.
 Set - Brass Cap at $\frac{1}{4}$ Cor. Mkd: County T30S R3W
 Surveyor's S 33
 Office, 1966 $\frac{1}{4}$ T31S R3W
 New BT's: 4" Hemlock N. 13 $\frac{1}{2}$ ° E. 28.0 ft. scribed $\frac{1}{4}$ S33 CS BT.
 Note - Corner lies directly under large windfall. Creek bears
 West about 150 ft. Corner is on E. - W. cutting line.

John M. Powell
 Frank Jones & Joe Brady
 December 1965 & January 1966
 C. S. File No. 52/63