

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUBENE, ORE. 21881

John M. Powell
Frank Jones & Joe Brady
December 1965
C. S. File No. 52/63

129
 $\frac{1}{4}$ Corner to Sections 33 and 34.
 Found - 22" Fir, now 24", S. 50° W. 13.2 ft., prev. opened for scribe.
 19" Fir, now 21", S. 59° E. 5.9 ft., shows good scar, patched over.
 I. Pipe at $\frac{1}{4}$ Corner, See Ren. #7.
 Set - Brass Cap alongside I.P. for $\frac{1}{4}$ Cor. Mkd: T31S R3W
 County Surveyor's Office, 1965 $\frac{1}{4}$ S 33 / S 34
 Both BT's. in good condition.

130
 $\frac{1}{4}$ Corner to Sections 27 and 34.
 Found - I. Pipe at $\frac{1}{4}$ Corner, See Ren. #91.
 11" R. Fir, now 12", S. 3° E. 73.8 ft., shows good scars, " $\frac{1}{4}$ " scribe.
 6" R. Fir, now 7", N. 69° E. 33.5 ft., shows good scars.
 Set - Brass Cap at Cor. alongside I.P. Mkd: T31S R3W
 County Surveyor's Office, 1965 $\frac{1}{4}$ S 27
 S 34
 Both BT's. in good condition.

131
 $\frac{1}{4}$ Corner to Sections 13 and 24.
 Found - No trace of Corner Stone.
 14" Laurel, now 16", S. 73° E. 16.5 ft., no scribe, badly burnt out.
 30" Fir, now 34", N. 29° E. 41.6 ft., opened tree for scribe "S".
 Set - Brass Cap at $\frac{1}{4}$ Cor. Mkd: County Surveyor's Office, 1965 T31S R3W
 $\frac{1}{4}$ S 13
 S 24
 New BT's: 11" D. Fir S. 86° E. 9.9 ft. scribed $\frac{1}{4}$ S24 CS BT.
 Note - Old logging road bears south about 400.0 ft.

132
 $\frac{1}{4}$ Corner to Sections 15 and 14.
 Found - $\frac{1}{4}$ " I. Pipe & stone at $\frac{1}{4}$ Corner, See Ren. # 67
 34" D. Fir Stump S. 34° E. 9.2 ft. (Orig. BT) shows good scar.
 40" Cedar N. 67° W. 31.6 ft. (Orig. BT) Bearing should be N. 69° W.
 No trace of S. 72° E. Fir.
 6" Fir, now 8", S. 54° W. 18.6 ft., shows good scars.
 8" Fir, now 10", N. 64° W. 19.1 ft., shows good scars.
 9" Fir, now 11", N. 28° W. 33.8 ft., shows good scars.
 Set - Brass Cap alongside $\frac{1}{2}$ " I.P. for $\frac{1}{4}$ Cor. & Mkd: T31S R3W
 County Surveyor's Office, 1965 $\frac{1}{4}$ S 15 / S 14
 New BT: 6" Fir S. 89° E. 39.6 ft. scribed $\frac{1}{4}$ S14 CS BT.

133
 $\frac{1}{4}$ Corner to Sec. 33, T31-3W. & Sec. 4, T32-3W.
 Found - I. Pipe at $\frac{1}{4}$ Cor. & Scribed Stake, See Ren. #24, T32-3W.
 11" D. Fir N. 1° E. 24.5 ft., shows scribed "BT $\frac{1}{4}$ ".
 17" D. Fir S. 41° W. 11.0 ft., shows good scars.
 Set - Brass Cap alongside I.P. for $\frac{1}{4}$ Cor. & Mkd: $\frac{1}{4}$ S 33 T31S R3W
 County Surveyor's Office, 1966 S 4 T32S
 All Trees in good condition.

134
 SEC. COR. to Secs. 31 & 32, T31-3W. & Secs. 5 & 6, T32-3W.
 Found - I. Pipe at Sec. Cor., See Ren. #10.
 12" Fir Snag N. 46 $\frac{1}{2}$ ° E. 33.0 ft., bearing S.E. N. 49° E., Scribed "32".
 14" Fir Stump N. 66 $\frac{1}{2}$ ° W. 104.3 ft., bearing S.E. N. 65° W. 140.0 ft.,
 Scribing visible.
 Orig. 36" Fir S. 22° E. 59.4 ft., bearing S.E. S. 20° E., bark scribe "BT",
 and other faint scribing visible. No trace S. W. BT.
 Set - Brass Cap alongside I.P. at Cor. Mkd: R3W T31S S 31 | S 32
 County Surveyor's Office, 1965 T32S S 6 | S 5
 New BT's: 14" Fir S. 12° E. 31.3 ft. scribed T32S R3W S5 CS BT.
 4" Pine S. 35° W. 24.6 ft. scribed S6 CS BT.
 8" Pine N. 38° W. 17.0 ft. scribed S31 CS BT.
 28" Fir N. 16° W. 94.0 ft. scribed T31S R3W S31 CS BT.