

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

152

$\frac{1}{4}$ Corner to Sections 29 and 30.
Found - I. Pipe at $\frac{1}{4}$ Corner as recorded in Ren. #18.
28" Cedar N. 44° E. 15.5 ft., scribing visible "S B". This bearing should be N. 32° E.
16" Cedar, now 24", N. 68° W. 33.6 ft., shows good scar.
Set - Brass Cap at $\frac{1}{4}$ Cor. Mkd: County Surveyor's Office, 1966
(alongside Iron Pipe) T31S R3W $\frac{1}{4}$ S 30/S 29
All Bearing Trees in good condition.

153

$\frac{1}{4}$ Corner to Sections 30 and 31.
Found - Iron Pipe as recorded in Ren. #20.
18" Fir, dead, N. 23° E. 8.0 ft., scribe visible, " $\frac{1}{4}$ S BT".
12" Fir, dead, S. 61° E. 20.8 ft., scribe visible, " $\frac{1}{4}$ SBT".
Set - Brass Cap at $\frac{1}{4}$ Cor. Mkd: County Surveyor's Office, 1966
(Alongside I. Pipe) T31S R3W $\frac{1}{4}$ S 30
S 31
New BT's: 12" Laurel S. 38 $\frac{1}{2}$ ° E. 28.8 ft. scribed $\frac{1}{4}$ S31 CS BT.
13" D. Fir N. 35° E. 65.0 ft. scribed $\frac{1}{4}$ S30 CS BT.

RE-RENEWED SEE CORNER NO. #246

154

$\frac{1}{4}$ Corner to Sections 26 and 35.
Found - $\frac{3}{4}$ " Iron Pipe, See Ren. #86.
12" Fir, now 15", N. 35° W. 50.0 ft. scribed $\frac{1}{4}$ S26 BT, badly burned.
11" Cedar, now 12", S. 74° W. 85.0 ft. scribing visible " $\frac{1}{4}$ S35 BT".
10" Laurel, dead, N. 66° E. 46.0 ft.
5" Fir, dead, S. 26° E. 52.0 ft. scribed " $\frac{1}{4}$ S BT".
Set - Brass Cap at Sec. Cor. Mkd: County Surveyor's Office, 1966
(Alongside Iron Pipe) T31S R3W $\frac{1}{4}$ S 26
S 35
New BT's: 13" D. Fir N. 30° E. 116.4 ft. scribed " $\frac{1}{4}$ S26 CS BT."
22" Fir Stump S. 24° W. 21.4 ft. scribed " $\frac{1}{4}$ S35 CS BT".
Reblazed & Rescribed: 15" D. Fir N. 35° W. 50.0 ft. scribed " $\frac{1}{4}$ S26 CS BT."
Note - This corner is on skid road in middle of cutting unit.

155

Sec. Cor. to Sections 26 - 27 - 34 - 35.
Found $\frac{7}{8}$ I. Pipe & Wood Stake Mkd. "CS", See Ren. #21.
26" Fir N. 12° E. 23.4 ft., now snag, scribing visible. #212
36" Fir, now 41", S. 31° W. 27.3 ft., shows good scars.
28" Fir N. 30 $\frac{1}{2}$ ° E. 24.4 ft., should be N. 34° E.
Set - Brass Cap at Sec. Cor. Mkd: County Surveyor's Office, 1966
(Alongside Iron Pipe) T31S R3W S 27 | S 26
S 34 | S 35
New BT: 4" D. Fir N. 26° W. 19.0 ft. scribed S27 CS BT.

RE-RENEWED SEE CORNER NO. #212

156

Sec. Cor. to Sections 22 - 23 - 26 - 27.
Found - Iron Pipe at Sec. Cor. as recorded in Ren. #30.
6" Laurel, now dead, N. 58 $\frac{1}{2}$ ° E. 21.7 ft. (dist. S.B. 28.9 ft.)
Find scribing visible, "T31".
5" Laurel, now 6", S. 70 $\frac{1}{2}$ ° W. 17.8 ft. (dist. S.B. 25.0 ft.)
This tree bark scribed.
6" Laurel, now 9", N. 49° W. 23.1 ft., bark scribed.
Orig. 20" Live Oak, S. 42° E. 21.8 ft., shows good scar.
Set - Brass Cap at Sec. Cor. Mkd: County Surveyor's Office, 1966
(Alongside Iron Pipe) T31S R3W S 22 | S 23
S 27 | S 26
New BT's: 9" Laurel S. 85° E. 25.4 ft. scribed T31S R3W S26 CS BT.
23" Laurel N. 13° W. 3.7 ft. scribed T31S R3W S CS BT.
Reblazed & Rescribed: 9" Laurel N. 49° W. 23.1 ft. scribed T31SR3WS22 CS BT.
6" Laurel S. 70 $\frac{1}{2}$ ° W. 25.0 ft. scribed T31SR3WS27 CS BT.

157

Sec. Cor. to Sections 27 - 28 - 33 - 34.
Found - Iron Pipe at Sec. Cor., See Ren. #9.
Orig. 12" Laurel gone N. 45° E. 5.3 ft.
Orig. 16" Laurel, rotted out, S. 105° E. 21.1 ft.
Orig. 10" Laurel, gone, N. 50° W. 22.4 ft.
6" Fir, now 17", S. 39° E. 17.2 ft., shows good scar.
16" Laurel, now 22", N. 47° W. 51.8 ft. Tree opened, scribe visible.
10" Pine, now 35", N. 15° E. 61.7 ft., shows good scar. (Dist. S.B. 63.3)
20" Laurel, now 22", S. 24 $\frac{1}{2}$ ° E. 39.0 ft., scribe visible.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966
T31S R3W S 28 | S 27
S 33 | S 34
New BT: 5" Hemlock N. 5° W. 17.9 ft. scribed S28 CS BT.

RE-RENEWED SEE CORNER NO. #207

John M. Powell
Frank Jones & Joe Brady
January & February 1966
C. S. File No. 52/63

Fd 8C 7/81
BLM Admin. Survey
SEE GIS FILE