

Douglas County Surveyor's Record of
Government Corners Renewed

T.31S. T. S. R.3W. R.W.W.M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21801

196

Center $\frac{1}{4}$ Corner Section 35.
Set - 1" by 30" Galv. Iron Pipe with Brass Cap, 26 " in the ground
Marked Disk: T 31 S R 3 W
C $\frac{1}{4}$ S 35
1969
OLS 536
Scribed - 6" Hemlock "C $\frac{1}{4}$ S35 BT" which bears N.62°E. 10.9 ft.
placed BT Tag.
15" Doug. Fir "C $\frac{1}{4}$ S35 BT" which bears N.86°W. 35.0 ft.
placed BT Tag.

Glenn S. Baughman
For Ump. Nat'l. Forest
April, 1969
C.S. 55/114 M 37 - 60

MAR 74

Center $\frac{1}{4}$ Corner for Section 31.
Set Brass cap. See also Ren. #100
BT's - 22" Oak, bears S.50°W., 99.6 ft.
22" Pine, bears S.5°W., 110.5 ft.

197 Glenn Baughman
For: Pram Realty
June 1975
M 56 - 15

6/75

NE Corner Government Lot #9
Found - 1 1/2" x 36" I. Pipe loose and protruding 28" above ground.
A 14" now 18" Cedar bears N. 84°E., 22.2 ft. Tree alive with well-
healed double blaze. C.S. 42/392 (J.H. Markham for Stomar Lbr.)
A 14" now 17" Maple bears N. 13°E., 27.8 ft. Tree alive with "1/16
S3 X BT" visible in healing double blaze. C.S. 42/392
A 22" Alder bears S.23°W., 32.0 ft. Tree alive with "1/16 S4 in healing
double blaze. C.S. 42/392
Set - At true corner point: A 1" x 36" I. Pipe with Brass cap marked:
"Douglas Co. Surveyor" T31S R3W
1976

198

M. Lenora Ladig, Surveyors Office
J. Cook; Karen Cheney
June 9, 1976
C.S. 59/15

Placed 1 1/2" I. Pipe on North side of cap.
Note- Corner lies approx 50 ft. East of the West fork of Stouts Creek.
Corner also lies approx 280 ft. East of Rd. #31-3-3.2 which is a
summer only road.

6/9/76

NE Corner Govt Lot #9
Found - A 5/8" I.R. with 2" Alum. cap set 6" above ground and mkd.
"T31S R3W N 1/16 S4 S3 LS 498" with an 18" mound of stone to top
of cap.
A 1" x 36" I.P. with brass cap set 2" above ground mkd. "Douglas
County Surveyor" T31S R3W Lot 8 Lot 5 Lot 9 Lot 12 S 4 S 3 1976.
A 1 1/2" x 36" I.P. at North edge of brass cap set 6" above ground.
Note: All bearings and distances are from 2" alum. cap.

199

Accessories found:

A 14" now 16" Cedar bears N.65°E., 38.3 ft. with visible scribe
marks in almost healed blaze.
A 14" now 16" Maple bears N.25°E., 45.8 ft. with scribing "1/16
S3 BT in partly healed double blaze.
A 22" now 18" Alder bears South 14.1 ft. with visible scribing
"1/16 S4 T" in rotting double blze.

No New monument set.

Removed DCSO brass cap to recognize alum. cap set by Johnstone survey. (M 65-41)
BLM has confirmed 1 1/2" Iron pipe of prior survey is doubtful. (Ref.
pending BLM survey). See Ren. #198, C.S. 42/392 and M 65 - 41

10/3/77

1/4 Corner for Secs. 3 and 2.

200

Found - A 3/4" Iron rod, bent over. Ren. #96
A 10" now 12" D. Fir bears N.62°W., 411.9 ft. with partially
healed, barked, double blaze and visible scribing "CS BT".
Set - A 5/8" x 30" Iron rod with 1 1/2" Alum. cap set 1.0 ft. below
road surface elevation marked "Douglas Co. 1/4 S3 S2 1977
Surveyor"
New BT - A 6" Maple bears S.29°W., 28.6 ft. double blazed and scribed
"1/4 S3 CS BT"
Note - Corner is in ditch of existing road.

R. B. Kimberling
M. W. Cline
S. J. Flause
Doug. Co. Surveyors
Office
Oct. 25, 1977
C.S. 59/40

-10/25/77