

Douglas County Surveyor's Record of
Government Corners Renewed

T 31 T. S. R 3 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

256

1/4 Corner for Section 31 only of T.31-2

Found - 1" galv. I.P. with 2 1/2" brass cap extended 9" above ground and
mkd. 1966 County Surveyor office. Ren. #190

1" Iron pipe to the southwest and alongside B.C. Ren. #19, T31-2

14" D. fir snag bears N.76°29'E., 21.5 ft. (healed blaze. Ren.#19

19" Hemlock bears S.49°41', 7.2 ft. (healed blaze. Ren.#19, T31-2

New BT - 20" W. fir bears N.43°E., 11.9 ft. scribed "T31S R2W 1/4 BT"
doubled blaze, set 1/2" brass washer in lower blaze.

Bearing tree signs and monument signs were placed on all BTs without them
and a 6" red band and face blazes were painted on all bearing trees.

4/21/88

257

Section Corner for Secs. 32 and 33 only of T.30-3

Found - A 3/4" I.D. iron pipe firmly set and flush with the ground.
(See Ren. #78 in T.30-3)

A 1 1/4" O.D. iron pipe with a 2 1/2" dia. DCSO brass cap loosely set
protruding 20" above ground. Ren. #118. 3/4" I.P. is along
south side of DCSO BC/IP.

(Original stone not seen)

20" now 20" dia. 6 ft. high cedar stump with a fully healed
double blaze bears N.7°E., 6.0 ft. (agrees with rec.)

16" now 18" dia. 6 ft. high cedar stump with partially healed
double blaze, faces are burnt, no scribing visible, bears
S.1°W., 34.0 ft. (Rec. S.1°W., 34.7 ft. possible slope
measurement.)

20" now 24" dia. 6 ft. high cedar stump with a fully healed
double blaze bears S.35°W., 31.7 ft. (Rec. S.35°W., 34.0 ft.
Dist. possible to center of trunk, not root crown)

20" now 35" dia. burnt and dead standing cedar with a fully
healed single blaze, bears N.5°W., 22.0 ft.

Set - Dirt mounded around BC/IP. Brass cap now protrudes 6 ins. above
ground.

No trees alive or suitable stumps in area to use as BTs or BOs.

1/4/89

258

1/4 Corner for Section 34; and Sec. 3 of T.32-3

Found - 1" iron pipe with a 2 1/2" brass cap 10" above ground, properly
mkd. Ren. No. 168

Roothole N.39 1/2°E., 18.6 ft. 12" D. fir down and rotted. Ren. No.13

Roothole S.71 1/2°E., 12.3 ft. 10" D. fir down and rotted. Ren. #13

20" D. fir N.28°W., 23.8 ft. healed blazes. Ren. No. 168

10" W. fir S.71 1/2°W., 18.8 ft. (dead) healed blazes. Ren. No. 168

1 1/2" iron pipe alongside brass capped pipe. Ren. No. 13

(See also Ren. No. 244 for Corner report)

New BT - 8" W. fir S.21°W., 13.9 ft. scribed "1/4 S 3 BT" nailed alum.
washer mkd. "Artman RLS 2268" flush to BT face.

12/90

259

Center 1/4 for section 36.

Set - 5/8" X 30" iron rod with 1" cap marked "ARTMAN RLS 2268"

BTs - 12" D. fir bears S.27°W., 29.5 ft. scribed "C1/4 S36 BT"

54" D. fir bears S.43 1/2°E., 15.2 ft. scribed "C1/4 S36 BT"

6" D. fir bears N.14 1/2°E., 6.9 ft. scribed "C1/4 S36 BT"

8" D. fir bears N.63°W., 16.8 ft. scribed "C1/4 S36 BT"

Note - All BTs have an alum. tag marked "Artman RLS 2268" flush with BT.
Corner lays 275 ft west of a north south ridge.

3/91

260

North 1/4 Corner Section 32

Set by single proportion, a 5/8" x 30" long Iron rod with yellow plastic
cap marked "NYGREN LS1035", extended 3" above ground.

New BTs - A D.Fir 5" dia. bears N.6°E., 28.6 ft. scribed "1/4 S29 BT".

A D.Fir 5" dia. bears S.58°W., 16.8 ft. scribed "1/4 S32 BT".

A D.Fir 8" dia. bears S.48°E., 6.3 ft. scribed "1/4 S32 BT".

A D.Fir 8" dia. bears S.23°W., 17.7 ft. scribed "1/4 S32 BT".

8/20/91

Gerald V. Nygren
S. #1035
ril 21, 1988
S. 63/69

Douglas County
Surveyors office
Randall Smith
Stephen Flause
Jan. 4, 1989
C.S. 62/61

James Artman
RLS No. 2268
Dec. 1990
C.S. 63/124

James Artman
RLS No. 2268
March 1991
M 111 - 67
C.S. 63/101

Gerald V. Nygren,
PLS #1035
For: Medford Corp.
August 20, 1991
M 114-7 and
C.S. 63/134