

Douglas County Surveyor's Record of  
Government Corners Renewed

31 T. S. 4 R. W. W. M.

KOKK-CHAPMAN CO., EUGENE, ORE. 97199

1/4 section corner to sections 21 and 22.  
Found Madrona S.77°30'E., 40.0 feet. Tree down but scribe marks plain.  
Set 4 inch stake.  
Marked 2 new trees: -  
16 inch Fir, S.66°25'E., 35.1 feet.  
30 inch Fir, S.85°W., 25.2 feet.

27

Geo. J. Wenderoth  
March, 1955.  
C. S. File No. 46/107.

Township corner to sec. 36, T 31 S, R 4 W., sec. 1, T 32 S, R 4 W., sec. 6,  
T 32 S, R 3 W., and sec. 31, T 31 S, R 3 W.  
1 1/4 inch iron pipe.  
8" Thorn, S.77°E., 48.8 feet.  
10" Hemlock, S.33°40'W., 185.5 feet.  
24" Fir, N.12°20'W., 142.0 feet.

28

George J. Wenderoth, Dep.  
County Surveyor  
May, 1955.  
C. S. File No. 46/134.

1/4 sec. corner to sec. 36, T 31 S, R 4 W. and sec. 1, T 32 S, R 4 W.  
I. Bar.  
48" Cedar, S.57°09'W., 170.0 feet.  
18" Fir, N.48°E., 130.4 feet.

28A

Robert M. Thompson, R. E. 3683  
For Harbor Plywood Corp.  
April 1, 1955.  
C. S. File No. 41/378.

1/4 sec. corner to secs. 3 and 10.  
A quartz stone, no marks visible.  
The B. T. calls check to a 50 inch Cedar with face burned out, but old axe work  
work visible, and a clump of Madrone sprouts in place of original  
Madrone B. T.  
I renew this corner by marking new B. T.'s in the prescribed manner:  
17 inch Doug. Fir, N.66°15'W., 21.3 feet.  
17 inch Doug. Fir, S.39°50'W., 13.3 feet.

29

Section corner to sections 2, 3, 10 & 11.  
Corner set by double proportion.  
Set a 4 inch X 5 foot yew wood post firmly in the ground,  
from which:  
16 inch Doug. Fir, S.22°50'W., 40.7 feet.  
23 inch Doug. Fir, N.10°10'W., 27.3 feet.  
40 inch Doug. Fir, S.13°40'E., 36.6 feet.  
18 inch Doug. Fir, N.74°20'E., 18.1 feet.

30

FOUND UNRECORDED I.P. &  
NE & SW B.T's. July, 1970  
C.S. 54/20 V.R.T.

1/4 sec. corner to secs. 5 & 6.  
Found stake set in location of original Yew tree. Tree was knocked over  
during road construction. Stake was set by Richard Hamlin to preserve  
location.  
Corner fell on cut bank so set Witness Corner 25.0 feet South.  
Set iron pipe with Brass Cap marked County Surveyors Office T31S R4W,  
Wit Cor 1/4 S 5/6 true corner 25.0' North, 1956.  
From which:  
A 16 inch W. Fir, bears S.43°W., 6.3 feet mkd. 1/4 S 6 CS BT.  
A 14 inch W. Fir, bears S.22°E., 23.5 feet mkd. 1/4 S 5 CS BT.

31

James W. Byron, Deputy County Surveyor.  
June 11, 1956.  
C. S. File No. 47/89.

Section corner to secs. 5, 6, 7, & 8.  
Found OBT, a 28 inch Fir, blown over and with scribing visible. Also  
found stump of 40 inch Fir, no scribing.  
Set an iron pipe with Brass Cap mkd. County Surveyors Office 6/5/8 1956.  
From which:  
An 8 inch R. Fir, bears S.14°W., 34.8 feet mkd. S. 7 CS BT.  
An 6 inch R. Fir, bears N.48°W., 23.3 feet mkd. S 6 CS BT.  
No other trees near.

32

Section corner to sections 11, 12, 13, and 14.  
I find Fir B. T.s for sections 13 and 14 down with scribing and axe work  
visible. No trace of Hemlock in section 12 or of Laurel in Sec. 11.  
I set a 2 inch x 4 inch Fir stake and scribe 4 new B. T.s as prescribed by law;  
12 inch D. Fir, N.40°W., 23.2 feet.  
10 inch D. Fir, N.31°E., 38.1 feet.  
16 inch D. Fir, S.34°E., 69.1 feet.  
40 inch D. Fir, S.59 1/2°W., 42.1 feet.

33

Robert M. Thompson  
Jan. 30, 1956.  
C. S. File No.  
42/200.

RENEWED, SEE CORNER NO. #158