

Douglas County Surveyor's Record of  
Government Corners Renewed

31 T. S. 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Section Corner to Sections 28 & 33.  
Found - 12" Fir N.30°34'E. 32.9 ft. scribe marks visible. **40**  
40" Fir Snag shows old faces. I find bearing to be N.19°W.  
110.9 ft.  
Corner is on logging road. Pipe set at corner not found. - *Rec. #2 - #5 - #7*  
Set Brass Cap marked 1/4 Corner S28 T31S R4W County Surveyor's  
S33 Office, 1956.  
From Which: 12" Cedar bears N.84°E. 68.5 ft. scribed 1/4 S28 CS BT.  
Dec. 28, 1956

James W. Byron  
For Douglas County - Cow Creek #36  
Dec., 1956-Feb., 1957  
Road File Dr. 48/Rd. #36

1/4 Section Corner to Section 36, T31S R4W, & Section 31, T31S, R3W. **41**  
Found - 2"X 2" Sq. Post at corner. Also both orig. BTs (stumps only now)  
The S.W. BT. has visible scribe marks.  
The N.E. BT. has burned face. BTs. check for bearings & distances. **#173**  
Set Brass Cap at corner marked 1/4 R4W R3W T31S, County Surveyor's  
Corner under 3" Log. S36 S31 Office, 1957  
From Which: 16" W. Fir bears N.29°E. 79.5 ft. scribed 1/4 S31 T31S R3W CS BT.  
12" W. Fir bears N.83 1/2°W. 53.2 ft. scribed 1/4 S36 T31S R4W CS BT.  
Feb. 7, 1957

**RE-RENEWED CORNER NO. #173**

Renew Closing Corner to Sections 6 & 5, T31S R4W, and Section 31, T30S R4W.  
Found - All three Orig. BTs., all check bearings & distances. **42**  
The S.W. & S.E. BTs. have open faces, now snags.  
The N.E. BT. alive shows good scar. I do not open.  
Find Stone at corner which is about record size but broken now.  
I do not find notches or C.C. on stone. **#182**  
Set 1 1/2" I.R. at corner & alongside stone.  
New BTs.: 6" Laurel S.71°E. 18.9 ft. scribed C C S5 CS BT.  
40" R. Fir S.31 1/2°W. 12.6 ft. scribed C C S6 T31S R4W CS BT.

James W. Byron, Dep. County Surveyor  
M. Godfrey  
S. Blouw  
For Office Records  
Dec. 11, 1957  
C. S. File No. 49/45

Renew Closing Corner to Sections 5, T31S R4W, & Secs. 31 & 32, T30S R4W.  
Found - All three Orig. BTs. All Check bearing & distances except the  
45" now 48" Fir S.21 1/2°W. Record distance 37.9 ft. should  
be 44.9 ft. **43**  
The Orig. N.76 1/2°W. now dead. I open & find good scribing.  
Also Find 14"X 12"X 5" stone marked as recorded laying on  
ground & 2 ft. North of Corner.  
Set 3/4" I.R. at corner & reset stone at corner.  
C. C. for Sections 5 & 6 bears N.88°W. 111.2 ft.  
New BTs.: 12" R. Fir bears N.64°E. 19.4 ft. scribed CC S32 T30S R4W CS BT.  
10" R. Fir bears N.54°W. 21.2 ft. scribed CC S31 T30S R4W CS BT.

*FOOK K. Hoffmann  
4/94/123-69*  
**RE-RENEWED**

*S.W. Sec. 31*  
Township Corner common to Twps. T31/R4; T31/R5; T32/R5; T32/R4.  
Found - 3/4" Iron Pipe (unmarked) **44**  
24" Fir S.62 3/4°W. 39.5 ft., blaze healed.  
50" Fir Stump S.74 1/2°E. 25.5 ft., scribing visible.  
40" Fir Stump N.65°E. 20.0 ft., blaze healed.  
16" Fir Stump N.16°W. 54.0 ft., blaze healed.  
10" Fir N.79 3/4°E. 9.8 ft., scribing visible.  
Scribed: 6" Cedar N.27°W. 16.6 ft. mkd. S36 RE3024 BT.

Richard L. Templin, Jr.  
Sept. 1958  
C. S. File No.  
42/389

*FD OK 1995-0115A/B JULY 94 R. Templin*

Section Corner to Sections 13, 14, 23, & 24.  
As Det. by O.B.T.'s: 30" Fir bears S.29°W. 6.6 ft. dist. O.B.T. **45**  
I remark on bark S23 B.T.  
15" Fir Stump bears N.71°E. 6.3 ft. O.B.T.  
18" Fir bears S.69°E. 36.3 ft. dist. O.B.T.  
I remark on bark S24 B.T.  
16" Fir bears N.35°W. 25.7 ft. dist. O.B.T.  
I rescribe on bark S14 B.T. **103**  
At Corner Point found Stone & Set Iron Pipe from which:  
18" Fir bears N.82°E. 29.0 ft. dist. mkd. S13 T31S R4W B.T.

John H. Markham, Jr.  
For Stomar Lbr. Co.  
Oct. 2, 1958  
C. S. File No. 42/391

**RE-RENEWED CORNER NO. 103**