

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

99

James W.
Byron &
Crew
March 1963
C.S. File
No. 52/138

Renewed Corner $\frac{R4W}{S36} / \frac{R3W}{S31}$ T30S
S 1 T31S

Found - 1" I. Bar at Corner & BT's. as recorded by Markham, 1959 (see #149 T30-4)
Orig. 13", Laurel N.16°W. 33.0 ft., bark scribed, we rescribe (wood)
T30S R4W S36 CS BT.
Chinquapin to N. W. now dead.

100

Closing Corner Sec. 1, T31-4W & Sec. 6, T31-3W.

Found - Orig. 14", now 24" Maple S.67°W. 42.5 ft., shows good scribing.
Orig. 36", now 40" Fir S.55½°E. 22.6 ft., shows scribing.
Orig. N.E. BT., shows scar. We find Corner Stone as recorded.

Set - Brass Cap alongside Cor. Stone & Mkd: County Surveyor's R4W T30S R3W
Office, 1963 C C

Rescribe, now 24" Maple T31S S.67°W. 43.0 ft. S1 CS BT CC.

$\frac{S1}{S1} / \frac{S6}{T31S}$

101

Closing Corner to Sections 32 and 33 only, T30S R4W.
North Boundary // T31S R4W.

Found - Stone & all Bearing Trees, as recorded, except N.E. & N.W. BT's.
Now Snags.

Set - Brass Cap at Corner & Alongside Corner Stone, Mkd:
CC $\frac{S32}{S33}$ T30S R4W County Surveyor's
T31S Office, 1963

New BT's: 9" R.Fir bears N.33°W. 31.0 ft. scribed CC S32 T30S R4W CS BT.
8" Laurel bears N.33°E. 31.6 ft. scribed S33 CC T30S R4W CS BT.

Old $\frac{1}{4}$ $\frac{S34}{S3}$ T30S R4W
T31S

Note - This corner controls the Township Line only. It is not a
 $\frac{1}{4}$ corner for either S34 T30S or S3 T31S.

Found - Both Orig. BT's & both BT's as recorded by Markham.
Do not find Stone at Cor. as recorded by Markham. (See Cor. #162,
T30S R4W)

Set - $\frac{1}{4}$ " I. Rod at Corner.

Sept. 3, 1963

103

Section Corner to Sections 13 - 14 - 23 - 24.

Found - 1" Iron Pipe at Corner, See Ren. #45.

Orig. 30" Fir S.29°W. 6.6 ft., blown down, bark scribe S23.

Orig. 15" Fir Stump gone.

Orig. 18" Fir S.69°E. 36.3 ft., blown down.

Orig. 16" Fir N.35°W. 27.5 ft., cut & pushed over. Has old
bearing tree tag on it.

18" Fir (Tree mkd. by Markham) N.82°E. 29.0 ft., blown down.

Set - Brass Cap at Cor. Mkd: County Surveyor's T31S R4W $\frac{S14}{S23} / \frac{S13}{S24}$
Office, 1965

New BT's: 32" D. Fir East 92.3 ft. scribed T31S R4W S24 CS BT.

5" D. Fir N.36°E. 22.0 ft. scribed S13 BT.

31" D. Fir N.2½°W. 105.1 ft. scribed T31S R4W S14 CS BT.

6" D. Fir S.72°W. 40.3 ft. scribed S23 BT.

Renewed by John Powell & J. Brady, Sept. 28, 1965, C. S. File No. 52/40.

104

Township Corner T. 31 & 32 S., Ranges 3 & 4 West.

Found - I. Pipe at Corner out of ground, See Ren. #28 #31-2W.

8" Thorn, S. 77° E. 48.8 ft., scribe visible "S6 CS BT".

10" Hemlock, now 12" S. 33½° W. 185.5 ft. scribe visible.

24" Fir Stump N. 12° W. 142.0 ft.

Set - Brass Cap at Township Corner Mkd:
County Surveyor's R $\frac{S36}{S1} / \frac{S31}{S6}$
Office, 1966 4 3 W

T 31 S
R $\frac{S36}{S1} / \frac{S31}{S6}$
4 3 W
T 32 S

FD OK
BY R. BROWN
R 4-93
3 M112-72

New BT's: 6" D. Fir N.2°E. 120.2 ft. scribed S31 CS BT.

11" Hemlock S.75°E. 62.9 ft. scribed T32S R3W S6 CS BT.

Best way to reach corner is to wade Cow Creek in the summer.

James W. Byron, Deputy County Surveyor
Mike Darby and Wm. Stoffel
July 1963
C. S. File No. 53/26

Corner No. 103.

John M. Powell
F. Jones & J. Brady
January 13, 1966
C. S. File No. 52/63