

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

135

Section Corner to Sections 21 - 22 - 27 - 28.
Found - Iron Pipe, See Ren. #9.
Orig. 20" Fir, now 21", S. $14\frac{1}{2}^\circ$ W. 20.5 ft., opened for scribe.
8" Yew Wood, now 11" S. $65^\circ 18'$ E. 45.9 ft. (dist. S.E. 47.0 ft.)
(Scribing visible "S27 CS BT".)
4" Hemlock, now 12", N. $5\frac{1}{2}^\circ$ E. 53.6 ft.
26" Fir, N. 33° W. 60.1 ft., shows good scar.
Set - Brass Cap at Sec. Cor. Mkd: County Surveyor's Office, 1966
(Set alongside Iron Pipe)

T31S R4W
S 21 S 22
S 28 S 27

Reblazed & Rescribed: 12" Hemlock N. $5\frac{1}{2}^\circ$ E. 53.5 ft. scribed T31SR4WS22CSET.
34" Fir N. 33° W. 60.1 ft. scribed T31SR4W S21 CS BT.
New BT: 9" Yewwood S. 24° W. 44.2 ft. scribed T31S R4W S28 CS BT.

136

$\frac{1}{4}$ Corner to Sections 7 and 18.
Found - Set Quartz Stone at $\frac{1}{4}$ Corner, Ren. #68.
18" D. Fir, now 21", S. 74° W. 18.1 ft. scribe visible "BT".
(This Bearing S.B. S. 64° W.)
12" D. Fir, now 14", N. $45\frac{1}{2}^\circ$ E. 21.6 ft. scribed visible "BT".
Set - Brass Cap at $\frac{1}{4}$ Cor. Mkd: County Surveyor's Office, 1966
(Set alongside Quartz Stone)

T31S R4W
$\frac{1}{4}$ S 7
S 18

All BT's. in good condition. - This corner lies about 50.0 ft. N. of Ravine.

137

Sec. Cor. to Sections 23 - 24 - 25 - 26.
Found - Steel Fence Post at Sec. Cor. See Ren. #49.
6" Fir, now 10", N. 50° E. 20.0 ft., pitched over, scribe visible.
8" Maple, now 9", S. 79° E. 135.0 ft., scribe visible "S26 R4W 27".
6" Fir, now 8", N. 65° E. 20.6 ft., pitched over, scribe visible.
4" Fir, now 7", S. 30° E. 10.0 ft., scribe visible "S".
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

T31S R4W
S 23 S 24
S 26 S 25

New BT: 30" D. Fir S. 88° W. 57.3 ft. scribed T31S R4W S26 CS BT.
Note - Old Logging Road bears East 290.0 ft.

138

$\frac{1}{4}$ Corner to Sections 16 and 21.
Found - Steel Fence Post at $\frac{1}{4}$ Corner, See Ren. #47.
26" Fir, now 27", N. 69° W. 67.0 ft., pitched over, scribing visible.
16" Fir N. 5° E. 213.0 ft., pitched over, scribing visible.
Orig. 22" Fir Stump S. 29° W. 29.0 ft.
Set - Brass Cap at $\frac{1}{4}$ Cor. Mkd: County Surveyor's Office, 1966

T31S R4W
$\frac{1}{4}$ S 16
S 21

Bearing Trees in good condition.

139

$\frac{1}{4}$ Corner to Sections 8 and 9.
Found - 24" Fir Corner Tree scribe visible " $\frac{1}{2}$ S" on W. face. Ren. #25.
Orig. 30", now 36" D. Fir S. 43° E. 17.0 ft., shows good scar.
Orig. 30" B. Fir Stump N. $53\frac{1}{2}^\circ$ W. 10.0 ft., shows scar.
Set - Brass Cap at $\frac{1}{4}$ Cor. Mkd: County Surveyor's Office, 1966
T31S R4W $\frac{1}{4}$ S 8/S 9
New BT: 10" D. Fir N. 12° E. 4.3 ft. scribed $\frac{1}{4}$ S CS BT.

140

$\frac{1}{4}$ Corner to Section 18 only.
Found - Iron Pipe at $\frac{1}{4}$ Corner, See Ren. #66. I. Pipe Rusty.
13" D. Fir, now 14", N. $46\frac{1}{2}^\circ$ E. 52.2 ft., scribe visible, "S18",
rest pitched over.
12" D. Fir, now 16", S. $24\frac{1}{2}^\circ$ E. 25.3 ft., good scars.
(Distances to the face of trees)
Set - Brass Cap at $\frac{1}{4}$ Cor. Mkd: County Surveyor's Office, 1966

R	T31S	R
5	S 18	4
W		W

Bearing Trees in good condition.

John M. Powell
Frank Jones and Joe Eady
March 1966
C. S. File No. 54/20