

**Douglas County Surveyor's Record of
Government Corners Renewed**

31

T. S.

4

R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

Clell Goodwin
Gary Langlitz
M. Lenora Ladig
C S 57/39
1 25/75

1/4 corner to Sec. 12 and 13 REN # 78 **157**
Found-A 19" Fir with scribe marks visible in partially healed blaze bears
S46°W., 44.0 ft.
The tree found by Markham to be an Orig. bearing tree is now a 16" dead
snag. We find no scribe marks in partially healed blaze.
Set- At the corner we set a 1" X 30" IP with brass cap stamped
"DOUGLAS CO. SURVEYOR T 31 S R4W
1975 1/4 $\frac{S\ 12}{S\ 13}$

There are no live trees big enough to scribe nearby. Compass Declination 20°E
Note: We also find the remains of the laurel in the NW quadrant with
visible scribe marks in the bark but are unable to accurately determine
where it stood. 11/25/75

Sec. Corner to Sec. 11, 12, 13, and 14. See Ren # 33 **158**
Found- An unrecorned 1 1/2" x 20" flanged axle.
From which: An orig. 28" fir now Rotted stump bears S31 1/4°E., 9.1 ft.
A 17" D Fir bears N45°W., 24.3 ft. (call: N40 1/2°W., 23.2 ft) alive and well
healed.
A 14" D. Fir bears N31°E., 37.0 ft. (call: N31°E., 38.1 ft) alive and well healed.
A 20" D. Fir bears S34°E., 69.1 ft. alive and well healed
A 34" stump bears S57 1/2°W., 44.1 ft. (call: S59 1/2°W., 42.1 ft)
Renewal-At the corner we set a 1" X 30" IP with brass cap stamped

DOUGLAS CO. SURVEYOR T31S R4W
1975 $\frac{S11\ S12}{S14\ S13}$
We drive the axle in SW of the Corner.
a 9" D. Fir scribed "T31S R4W S14 CS BT" in a double blaze bears S40°W., 22.7 ft
Compass Declination 20° East 11/26/75

1/4 Corner to Secs. 9 & 10. See Ren. #75. **159**
Found - 3/4" X 18" I.P. from which:
Orig. 11" now 22" La. bears N16°E., 26.4 ft. Tree has rotten
insides, no trace of markings.
9" La bears N47°W., 17.8 ft. Has faint bark scribing (tree appears
to sprout from orig. N.W. tree), tree is alive.
18" La bears N79°W., 36.0 ft. Tree is alive with "1/4 S9 X" in
unhealed blaze and "BT" bark scribe.
14" La bears N15°W., 34.5 ft. tree is alive with partly healed blaze.
9" La bears S26°W., 9.0 ft. (call S26°W., 8.0 ft.). Tree is alive
with "1/4 S9 T31S R4W BT" in visible bark scribe.
A downed La with "1/4 S10 BT" in unhealed blaze (tree pushed up by cat
Set - At true corner point a 1" X 36" I.P. with brass cap marked:

Douglas County Surveyor
T31S R4W
S9 | S10
1/4 1976
Placed Fd. 3/4" I.P. South of cap.
New BT - 7" D. fir bears N45°W., 31.4 ft. scribed "1/4 S9 CS BT" in
double scribe.
No suitable trees to the South.
NOTE: Corner lies S.W. from end of Rd #31-4-3.0 on cutting line.
Compass dec. 20° East.

SEE NEXT PAGE

11/26/75

M Lenora Ladig
C y L. Langlitz
James H. Cook
Douglas County
Surveyor's Office
C.S. 59/15
6/2/76