

Douglas County Surveyor's Record of  
Government Corners Renewed

T31      T. S.      R4      R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 31891

1/4-Corner Secs. 4 & 9. See Ren. #26

Found - Two 3/4" I.P.'s at corner from which:

33" now 36" dead fir snag bears S61°E., 28.5 ft. with "1/4 S9 BT" in visible bark scribe.

36" now 40" dead fir snag bears N21°E., 9.5 ft. with "1/4 S9 T31S R4W BT" in visible bark scribe.

Set - 1" X 36" I.P. with brass cap marked: Douglas County Surveyor

T31S R4W

1/4 ———  $\frac{S4}{S9}$  ——— 1976

Placed both 3/4" I.P.'s on North side of cap.

New BT's - 8" D. fir bears S36°E., 23.1 ft. scribed "1/4 S9 CS BT" in double blaze.

6" D. fir bears N10°W., 11.2 ft. scribed "1/4 S4 CS BT" in double blaze.

NOTE: Corner lies approx. 200 ft. East of Rd. #30-4-28.0.

Compass Dec. 20° East.

160 M. Lenora Ladig  
L. E. Monrean  
Pete L. Earle  
Douglas County  
Surveyor's Office  
C.S. 59/15  
6/7/76

Section Corner for Secs. 3, 2, 10 and 11.

Found - An unrecorded 1 1/2" x 26" I. Pipe. (First noted July 1970 by V.R.T., C.S. 54/20)

A 23" now 27" D. Fir bears N.10°10'W., 27.3 ft. Tree alive with well healed blaze. Ren. #30

A 40" now 41" D. Fir bears S.13°40'E., 36.6 ft. Tree alive with "31-4" in cut open blaze.

Note - July 1970. V.R.T. of County Surveyors Office (C.S. 54/20) stated he fd. the NE & SW BT as recorded in Ren. #30 with NW & SE BT's gone due to logging. I find NW & SE BT's as recorded in Ren. #30 with the NE & SW BT's gone.

Set - At true corner point, A 1" x 36" I. Pipe with Brass cap stamped:

"Douglas Co. Surveyor"      T 31 S R 4 W  
1976

$\frac{S 3 | S 2}{S 10 | S 11}$

Placed 1 1/2" I. Pipe on North side of Cap.

Did not mark new trees as no good trees in area due to logging.

6/10/76

East 1/16 Corner for Secs. 3 and 10.

Found - A 3/4" Iron Pipe. C.S. 42/391

A 6" now 8" Chinquapin bears N.34°W., 11.3 ft. Tree is alive with partly healed blaze.

A 4" now 8" Fir bears S.67°W., 12.7 ft. Tree alive with well healed blaze.

Set - At true corner point: A 1 1/2" x 36" I. Pipe with Brass cap mkd.

"Douglas Co. Surveyor"      T 31 S R 4 W  
1976

E       $\frac{S 3}{S 10}$   
1/16

Placed 3/4" I. Pipe on North side of Brass cap.

Note - Corner lies approx. 160 ft. East of Rd. #31-4-3.0.

5/25/76

Section Corner for Secs. 4, 3, 9 and 10. Ren. #93

Found - A 1/2" I. Pipe with orig. 14"x12"x6" Stone on North side. (Fd. on stone: 3 notches on east edge and 5 notches on north edge.)

An orig. 30" now 48" Fir bears N.15°E., 33.6 ft. Tree alive with healed blaze.

An orig. 18" now 40" Fir bears S.20°W., 54.0 ft. Tree alive. Blaze has been opened and scar is pitched over.

An orig. 14" now 26" Fir bears N.79°W., 60.0 ft. Tree alive. Blaze has been opened and scar is pitched over.

A 8" now 12" Laurel bears N.67°E., 28.6 ft. with "S3 T31S R4W BT" visible bark scribe. Tree is alive.

Set - At true corner point: A 1 1/2" x 36" I. Pipe with Brass Cap stamped:

"Douglas Co. Surveyor"      T 31 S R 4 W  
1976

$\frac{S 4 | S 3}{S 9 | S 10}$

Placed stone on North side of cap and 1/2" I. Pipe on south side of cap.

Note - Did not scribe a S.E. BT as area is a clear cut. Corner lies 100' North of Rd. #31-4-3.0.

5/25/76

161

162

163

M Lenora Ladig, Douglas County Surveyors Office  
Pete L. Earle  
5/25/76 and 6/10/76  
C.S. 59/15