

Douglas County Surveyor's Record of
Government Corners Renewed

31 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

23

$\frac{1}{4}$ Corner to Sections 14 & 23.

Found - Basalt Stone 15" x 10" x 8" marked $\frac{1}{4}$ from which:

Fir Snag, burned off nearly flush with the ground, bears
N.22°W. 13 lks.

There is no sign of the Cedar BT that should have been on
a rock outcrop. This BT very easily could have blown
over, burned and left no evidence.

Set - $1\frac{1}{2}$ " Iron Pipe 36" long, Set 30" into a mound of Stones.

It replaces the original Stone that is left there as a memorial.

This Corner falls at the East base of a solid rock outcrop 10' high
and is in an old burn, there are no trees available for
Bearing Trees. I marked 2 Bearing objects, both are 4" + 's
chisled into the rock outcrop.

4" + N.68°W. 8.5 ft.

4" + S.50° 30' W. 2.2 ft.

May 1966 - CAR. SEARCHED FOR
NOT FOUND - J. POWELL

24

$\frac{1}{4}$ Corner to Sections 14 & 15 - 15/14

Found - Stone 14" x 8" x 6" - 10" in ground marked $\frac{1}{4}$ on West Side.
Cedar Snag S.45°E. 12 lks. burned and no scribing visible.
Stump Hole from a Fir Tree N.62°W. 56 lks. The Stone
appears to have never been touched since it was originally
set.

Set - $1\frac{1}{4}$ " Iron Pipe 36" long 24" in the ground - it replaces the
stone which is still there as a memorial. I set the
following new Bearing Trees:

18" Fir N.41°W. - 23.5 ft. scribed $\frac{1}{4}$ S 15 BT

12" Yew S.33°E. - 34.5 ft. scribed $\frac{1}{4}$ S 14 BT

25

Section Corner to Sections 14, 15, 22, & 23. - $\frac{15}{22} \frac{14}{23}$

Found - 3 Original B.T.'s.

14" Live Oak N.25°W. 50 lks.

9" Madrona N. 05°E. 20 lks.

32" Fir S.50°W. 35 lks.

The Madrona shows scribing. The Oak & Fir have not been
chopped into, but show the scars of old blazes.

Set - $1\frac{1}{4}$ " Iron Pipe 36" long in a Mound of Stones, from which
I set the following new Bearing Trees.

10" Sugar Pine N.10°E. 32.0 ft. scribed T31 R5 S 14 BT

15" Fir S.49°E. 28.7 ft. scribed T31 R5 S 23 BT

26

Section Corner to Sections 17, 18, 19, & 20 - $\frac{18}{19} \frac{17}{20}$

Found - Original BT, 36" Fir N.68°W. - 23 lks. with scribing
visible. (I rescribed this corner in the bark)

Set - 1" Steel Reinforcing Rod 36" long 30" in the ground, from
which I set the following new Bearing Trees.

7" W. Fir S.72°E. 13.4 ft. scribed T 31 R 5 S 20 BT

9" W. Fir S.24°W. 29.6 ft. scribed T 31 R 5 S 19 BT

12" W. Fir N.40°W. 6.9 ft. scribed T 31 R 5 S 18 BT

27

Section Corner to Sections 18 & 19, T31S R5W., & Secs. 13 & 24, R6W.

Found - Original BT: 10" Live Oak N.43°E. 40 lks, with scribing.

8" Laurel N.41°W. 41 lks., this BT. is
dead & rotten, but shows old scar from blaze.

Set - $1\frac{1}{2}$ " Iron Pipe 3' long from which I set the following new BT's.

5" Fir N.44°E. 28.9 ft. scribed T 31 R 5 S 18 BT

11" Live Oak S.61°E. 35.7 ft. scribed T 31 R 5 S 19 BT

10" Live Oak S.46°W. 15.4 ft., scribed T31 R6 S 24 BT

6" Fir N.63°W. 14.4 ft. scribed T 31 R 5 S 23 BT

Victor S. King
Witness: Chester C. Jones
For: Bate Lumber Co., Merlin, Oregon
Feb. 5, 1959
C. S. File No. 42/425

75

76

90

92