

Douglas County Surveyor's Record of  
Government Corners Renewed

31 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 15, 16, 21 and 22. 44

Found - Wood Stake in mound of stones.

Cedar Snag with old X (before the burn).

2 Fir Stump holes, a stool of Madrona. These all fit the bearing & distance for the orig. bearing trees. No scribing anywhere.

There is a blzd line coming in from the South. Found 1 original blze 692 ft. north of the corner.

Set - 1" Pipe 30' long in a mound of stones.

Scribed the following new bearing trees:

4" live Oak N.72 $\frac{1}{2}$ °W. 16.5 ft. scribed T31S R5W S16 BT.

6" Madrona S.84 $\frac{1}{2}$ °W. 36.1 ft. scribed T31S R5W S21 BT.

8" Madrona S.52°E. 8.1 ft. scribed T31S R5W S22 BT.

8" Madrona N.33°E. 28.4 ft. scribed T31S R5W S15 BT.

Victor S. King  
For Bate Lumber Co.  
August 11, 1960  
C. S. File No. 51/56

FD. OK  
B. Shaner  
6/92 M112-49

$\frac{1}{4}$  Section Corner to Sections 16 and 21. 45

Found - Original BT: 40" Fir with bark scribing plainly visible S.18°W. 53 lks.

Original blazes to the West.

Set - 1" Iron Pipe 45" long in a mound of stones.

Scribed the following new bearing trees:

24" Fir N.32 $\frac{1}{2}$ °W. 29.3 ft. scribed  $\frac{1}{4}$  S16 BT

22" Fir S. 8 $\frac{1}{2}$ °E. 38.3 ft. scribed  $\frac{1}{4}$  S21 BT.

Section Corner common to Secs. 29, 30, 31 and 32. 46

Orig - Fir Stake (missing) from which a:

20" Fir bears N.23°E. 31 lks.; now 32" stump.

10" Chinquapin bears S.32°E. 34 lks.; sprouted in place.

32" Fir bears S.45°W. 65 lks.; 48" uproot, face down.

18" Fir bears N.80°W. 62 lks.; now 20" Stump.

Restoration by Victor S. King, 1959. *REN. #1* 73

Fir stake (found, not in place) from which a:

12" Fir bears N.89°E. 93.3 ft.; uproot, scribed T31S R5W S29 BT.

14" Fir bears N.63 $\frac{1}{2}$ °W. 103.8 ft.; uproot, scribed T31S R5W S30 BT.

48" Fir (orig.) bears S.45°W. 56.1 ft.; uproot, face down.

18" Fir bears S.10°E. 68.4 ft.; uproot scribed T31S R5W S32 BT.

Restored: Set 1 $\frac{1}{2}$ " x 36" Gal. iron pipe with 3" cap mkd: "Ore.St.Bd. of Forestry S29 S30 S31 S32 T31S R5W 1963 RS 359", 30" in ground, from which:

26" stump bears N.12°E. 12.0 ft.; scribed T31S R5W S29 BT.

26" Fir bears S.13°W. 59.6 ft.; scribed T31S R5W S31 BT RS359.

22" Fir bears S.74°E. 180.0 ft.; scribed T31S R5W S32 BT.

Set - 4" x 4" x 72" white painted Cedar Post 1.0 ft. SE. of corner pipe.

Ore. State Forestry Dept. metal location poster on 26" stump BT.

Oregon State Bd. of Forestry  
Arnold G. Gibson  
D. Bagger, R. Schulson, H.B. Baughn  
August 1963  
C. S. File No. 51/264

$\frac{1}{4}$  Corner common to Sections 30 and 31. 47

Orig. - Cedar Stake (missing) from which a:

20" Fir bears N.70°E. 28 lks.; now 42" stump.

24" Fir bears S.35°W. 9 lks.; now 36" unproot stump, scribes  $\frac{1}{8}$ S visible in bark. 72

Restored: Set 1 $\frac{1}{2}$ " x 36" Gal. Iron Pipe with 3" cap mkd: "Ore.St.Bd. of Forestry  $\frac{1}{4}$  S30 S31 1963 RS 359", 30" in ground & from which a:

23" Hemlock bears S.26°W. 25.8 ft.; scribed  $\frac{1}{4}$  S31 BT.

23" Cedar bears N.24°E. 28.1 ft.; scribed  $\frac{1}{4}$  S30 BT RS 359.

Set - 4" x 4" x 72" white painted Cedar post 3.0 ft. N. of corner pipe.

Ore. St. Forestry Dept. metal location poster on Cedar BT.

$\frac{1}{4}$  Corner common to Secs. 31 and 32. 48

Orig - 36" Sugar pine (now 42" stump, cut low) from which a:

22" Fir bears S.45°E. 3 lks.; now 32" stump, in place, burnt and rotted.

6" Dogwood bears N.30°W. 16 lks.; burnt roots in ground.

3 link Cr., SE, North 7.00 chains; in place. Line Blazes N & S.

Restored - Set 1 $\frac{1}{2}$ " x 36" Gal. Iron Pipe as ref. monument N16E. 2.1 ft. from cor. point in center of pine stump with 3" cap mkd: "Ore.St.Bd. of Forestry RM 2.1 ft. 1963 RS 359", 30" in ground & from which a:

(continued next page)