

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 5 W R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Aug. 1963
C.S. File
No. 51/264

(continued)

48

from which a:

26" 5" Fir bears N.31°E. 23.8 ft.; scribed $\frac{1}{4}$ S32 BT.
15" Fir bears N.75 $\frac{1}{2}$ °W. 54.0 ft.; scribed $\frac{1}{4}$ S31 BT RS 359.
Set - 4" x 4" x 72" white painted Cedar Post 2.0 ft. East of corner piep.
Ore. State Forestry Dept. metal location poster on 15" Fir BT.

Section Cor. to Secs. 2 & 3, T31-5W. & ~~Secs. 34 & 35, T30-5W.~~

49*

Found - Mound squared stake & Mound of Stone at Corner and Bearing
Trees as recorded, Ren. No. 29,

Set - Brass Cap at Cor. Mkd: County Surveyor's

S34	S35	T30S	
S 3	S 2	T31S	R5W

No New Bearing Trees.

Sec. Cor. to Secs. 5 & 4, T31-5W. & Secs. 32 & 33, T30-5W.

50

Found - Brass Cap at Cor. and all Bearing Trees as recorded. #110

See Corner #32, T30-5W. All BT's. now snags.

New BT's: 16" R.Fir bears N.86°W. 71.1 ft. scribed S32 T30S R5W CS BT.

(This BT. scribed 3' high, Log on east side)

18" Laurel N.70°E. 86.4 ft. scribed S33 T30S R5W CS BT.

16" R.Fir bears S.66°E. 35.7 ft. scribed S 4 T31S R5W CS BT.

$\frac{1}{4}$ Cor. to Sec. 31 only, T30-5W. (South Side Sec. 31)

51

Found - 1" I.P. at Corner & both BT's. as recorded, Cor. #60, T30-5W.
Each BT. has had scribing axed off.

New BT's: 10" Laurel bears N.58°W. 10.0 ft. scribed S $\frac{1}{4}$ S31 CS BT.

8" B.Oak bears N.29°E. 31.2 ft. scribed S $\frac{1}{4}$ S31 CS BT.

Township Corner

S36	S31	T30S	
R6W	S 1	S 6 R5W	T31S

52

Found - $\frac{3}{4}$ " I.P. at Corner & all BT's. as recorded, See Cor. #2. #112
Bearing Trees to north now stumps.

Note - Small stream is 25 ft. west of corner.

New BT's: 14" Maple bears North 37.6 ft. scribed S36 T30S R6W CS BT.

6" R.Fir bears N.70°E. 30.9 ft. scribed S31 CS BT.

Sec. Corner to Secs. 1 & 2, T31-5W. & ~~Secs. 35 & 36, T30-5W.~~

53*

Found - 3# Sq. Stake at Corner & BT's. as recorded, Ren. #30, T30-5W.

Set - Brass Cap at Cor. Mkd: County Surveyor's

S36	T30S	
S 2	S 1	T31S R5W

Office, 1963

No new Bearing Trees.

$\frac{1}{4}$ Corner to ~~Sec. 36, T30-5W.~~ & Sec. 1, T31-5W.

54*

Found - Both Orig. BT's. Orig. 6", now down 10" Laurel N.55°W. 13.9 ft.

We open & find good scribing "BT".

Orig. S.E. BT. shows old axe work.

Corner Stone not found, corner is on steep east slope.

Set - $\frac{3}{4}$ " I. Rod at Corner.

New BT's: 7" R.Fir bears N.20°W. 16.8 ft. scribed $\frac{1}{4}$ S36 CS BT.

8" R.Fir bears S.35°W. 17.2 ft. scribed $\frac{1}{4}$ S1 CS BT.

$\frac{1}{4}$ Corner to Sec. 2, T31-5W. & ~~Sec. 35, T30-5W.~~

55*

Found - Orig. 12", now 20" Laurel S.10°E. 21.0 ft.

Orig., now 20" Laurel Stump N.15°W. 17.8 ft. We open S. E. BT.
& find good scribing "T".

New BT's 13" Cedar bears S.38°E. 28.0 ft. scribed $\frac{1}{4}$ S 2 CS BT.

22" Laurel bears N.25°W. 20.0 ft. scribed $\frac{1}{4}$ S35 CS BT.

Note - Corner is on West slope 100.0 ft. East of small stream.

CORNERS No. 49-53-54 & 55
NOT COMMON - SEE
1966 DEPENDENT
RESURVEY

*

James W. Byron, Deputy County Surveyor
Mike Darby and James Halterman
November & October 1963
C. S. File No. 53/26

RE-RENEWED CORNER NO. #110