

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31881

80

Sec. Corner to Sections 27 - 28 - 33 - 34.
Found - GLO Brass Cap at Sec. Cor., 1955.
25" R. Fir, now 26", N. 76° E. 31.7 ft., pitched over,
scribing visible.
15" R. Fir, now 17", S. 35° W. 46.9 ft., shows good scar.
15" Hemlock, now blown down, S. 24° E. 55.1 ft.
20" Pine, now blown down, N. 26° W. 40.9 ft.
New BT's: 5" Live Oak N. 87° W. 19.0 ft. scribed S28 CS BT.
8" Maple S. 12° E. 31.0 ft. scribed T31S R5W S34 CS BT.
Note - This corner lies in deep draw with creek South 50.0 ft.

81

1/4 Corner to Sections 28 and 27.
Found - Stone at Cor. Mkd: 1/4 on West Face, Ren. #39.
Orig. 46" D. Fir, now 64", N. 80° E. 17.8 ft., bark scribe vis.
Orig. 54" Pine, now stump, N. 65° E. 30.4 ft.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966 #127
New BT: 13" W. Fir N. 43° W. 104.3 ft. scribed 1/4 S28 CS BT.

RE-RENEWED CORNER NO. #127

82

1/4 Corner to Sections 21 and 22.
Found - Fir Post at 1/4 Corner, See Ren. #40.
44" Cedar N. 25° E. 12.5 ft., bark scribed 1/4 S22 BT.
32" Cedar S. 35° W. 22.4 ft., bark scribed 1/4 S21 BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966 T31S R5W 1/4 S 21/S 22
New BT's: 12" Pine S. 71° E. 34.0 ft. scribed 1/4 S22 CS BT.
15" D. Fir S. 73° W. 19.2 ft. scribed 1/4 S21 CS BT.
Note - This corner is about 360.0 ft. south of power line.

83

Sec. Corner to Section 21 - 22 - 27 - 28.
Found - Scribed Stake mkd. "RS 442", See Ren. #38.
16" D. Fir, N. 66° E. 29.0 ft., shows good pitched over
scribe marks.
36" D. Fir N. 32° W. 54.3 ft., shows good face.
14" W. Fir S. 51° W. 19.5 ft. scribe visible "T31S R5W BT.
Orig. 32" D. Fir S. 30° E. 9.9 ft., shows good face.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966 T31S R5W
S 21 | S 22
S 28 | S 27

All Bearing Trees in good condition.

84

1/4 Corner to Sections 17 and 16.
Found - Fir Post at Corner, See Ren. #33.
Orig. 30" Fir, now 40", S. 75° W. 27.1 ft., opened for old
scribe marks. Had been opened but could not see any marks.
34" D. Fir, now 36", S. 73° E. 34.0 ft., shows good face.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966 T31S R5W 1/4 S 17 / S 16
Reblazed & Rescribed:
40" D. Fir S. 75° W. 27.1 ft. scribed 1/4 S17 CS BT.
(This tree is Double Fir)
Note - Corner lies in bottom of small ravine.

85

Sec. Cor. to Sections 8 - 9 - 16 - 17.
Found - 1" Iron Pipe at Corner, See Ren. #36.
Orig. 6" Dogwood, now dead, S. 21° E. 7.9 ft.
48" Fir N. 29° W. 39.5 ft., bark scribed "T31SR5WS8 BT" faint.
18" Fir, now 21", S. 64 1/2° E. 86.5 ft.
12" Fir, now 14", S. 41 1/2° W. 10.7 ft.
24" W. Fir, N. 69 1/2° E. 8.7 ft., face rotten on this tree.
All BT's. have recently been opened, but O.K., with exception of one.
New BT: 28" D. Fir N. 86° E. 56.0 ft. scribed T31S R5W S9 CS BT.
Reblazed & Rescribed: 48" Fir N. 29° W. 39.5 ft. scribed T31S R5W S8 CS BT.
Note - Corner now lies in cutting corner.

John M. Powell
Frank Jones and Joe Brady
May 1966
C. S. File No. 54/25

FD ok
By Stone
4/103 Miller
CS 6/31/49