

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued)

55" Fir bears S. 15° W. 11.5 ft.; scribed T31S R6W S 1 BT.
(also scribes S6 CS BT by Wenderoth).
6" Fir bears N. 86° W. 54.5 ft.; scribed T31S R6W S36 BT.
4" Hemlock bears S. 58° E. 22.3 ft.; scribed X
4" Fir bears N. 9° E. 19.0 ft.; scribed X.
Wenderoth's 2" Pipe bears West 15.3 ft.
Set 4" x 4" x 72" white painted Cedar Post 2.0 ft. South of Corner
Pipe. Ore. St. Forestry Dept. metal location poster on 55" Fir BT.
Also RWM poster on 36" Fir 150.0 ft. N. on N. side of creek.

RE-RENEWED SEE CORNER NO. #123

Arnold G. Gibson
July 15, 1966
C. S. File No. 55/6

1/4 Corner to Sec. 7, T31-5W. & Sec. 12, T31-6W. 101
Found - Orig. 6" fir S. 48° W. 8.6 ft., now remains of old Fir,
shows old axe work. No scribing found. See Statement
signed by James Combs in file, to wit:
I, James Combs, state that the remains of old Fir Stump found and
used on this date for the Orig. S.E. BT. did show good wood
scribing in 1952.
Found - Base of Orig. N.E. BT., no scribing.
Tag set by Haines on now down 30" Fir, see forest appraisal
record.

Set - Brass Cap at 1/4 Cor. Mkd: County Surveyor's R T 31 S R
Office 6 S 12/S 7 5
1966 W W

New BT's: 22" D. Fir S. 28° W. 68.2 ft. scribed 1/4 S12 CS BT.
10" Yew S. 59° E. 26.4 ft. scribed 1/4 S 7 CS BT.

Aug. 4, 1966

James W.
Byron, Co. Surv.
John Powell
& Crew
Aug., 1966
C. S. File
No. 54/25

Sec. Cor. to Secs. 6 & 7, T31-5W. & Secs. 1 & 12, T31-6W. 102
Found - 16" D. Fir, now 36", S. 4° E. 11.9 ft., Had been opened &
burned open more, but no scribing visible.
14" Fir, now down, S. 78° W. 7.9 ft., Old rotten snag has
axed face with faint OS & other marks. Scribing done
with very fine scrb. or knife.
12" Fir, now down Snag, North 6.6 ft., has old axe work. no scribe.
No trace of 8" V. Maple.
By ring count on 36" Fir it places this corner at "1878". Also,
call on small creek of 16.5 ft. north of corner, hits very good.

Set - Brass Cap at Cor. Mkd: County Surveyor's R T 31 S R
Office 6 S 1 | S 6 5
1966 W S 12 | S 7 W

New BT's: 14" Maple N. 8° E. 31.0 ft. mkd. T31S R5W S 6 CS BT.
12" Maple N. 58° W. 48.3 ft. mkd. T31S R6W S 1 CS BT.
13" Maple S. 84° W. 36.0 ft. mkd. T31S R6W S12 CS BT.
Reblaze & Rescrib: 36" D. Fir S. 4° E. 11.9 ft. mkd. T31S R5W S 7 CS BT.

Oct. 13, 1966

John M. Powell
Frank Jones & C. Stone
October, 3, 1966
C. S. File No. 54/31

FOUND - South 1/4 corner of Section 32, T31S, R5W.
ONLY - Found - Brass Cap and Iron Pipe. (1962 Gov't. Brass Cap)
18" D. Fir S. 68 1/2° E. 38 lks.
15" D. Fir N. 15° E. 26 lks.
20" D. Fir N. 57° W. 34 lks.

This corner is in good condition. No new accessories were set

North 1/4 Corner of Section 5, T32S, R5W. 103 A
Found - No trace of 1962 Cadastral Brass Cap.
10" D. Fir S. 83° W. 23 lks., knocked over by logging.
12" I. Cedar S. 15 1/2° E. 35 lks., scribing buried under logs.
Set - 1 1/2" x 40" Iron Pipe, 32 in. into the ground, from which:
Rescribed the 12" I. Cedar "1/4 S RS 749 BT. four feet above ground.

F. H. Mehl, III
For Robert Dollar Co.
June 16, 1967
C.S. File No. 55/15