

Douglas County Surveyor's Record of
Government Corners Renewed

31

T. S.

5

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

108

Sec. Cor. to Sec. 5, 6, 7, & 8
Found.-Orig. 18" now 33" corner tree with healed blazes on SE and SW faces from which-Original bearing trees are located as follows:
BT's- An orig. 12" now 19" D. Fir alive and well-healed, bears N 10°W., 2.6ft.
An orig. 10" now 21" D Fir. alive and well healed, bears N 30°E., 2.0 ft.
An orig. 14" now 26" P. Pine, alive and well-healed bears S75°E., 15.8 ft.
An orig. 30" I cedar, now a 40" stump with scribe marks visible on opened blaze, bears S 22°E., 30.4 ft.
A 2 1/2" Dia. Iron pipe firmly set with brass cap attached properly marked (A BLM 1966 brass cap) Bears S 30°E., 3.3 ft.
A madrone bt also marked in 1966 by BLM has been destroyed by road construction.
We mark two additional BT's as follows:
A 14" D Fir bears N 12 1/2°W., 52.2 ft. scribed "T31S, R5WS6 CSBT" on a double blaze.
A 16" Incense cedar bears N55°E. 45.9ft. scribed "T31S R5W S5 CSBT" on a double blaze.
This corner is located approx. 30 ft. north of a newly constructed road.
Compass declination 20°E - - - 12/16/75 - - -

ary L Langlitz
Clell E Goodwin
A Vic Cangie
M. Lenora Ladig.
CS57/39
12/16/75

109

1/4 Corner for Sec. 33. South Boundary.
(Set by single proportionment)

Set - 5/8" x 30" Iron rod, 25 inches in the ground with a yellow plastic cap mkd. "TEMPLIN RE 3024"

From which:

A Ponderosa Pine, 2", bears N. 03°E., 14.5 ft. mkd. "1/4 X".
A Chinquapin, 10", bears N. 68°E., 60.1 ft. mkd. "1/4 S33 RE3024 BT".

Note: This corner falls on the south edge of an old skid road in the middle of a large clear cut logging unit. No evidence of orig. cor. found.)

Richard L. Templin
For: Arrant Lbr. Co.
April 8, 1977
C.S. 58/93

JAN 78

110

Section corner for Secs. 5 and 4; and secs. 32 & 33 of T30-5.
Found - A 1" I.P. with attached brass cap marked "County Surveyors Office T30S R5W S32 S33 S5 S4 T31S R5W 1957". Monument is approx. 14" high and firmly set. Did not find Iron pipe. Ren. #50
Orig. 1858 BT, fragmentary remains around root hole of a Rec. 64" Madrone bearing N. 85°E., 4.0 ft. to the area of the apparent face. Ren. #7
Orig. 1858 remains of a badly decayed madrone (fd. no scribing or blaze) root hole bears S. 52°W., 19.8 ft.
A Fir 8" now a 12" stump 3 1/2 ft. high bears N. 63°E., 24.0 ft. scribed "CS BT" legible on a double blaze. Ren. #7
A Fir 10" now a 13" snag, 12 ft. high bears S. 35°W., 14.5 ft. to face 15 ft. to center, scribing "S4 T31S R5W CS BT" visible in unhealed blaze. Ren. #7
A Fir, 10" now a 13" snag, 10 ft. high, bears S. 83°E., 11.5 ft. to face 12 ft. to center (Rec. 14 ft.) scribing "T S" visible in burned out double blaze. Ren. #7
A Fir 16" now a 30 ft. high snag bears N. 89°W., 68.8 ft. (Rec. West 70.5 ft.) scribed "T30S R5W S32 CS BT" on a partially healed double blaze. #42
A 9" Madrone now dead with a new growth around old trunk bears S. 85°E., 70.2 ft. (Rec. S. 87°E.) scribed "S 4 T31S R5W CS BT" on a double blaze. #42
A 48" Cedar now a 40 ft. high snag bears S. 38°W., 100.7 ft. scribed "S5 T31S R5W CS BT" on a single blaze. #42
A Fir 16" now a 20 ft. high snag bears N. 84°W., 75.2 ft. (Rec. N. 86°W., 71.1 ft.) scribed "S32 T30S R5W CS BT" on a 3 ft. high blaze. Ren. #50
A madrone 18" now a 19" diam., 12 ft. high snag bears N. 70°E., 86.4 ft. blaze rotted out. Ren. #50
A R. Fir bearing S. 66°E., 35.7 ft. is now a tipped out snag partially rotted. #50
New BT - A Madrone 4" bears N. 67°E., 7.2 ft. bark scribed "S33 CS BT"
No other trees available at this time.

Larry E. Monrean, Doug. Co. Surveyors Office
F. C. Silagy
June 27, 1978
C.S. 60/11
Witness

6/27/78