

Douglas County Surveyor's Record of
Government Corners Renewed

31

T. S.

6

R. W. W. M.

KOYE-CHAPMAN CO., EUGENE, ORE. 97198

J. W. Cole - - - February 11 - 16, 1924.
County Surveyors Record Vol. 3, Page 181.

Section corner to secs. 22, 23, 26 and 27.
I renewed this corner from the original bearing trees.
Set a 1 inch by 40 inch drill steel for the corner and marked
new trees as follows:

- A Fir, 20 inches in diameter, S.76°30'W., 77.8 feet.
- A Fir, 40 inches in diameter, N.45°15'W., 58.0 feet.
- A Fir, 18 inches in diameter, N.59°45'W., 68.5 feet.

108

14

Section corner to secs. 23, 24, 25 and 26.
Identified from original bearing trees which I identified.
Set a rock mound for the corner and also a 1 inch by 40 inch
drill steel.

Did not mark new trees as this area had been badly burned and
no suitable trees convenient.

46

15

$\frac{1}{4}$ sec. corner to secs. 23 and 26.
Could find no evidence of original corner.
Established corner midway on true line between section corners.
Set a 1 inch by 40 inch drill steel, also a fir post properly
marked for the $\frac{1}{4}$ corner, from which

- A ledge rock bears S.64°00'W., 70.0 feet, marked $\frac{1}{4}$ s CS, BO.
- A Fir, 36 inches in dia., bears West 14 feet mkd. with two
notches on the East and West faces.

48

16

John H. Markham Jr.
Witness: Harry Deyton
March 21, 1955.
C. S. File No. 41/370.

Section corner to secs. 3 & 4 (T31S, R6W) and secs. 33 & 34 (T30S, R6W).
Determined by O. B. T.s:

- A 30 inch B. O. Snag bears N.11°W., 72.0 feet.
- A 25 inch B. O. Stump bears S80°E., 69.0 feet.
- A 25 inch B. O. Stump hole bears N.30°E., 84.5 feet.
- A 25 inch B. O. Stump bears S.32°W., 41.0 feet.

At corner point set $\frac{3}{4}$ inch X 44 inch Iron Pipe from which:

- A 14 inch La. bears N.74°E., 46.5 feet dist., mkd S 34 B. T.
- A 15 inch La. bears N.22°E., 17.0 feet dist., mkd S 34 B. T.
- A 14 inch La. bears N.35°W., 29.0 feet dist., mkd. S 33 B. T.
- A fence corner bears S.78°W., 9.2 feet dist. Fences run North -
South - East and West.

37

17

Clifford M. Brydon
Work done for Roseburg Lumber Co.
February 14, 1957.
C. S. File No. 42/250.

Section corner to secs. 28, 29, 32 and 33.
This corner destroyed by road building-all B. T.s destroyed.
Reset corner from references set when corner previously renewed by
R. H. Gee. - See REN #12

$\frac{1}{2}$ inch x 3 foot iron pipe at corner,
from which new witness trees:

- Fir, 4 inches, S.77 $\frac{1}{2}$ °E., 74.8 feet.
- Fir, 6 inches S.42 $\frac{1}{2}$ °W., 66.1 feet.
- Fir, 4 inches, N.38°E., 36.5 feet.
- Fir 4 inches, N.4°W., 76.4 feet.
- Scribed R. E. 3937 B. T.

107

18

$\frac{1}{4}$ section corner to secs. 20 and 21.
Found old B. T. - Cedar 18 inches, S.62 $\frac{1}{2}$ °W., 7.3 feet.
Set 2 inch x 4 inch x 4 foot cedar post at corner point,
from which:

- New B.T.- Fir, 18 inches, N.81°E., 79.0 feet, scribed R. E. 3937 BT.

79

19

James Byron
G. Welker
J. Fee
Oct, 1956-Jan., 1957
C.S. File #48/Rd. 93

$\frac{1}{4}$ section Corner to Secs. $\frac{33}{4}$
Found orig. N.W. BT. (Now 26" W.O.). Checks bearing dist. to scribed 4x4 inch
stake set for Cor. by R. Gee. BT opened by Gee "BT" scribing visible.
S.W. BT is gone. Set brass cap alongside post marked: $\frac{1}{4}$ Sec. $\frac{33}{4}$ T30S, R6W
County Surveyors Office, 1956 $\frac{4}{4}$ T31S, R6W.
From which: 24 inch R. Fir bears N 39°W 58.3 ft. scribed $\frac{1}{4}$ S33 T30S, R6W. CS BT
24 inch W.O. bears N 60°E 4.0 ft. scribed $\frac{1}{4}$ S 33 CS BT.

#60

20