

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 31 S. T. S. R. 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Secs. 18 & 19, T31-6W. & Secs. 13 & 24, T31-7W.  
Found -  $\frac{3}{4}$ " I. P. at Corner & all BT's. except S.E. BT.  
N.E. & S.W. BT's. show scribe. **54**

Set - Brass Cap alongside Cor. Pipe & Mkd: County Surveyor's  
Office, 1962

S 13 | S 18 T31S  
R7W S 24 | S 19 R6W

New BT's: 14" R.Fir bears S.6°E. 29.5 ft. scribed T31S R6W S19 CSBT.  
12" R.Fir bears S.46°W. 45.9 ft. scribed S24 T31S R7W CSBT.  
24" Rescribe now R.Fir 13.8 ft. N.20°W. T31S R7W S13 CS BT.

Byron & Crew  
Dec. 27,  
1962  
C.S. File  
No. 49/109

Section Corner to Secs. 36 and 35, T31-6W. & Sec. 2 & 1, T32-6W. **55**  
Found - Orig. 14", now 30" Fir N.30°W. 38.9 ft., shows scribe marks  
on partly rotted face.

Orig. 6", now down 12" Fir S.53°E. 33.0 ft., shows scar.  
No other Orig. BT's. found.

Set -  $\frac{3}{4}$ " Iron Rod at Corner

New BT's: 12" Hemlock bears N.80°W. 50.0 ft. scribed S35 T31S R6W CS BT.  
12" Hemlock bears S.12°E. 3.5 ft. scribed S1 T32S R6W CS BT.  
9" Cedar bears East 43.1 ft. scribed S36 T31S R6W CS BT.

James W. Byron, Deputy  
For C. & D. Lumber Co.  
April 2, 1963  
C. S. File No. 53/12  
Map File M 25 - 10

$\frac{3}{4}$  Corner to Sections 35 and 36. **56**

Set - Brass Cap at  $\frac{1}{4}$  Cor. Mkd: County Surveyor's Office, 1963

$\frac{1}{4}$  S 35/S 36 T31S R6W

New BT's: 15" R.Fir bears N.23°E. 28.5 ft. scribed  $\frac{1}{4}$  S36 CS BT.  
5" Cedar bears S.83°E. 40.3 ft. scribed  $\frac{1}{4}$  S36 CS BT.  
6" Fir bears N. W. 24.9 ft. scribed  $\frac{1}{4}$  S35 CS BT.

Section Corner to Sections 14 - 15 - 22 - 23. **57**

Found - All 4 Orig. BT's: Orig. 36", now rotted base of Large Fir,  
S.50°W. 5.3 feet.

Orig. 7", now 12" Laurel Snag S.60°E. 48.2 ft., shows scribing.

Orig. 26", now 40" Fir N.60°W. 26.4 ft., shows good bark scrbing.

Orig. 30", now 40" Fir N.21°E. 16.5 ft.

Set - Brass Cap alongside found scribed Cor. Stake & Mkd:

County Surveyor's S15 | S14 T31S R6W  
Office, 1963 S22 | S23

New BT's: 15" R.Fir bears S.68°E. 12.7 ft. scribed S23 T31S R6W CS BT.  
6" R.Fir bears N. 2°E. 19.4 ft. scribed S14 CS BT.  
18" R.Fir bears S.20°W. 6.0 ft. scribed T31S R6W CS BT.

James W. Byron  
Mike Darby & Wm. Stoffel  
March 19, 1963  
C. S. File No. 52/25

Section Corner to Sections 5 - 6 - 7 - 8. **58**

Found - Orig. 8", now 10" Rotted Laurel Snag N.50°E. 19.1 ft.

Orig. 26", now 40" Fir S.36°E. 24.4 ft., shows scribing.

Orig. 20", now 25" Laurel N.16°W. 24.4 ft., shows scribing.

Stump Hole that checks for S.W. Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's S 6 | S 5 T31S R6W  
S 7 | S 8

New BT's: Rescribe, now 25" Laurel N.16°W. 25.2 ft. S6 CS BT.  
8" R.Fir bears N.54°E. 43.5 ft. scribed S5 CS BT.  
10" R.Fir bears S.14°W. 52.0 ft. scribed S7 T31S R6W CS BT.  
Sept. 16, 1963

E. S.  
File  
No.  
52/25

Township Corner S36 | S31 T30S  
R6W S 1 | S 6 R5W T31S **59**

Found -  $\frac{3}{4}$ " I.P. at Corner & all BT's. as recorded, See Ren.# 2.  
Bearing Trees to north now stumps.

Note- Small Stream is 25 ft. west of corner.

New BT's: 14" Maple bears North 37.6 ft. scribed S36 T30S R6W CS BT.  
6" R. Fir bears N.70°E. 30.9 ft. scribed S31 CS BT.

James W.  
Byron &  
Crew  
Oct. 28,  
1963  
C.S. File  
No. 53/26

RE-RENEWED, SEE CORNER NO. #139