

Douglas County Surveyor's Record of
Government Corners Renewed

31 T. S. 6 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

68

$\frac{1}{4}$ Corner to Section 8 & 17.

Found - Madrone (now 21" diam.) N. 18° E 11.2 ft. Previously opened-good scribing visible " $\frac{1}{4}$ S"

Portion of rotten Laurel on ground in general location of South BT. - impossible to determine where it stood.

Set - Brass Cap Mkd: "County Surveyor's Office 1964 T 31 SR 6 W
 $\frac{1}{4}$ S 8
S 17

New BT's: 8" Doug. Fir S 74° E 9.0 ft. Mkd: " $\frac{1}{4}$ S 17 CS BT"
8" Doug. Fir N. 83° W 7.0 ft. Mkd: " $\frac{1}{4}$ S 8 CS BT"

Hilo Godfrey, Deputy
Mike Stone
June, 1964
C. S. File No. 52/25

69

Section Corner to Sections 8, 9, 16 & 17.

Found - Doug. Fir (now 39" diam.) N. 72° E 20.5 ft. Some bark scribing visible on old bark blaze - a "T" & part of an "S"

No trace of any other BT's.

Locations for trees are in old car road & bulldozer areas.

Set - Brass cap mkd: "County Surveyor's Office 1964 T 31 SR 6 W.
S 8 | S 9"
S 17 | S 16

Blaze & Rescribe (in wood)

39" Doug. Fir N. 72° E 20.5 ft. Mkd: "T 31 SR 6 W S 9 CS BT".

New BT's: 30" Doug. Fir S 69° W. 60.6 ft. Mkd: "T 31 SR 6 W S 17 CS BT"

10" Madrone S 43 $\frac{1}{2}$ ° E 48.8 ft. Mkd: "S 16 CS BT"

20" Incense Cedar N. 16° W 56.4 ft. Mkd: "T 31 SR 6 W S 8 CS BT"

Corner lies on fairly steep S.W. slope, near bottom of small draw running S.E.

FD O.K. 4/3/00
BRUCE A. SHAMER
LCH 430 RM 3-22

70

$\frac{1}{4}$ Corner to Sections 22 and 27.

Found - Both Orig. BT's: 18" Fir S. 5° W. 18.5 ft., scribe in open blaze.
10", now 30" Fir N. 70° W. 35.0 ft., shows scar, not opened.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 31 S R 6 W $\frac{1}{4}$ S 22
Office, 1964 S 27

New BT's: 15" D. Fir S. 26° W. 16.4 ft. Mkd: " $\frac{1}{4}$ S 27 CS BT.

12" D. Fir North 19.5 ft. Mkd: " $\frac{1}{4}$ S 22 CS BT.

Note - This corner lies on southerly slope approx. 150 ft. above creek.

Vernon "Ray" Tracy
Mike Darby and Jack Barnett
September 1964
C. S. File No. 52/25

71

Section Corner to Secs. 21 - 22 - 27 - 28.

Found - 16" Cedar N. 44° W. 31.7 ft., now 30", chopped out & face rotted, alive.

15" Fir S. 45° E. 8.6 ft., rotted stump, shows "27W" bark scribe.

N.E. & S.W. BT's. are down, burned & rotting. No scribe found.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 31 S R 6 W S 21 | S 22
Office, 1964 S 28 | S 27

New BT's: 8" W. Fir S. 56° E. 32.7 ft. Mkd: T 31 S R 6 W S 27 CS BT.

12" W. Fir N. 75° E. 40.5 ft. Mkd: T 31 S R 6 W S 22 CS BT.

14" D. Fir S. 72° W. 17.2 ft. Mkd: T 31 S R 6 W S 28 CS BT.

8" W. Fir N. 15° W. 30.0 ft. Mkd: T 31 S R 6 W S 21 CS BT.

Fd B.C. 4-8-87
BLM Admin
Survey 1977
SEE GIS FILE

72

$\frac{1}{4}$ Corner to Sections 21 and 28.

Found - $\frac{3}{4}$ " I. Pipe & Both Orig. BT's;

28" Cedar, now 39" N. 20° W. 15.8 ft., shows " $\frac{1}{4}$ S", bark scribe.

8" W. Fir, now 24" S. 22° W. 22.4 ft., opened & shows "4S" scribe.

Set - Brass Cap with other Pipe alongside at Cor. Mkd: County Surveyor's
Office, 1964 T 31 S R 6 W $\frac{1}{4}$ S 21
S 28

New BT's: 9" D. Fir S. 7° W. 35.9 ft. Mkd: " $\frac{1}{4}$ S 28 CS BT.

12" D. Fir N. 59° W. 27.5 ft. Mkd: " $\frac{1}{4}$ S 21 CS BT.

73

Witness Corner to $\frac{1}{4}$ Corner to Secs. 21 and 28.

See Renewal above, #72. We measure 150.0 ft. West on line &

Set - same Brass Cap, now mkd: County Surveyor's T 31 S R 6 W W.C. $\frac{1}{4}$ S 21
Office, 1964 S 28

New BT's: 15" D. Fir N. 49° E. 27.4 ft. Mkd: W.C. $\frac{1}{4}$ S 21 CS BT.

11" D. Fir S. 32° E. 9.4 ft. Mkd: W.C. $\frac{1}{4}$ S 28 CS BT.

Oct. 12, 1964

Fd B.C. 4-2-87
BLM Admin. Survey
SEE GIS FILE