

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 31 S. T. S. R. 6 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 97101

89

Sec. Cor. to Secs. 1 & 12, T31-6W. & Secs. 6 & 7, T31-5W.  
Found - 16", now 36" D.Fir, S. 4° E. 11.9 ft., Tree had been opened  
& burned open more, but no scribing visible.  
14" Fir, now down, S. 78° W. 7.9 ft., Old, rotten snag has  
axed face with faint "S" & other marks. Scribing done with  
very fine scribe or knife.  
12", now down Snag (Fir), North 6.6 ft., has old axe work, but  
no scribing visible.  
No trace of 8" V. Maple.  
By ring count on 36" Fir, it places this corner at Resurvey,  
1878". Also, call on small creek at 16.5 ft. north of corner  
hits very good.

Set-Brass Cap at Cor. Mkd: County Surveyors  
Office 1966

R	T 31 S	R
6 S	1	S 6 5
W. S	12	S 7 W

New BT's: 14" Maple N. 8° E. 31.0 ft. mkd. T31S R5W S6 CS BT.  
12" Maple N. 58° W. 48.3 ft. mkd. T31S R6W S 1 CS BT.  
13" Maple S. 84° W. 36.0 ft. mkd. T31S R6W S12 CS BT.  
Reblazed & Rescribed: 36" D.Fir S. 4° E. 11.9 ft. mkd. T31S R5W S7 CS BT.

RE-RENEWED, SEE CORNER NO. #138

90

Sec. Cor. to Sections 29 - 30 - 31 - 32.  
Found - 3/4" Iron Pipe, See Ren. #27.  
Orig. 15", now 34" D.Fir N. 66° E. 8.6 ft., bark scribed.  
Orig. 22" D.Fir, now Snag, S. 6° W. 10.6 ft., bark scribed.  
30" D. Fir, down & rotten, N. 53° W. 76.6 ft.  
14" D. Fir Stump Hole S. 70° E. 16.5 ft.

Set - Brass Cap alongside I.P. Mkd: County Surveyors  
Office 1966

T 31 S	R 6 W
S 30	S 29
S 31	S 32

New BT's: 44" D. Fir S. 27° E. 42.5 ft. mkd. T31S R6W S32 CS BT.  
42" D. Fir S. 60° W. 23.9 ft. mkd. T31S R6W S31 CS BT.  
30" D. Fir North 15.0 ft. mks. T31S R6W S30 CS BT.

John M. Powell  
Frank Jones & Cliff Stone  
Sept. and Oct., 1966  
C. S. File No. 54/31

91

1/4 Corner to Sections 30 and 29.  
Found - Orig. 6" Laurel N. 40° W. \_\_\_ lks. Had been opened "1/4" visible.  
No trace of other 6" Laurel.  
10", now 12" D.Fir N. 77 1/2° E. 31.4 ft., shows good scar.  
30" I. Cedar S. 64° W. 28.5 ft. mkd. 1/4 S30 BT. See Ren. #31

Set - Brass Cap at 1/4 cor. mkd. County Surveyors  
Office, 1966

T31 S	R 6 W
1/4 S	30/S 39

Bearing Trees are in good condition. No New trees mkd.  
Note - This corner is at base of 12" Laurel on South Side.

92

1/4 Corner to Sections 29 and 32.  
Found - 3/4" Iron Pipe, See Ren. #26.  
Orig. 12" Laurel, now dead, N. 60 1/4° E. 15.2 ft.  
Orig. 12" Laurel, now 24", S. 25° E. 14.5 ft., Opened for scribe.  
New BT's: 17" D.Fir, now 18", N. 56° W. 6.5 ft., shows good scar.  
32" Cedar, S. 72° E. 19.0 ft., scribe visible "1/4 SBT".

Set-Brass Cap alongside I.P. & Mkd: County Surveyors  
Office 1966

T 31 S	R 6 W
1/4 S	29 = (26) or 28
S	32

New Bearing Trees all in good condition. No new trees marked.

RE-RENEWED, SEE CORNER NO. #153

93

1/4 Corner to Sections 24 and 25.  
Found - Iron Rod at 1/4 Corner, See Ren. #63.  
8" Hemlock, N. 36° W. 65.1 ft. mkd. scribe visible, 1/4 S24 BT.  
36" D.Fir, now stump, S. 70° W. 66.5 ft., scribe visible.

Set - Brass Cap at 1/4 Cor. Mkd: County Surveyors  
Office 1966

T 31 S	R 6 W
S 24	S 25

New BT's: 7" W. Fir N. 82° E. 34.9 ft. mkd. 1/4 S24 CS BT.  
No trees available in Section 25.

Note - This corner lies on steep, north slope, about 200.0 ft. south  
of creek. Location tag on stump north side of logging road  
about 300.0 ft. north of 1/4 corner.

RE-RENEWED, SEE CORNER NO. #163