

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97881

99

$\frac{1}{4}$ Corner to Sections 14 and 23.
Found - 36", now 50" D. Fir N. 23° W. 15.2 ft., faint bark scribe visible "BT". (dist. to approx. face of tree) This tree will be cut.
28" Hemlock, now rotten stump, S. 16° E. 13.9 ft.
Set - Brass Cap at Cor. Mkd: County Surveyors T 31 S R 6 W
Office S 14
1966 S 23
New BT's: 14" D. Fir N. 72 $\frac{1}{2}$ ° W. 33.1 ft. mkd. $\frac{1}{4}$ S14 CS BT.
17" Yew S. 31 $\frac{1}{2}$ ° E. 31.0 ft. mkd. $\frac{1}{4}$ S23 CS BT.
Note - This corner lies 53.0 ft. west of small creek.

100

$\frac{1}{4}$ Corner to Sections 10 and 11.
Found - Orig. 27", now 38" Cedar, N.50° E. 11.9 ft., burnt out, no scribe visible
Orig. 5", now D. Fir Snag, N. 60° W. 15.2 ft., opened for scribing "BT".
Set - Brass Cap at Cor. Mkd: County Surveyors T 31 S R 6 W
Office, 1966 $\frac{1}{4}$ S10/S11
New BT's: 20" D. Fir N. 19° W. 24.0 ft. mkd. $\frac{1}{4}$ S10 CS BT.
Reblazed & Rescribed: 38" Cedar N.50°E. 11.9 ft. mkd. $\frac{1}{4}$ S11 CS BT.

101

Sec. Cor. to Sections 2 - 3 - 10 - 11.
Found - 1" Iron pipe, not recorded.
Pine Snag N. 28° W. 41.0 ft. See Ren. #5.
Orig. 27", now 30" Laurel S.80° E. 46.5 ft. Tree open, scribe visible, rotten face.
Orig. 16", now 20" Laurel, N. 60° E. 42.5 ft. Tree had been opened, no orig. scribe visible. Rescribe "BT" visible.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 31 S R 6 W
Office S 3 | S 2
1966 S 10 | S 11
New BT's: 16" D. Fir S. 5° E. 17.6 ft. mkd. T31S R6W S11 CS BT.
7@ D. Fir N. 54° E. 13.5 ft. mkd. T31S R6W S 2 CS BT.
9" D. Fir N. 34° W. 26.6 ft. mkd. T31S R6W S3 CS BT.
7" D. Fir S. 45° W. 23.0 ft. mkd. T31S R6W S10 CS BT.

102

Sec. d Cor. to Sections 20-21=28-29.
Found - 3/4" Iron Pipe at sec. cor., See Ren. #10.
Orig. 36" Pine, now 36", N. 40° W. 65.3 ft., shows good pitched over scar.
Orig. 48" D. Fir, now 38", S. 80° E. 55.4 ft. bark scribed.
Orig. 38" I. Cedar, now 48@, S. 74° W. 34.3 ft., bark scribed.
8@ Fir, now 9", N. 40° E. 11.8 ft., shows good scar.
Set - Brass Cap at Cor. Mkd: County Surveyors T 31 S R 6 W
Office S 20 | S 21
1966 S 29 | S 28
New BT's: 10" D. Fir South 22.1 ft. mkd. T31S R6W S28 CS BT.
Reblzd. & Rescrbd: 48" I. Cedar S. 74° W. 34.3 ft. mkd. T31S R6W S28 CS BT.

103

$\frac{1}{4}$ Corner to Sections 29 and 28.
Found - 3/4" Iron Pipe at $\frac{1}{4}$ Corner. See Ren. #11.
Orig. 18", now stump, East 5.2 ft.
12" I. Cedar, now 14" S. 60 $\frac{1}{2}$ ° W. 8.8 ft., scribe visible.
Set - Brass Cap at Cor. Mkd: County Surveyors T 31 S R 6 W
Office, 1966 S 29/S 28
New BT: 13" I. Cedar N. 87° E. 28.2 ft. mkd. $\frac{1}{4}$ S28 CS BT.

104

$\frac{1}{4}$ Corner to Sections 32 and 33.
Found - 22" D. Fir, now 40", N. 70° E. 15.2 ft., bark scribe, faint "BT".
40@ D. Fir, now 47", S. 41° E. 15.2 ft., bark scribe, faint "S".
Set - Brass Cap at Cor. Mkd: County Surveyors T 31 S R 6 W
Office, 1966 $\frac{1}{4}$ S 32/S 33
New BT's: 40" Cedar S. 73° W. 30.8 ft. mkd. $\frac{1}{4}$ S 32 CS BT.
16" Laurel S. 32° E. 6.7 ft. mkd. $\frac{1}{4}$ S33 CS BT.

John M. Powell
Frank Jones
Cliff Stone
October, 1966

Fd B.C. # 4 BTs
BLM ADMIN. 1977
SURVEY
SEE
GIS FILES

C. S. File No. 54/31

Fd BC # 2 BTs
1977 BLM ADMIN.
SURVEY - SEE
GIS FILES