

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 31 S. T. S. R. 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

116

$\frac{1}{4}$  Corner to Sections 3 and 10.  
Found - 10" Yew, now 10", N.  $55\frac{1}{2}^\circ$  E. 36.5 ft., scribe visible. (Ren. #33)  
No trace of S. E. Bearing Tree.  
Set - Brass Cap at Cor. Mkd: County Surveyors Office, 1966 

T31S	R6W
$\frac{1}{4}$ S 3	S 10

 Fa. O.K. by:  
G. GRUBB  
APRIL 1982  
M 91-75  
New BT: 16" D. Fir N.  $82^\circ$  E. 65.0 ft. mkd.  $\frac{1}{4}$  S 3 CS BT.  
No trees near in Section 10.  
Note - This corner lies on edge of old skid road. Also  $40^\circ$  W. of draw, N-S.

117

$\frac{1}{4}$  Corner to Sections 6 and 7.  
Found  $\emptyset$  Orig. 14", now 21" Laurel, N.  $51^\circ$  W. 19.8 ft. Tree had been partially opened, scribing found "BT".  
No BT. at S.  $40^\circ$  W. 17.8 ft.  
Set - Brass Cap at Cor. Mkd: County Surveyors Office, 1966 

T31S	R6W
$\frac{1}{4}$ S 6	S 7

  
New BT's: 17" D. Fir S.  $27\frac{1}{2}^\circ$  W. 12.0 ft. mkd.  $\frac{1}{4}$  S 7 CS BT.  
17" D. Fir N.  $71^\circ$  E. 4.4 ft. mkd.  $\frac{1}{4}$  S 6 CS BT.  
Note - This corner lies in deep draw on top of small spur running N-S. Also about 150.0 ft. East to draw & 200 ft. west to draw.

118

$\frac{1}{4}$  Corner to Sections 7 and 18.  
Found - Orig. 6", now 24" D. Fir Corner Tree, opened & shows "S".  
Ring Count shows it to be original.  
No trace of original BT's.  
Set - Brass Cap on N. side of Corner Tree Mkd: County Surveyors Office, 1966 

T31S	R6W
S 7	S 18

  
New BT's: 22" D. Fir S.  $30^\circ$  W. 19.5 ft. mkd.  $\frac{1}{4}$  S 18 CS BT.  
18" D. Fir N.  $53\frac{1}{2}^\circ$  E. 46.0 ft. mkd.  $\frac{1}{4}$  S 7 CS BT.

119

$\frac{1}{4}$  Sec. Cor. to Sections 19 and 30.  
Found - 3 x 3 Post, See Ren. #40.  
7", now 8" D. Fir, N.  $10^\circ$  E. 8.3, shows scribing " $\frac{1}{4}$ S".  
7", now 8" D. Fir S.  $48^\circ$  E. 28.5 ft., shows scribing " $\frac{1}{4}$ S BT".  
Set - Brass Cap at Cor. Mkd: County Surveyors Office, 1966 

T31S	R6W
$\frac{1}{4}$ S 19	S 30

  
Note - This corner lies on top of spur, approx. 600 ft. East of a logging road.

120

$\frac{1}{4}$  Cor. to Sections 19 and 20.  
Found - 3 x 3 Post, See Ren. #39.  
Orig. 10", now 20" D. Fir S.  $70^\circ$  W. 22.4 ft., shows scribing "S".  
8", now 10" D. Fir S.  $47^\circ$  E. 14.6 ft., shows scribing " $\frac{1}{4}$ S".  
Set - Brass Cap at Cor. Mkd: County Surveyors Office, 1966 

T31S	R6W
$\frac{1}{4}$ S 19	S 20

  
Note - This corner lies approx. 170 ft. East of a logging road.

121

$\frac{1}{4}$  Corner to Sec. 33, T31-6W. & Sec. 4, T32-6W.  
Found - 12" Fir, now down & rotten, S.  $55^\circ$  W. 3.3 ft. Found old reverse, scribe marks.  
8" Fir, now 11", N.  $60^\circ$  E. 31.0 ft., shows very good face.  
Set - Brass Cap at Cor. Mkd: County Surveyors Office, 1966 

T31S	R6W
S 33	S 4

 T32S  
New BT: 26" D. Fir S.  $88^\circ$  W. 49.4 ft. mkd.  $\frac{1}{4}$  S 4 CS BT.  
PK Nail in Rock, West 3.6 ft.  
Note - This corner lies on very steep, north slope, 2.5 ft. west of Rocky point about 12.0 ft. high.

FD. OK 2/85  
O. FREDERIK  
M 90-47  
C.S. 13/11

John M. Powell  
Frank Jones and C. Stone  
E. West  
October, 1966  
C. S. File No. 54/31

881