

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 6 W. R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 97401

122

Sec. Cor. to Secs. 32 & 33, T31-6W. & Secs. 5 and 4, T32-6W.
Found - Orig. 5", now 9" Laurel, N. 42° E. 21.1 ft., shows old scar.
Orig. 18", now 47" Fir, S. 34° E. 21.7 ft., Tree has been
opened but badly burned.
24", now 24" D. Fir, N. 6° W. 35.0 ft., pitched over
scribing visible (REN. No. 25)
14", now 14" D. Fir, N. 54° E. 87.3 ft., pitched over,
scribing visible.
16", now 16" D. Fir, S. 63° E. 38.0 ft., pitched over, sc. vis.
Mound of Stone at Section Corner.

Set - Brass Cap at Cor. Mkd: County Surveyors Office
1966

T31S	R6W
S 32	S 33
S 5	S 4

All Bearing Trees in good condition. T32S R6W

123

1/4 Corner to Sec. 36, T31-6W. & Sec. 1, T32-6W.
Found - Squared Stake at 1/4 Corner. See Ren. #22.
8" Live Oak N. 5° W. 31.1 ft., scribe visible "1/4 S CS BT".
12" Live Oak N. 64° W. 17.3 ft. scribe visible, "1/4 S CS BT".

Set - Brass Cap at Cor. Mkd. County Surveyors Office
1966

T31S	R6W
S 36	
S 1	

Bearing Trees all O.K. T32S R6W

Note - As noted, corner lies E. of ridge, top about 297.0 ft.
Also, west of new Road about 150.0 ft.

124

1/4 Corner to Sec. 32, T31-6W. & Sec. 5, T32-6W.
Found - 16", now 21" Fir, N. 11° E. 27.7 ft. Tree had been opened,
scribe visible "B". Broken Top.

5", not 7" Fir, S. 42° W. 23.1 ft., scribe visible "1/4 S".
Set - Brass Cap at Cor. Mkd: County Surveyors Office
1966

T31S	R6W
S 32	
S 5	

New BT's: 22" D. Fir N. 19° E. 38.0 ft. mkd. 1/4 S32 CS BT.
17" D. Fir S. 27° W. 41.3 ft. mkd. 1/4 S 5 CS BT.

125

1/4 Corner to Sections 3 and 2.
Found - 3/4" Iron Pipe at 1/4 Corner, See Ren. #6.
26", now 36" Laurel, S. 68° W. 53.0 ft., faint bark scribe.
Orig. 20", now 26" Laurel, N. 67° E. 33.0 ft., no scribe found.

New BT's: 7" D. Fir S. 68° E. 10.2 ft. mkd. 1/4 S 2 CS BT.
10" D. Fir S. 38° W. 29.2 ft. mkd. 1/4 S 3 CS BT.

Note - This corner lies south of ridge approx. 200.0 ft.
Iron Pipe is 12" S.W. of squared -up 16" D. Fir.

FR. O.K. by
G. G. KUBS
APRIL 1982
M 91-75
Sept. 1, 1967

MICROFILM TO HERE 10/67

126

Township Corner

R	T 31 S	R
7	S 36 S 31	6
W	S 1 S 6	W
	T 32 S	

Set - 5/8" x 30" Rod & Alum. Cap by Double Proportionate Distance.
Scribed: 16" D.F. S. 28° W. 42.3 ft.
8" D.F. S. 43° E. 44.6 ft.
9" D.F. N. 57° W. 10.2 ft.
9" D.F. N. 72° E. 56.2 ft.

RE-RENEWED CORNER NO. #159

127

1/4 Corner to Sections 31 and 30.
Found - Original Bearing Trees
Set = 1" x 24" Iron Pipe.

128

1/4 Corner to Sec. 31, T31-6W and Sec. 6, T32-6W.
Set - 1 1/4" I. Pipe in Rock Mound by proportionate measurement.
Scribed: 18" I. C. S. 65° W. 22.3 ft.
14" D. F. N. 43° W. 9.9 ft.

John M. Powell
Frank Jones & C. Stone
November, 1966
C. S. File No. 54/31

Howard W. Johnstone
For Roseburg Lumber Co.
February, 1969
Map File M 33 - 49