

Douglas County Surveyor's Record of
Government Corners Renewed

T 31 T. S. R 6 R. W. W. M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21891

141

C O N T - - - - -

relied on a double proportionate measurement position for the township corner located approx. one-half mile east of the location. Additional investigation at the township corner led to the discovery of the original corner. This causes our earlier position for the 1/4 corner to be wrong and also causes the blazes on some of the newly marked bearing trees not to face the correct corner location. The directions of the blazes will be noted with the descriptions of the new BTs:

- A 16" D. Fir, scribed "1/4 S1 CS BT" on a double blaze which faces N.35°E., bears West 26.1 ft.
- A 10" Madrone, scribed "1/4 S36 CS BT" on a double blaze which faces the corner correctly bears N.66 1/2°W., 45.3 ft.
- A 12" D. Fir, scribed "1/4 S36 CS BT" on a double blaze which faces S.65°W., bears N.40°E., 32.0 ft.
- An 18" D. Fir, scribed "1/4 S1 CS BT" on a double blaze which faces N.20°W., bears S.8°E., 34.6 ft.

We return to the corner position of Cain and Wenderoth and find the following:

- A 12" Fir, now a 22" stump established as a corner tree by Cain in 1919 with a 3/4" I.P. set along the west side of Cain's corner tree by Wenderoth in 1946. No marks were found on Cain's corner tree.
- A 16" B. Oak, now a 17" snag with faint illegible scribing visible on unhealed upper blaze, bears S.7°E., 52.1 ft. (Rec. S.5 1/4° E. 52.1 ft.) Ren. #8 in T.30-6
- A 22" B. Oak, now a 24" stump, no marks found, bears N.72 1/4°E., 18.5 ft. (Ren. #8 in T.30-6)
- A 14" D. Fir, now an 18" stump with healed double blaze bears N.33°17'W., 11.2 ft. Ren. #1
- A 10" now 18" I. Cedar, with well healed double blaze bears S.43°04'W., 26.6 ft. (Rec. S.43°04'W., 25.9 ft.)
- A bearing tree marked by Byron in 1963, Ren. #61 a 12" now 17" D. Fir with healed double blaze bears N.28°W., 17.9 ft.

Note: We completely destroy all markings on the bearing trees associated with the corner position of Cain and Wenderoth. Wenderoth's 3/4" I.P. is left in place alongside Cain's corner tree which is also located at the corner of fences running north and east.

6/13/79

142

1/4 Corner for Sections 33 and 34

- Set: 5/8" Iron Rod with Alum. Cap
- BT's: A 22" Hemlock bears S.56°E., 7.6 ft. scribed "1/4 S34 BT"
- A 10" Hemlock bears N.44°W. 27.4 ft. scribed "1/4 S33 BT"

Section Corner for Sections 33 and 34, also Sections 3 and 4 T.32 S. R. 6 W.

- Set: Brass Cap stamped: $\begin{matrix} 5.83 & 5.34 & 2 \\ 5.4 & 5.3 & W \\ 7.325 & & \end{matrix}$ 1980 ALS 1005
- BT's: A 16" Fir bears S.26°E., 4.7 ft. and scribed "S3 T32 R6W".
- A 12" Fir bears N.54°E., 8.7 ft. and scribed "S34 T31 R6W".
- A 14" Fir bears N.68°W., 8.1 ft. and scribed "S33 T31 R6W".
- A 12" Fir bears S.42°W., 14.9 ft. and scribed "S4 T32 R6W".

143

1/4 Corner for sections 27 and 34

- Set: A 5/8" Iron Rod with Alum. cap
- BT's: An 8" Fir bears S.20°E., 25.10 ft., scribed "1/4 S34 BT".
- An 20" Douglas Fir bears N.48°E., 41.7 ft., scribed "1/4 S27 BT".

144

1/4 Corner for Sections 34 and Section 3, T.32S. R.6W.

- Set: A 5/8" Iron Rod with Alum. cap
- BT's: A 12" Douglas Fir bears N.22°E., 8.0 ft., scribed "1/4 S34 BT".
- A 10" Douglas Fir bears S.62°E., 19.7 ft., scribed "1/4 S3 BT".

145

Douglas County Surveyors Office
Gary Langlitz
Ed. Monrean; Karen Reed; S. Flauser; F. Silagy
June 1979
RM 3 - 26 C.S. 61/3

Ronald A. Quimby LS#1654
For: Roseburg Lumber Co.
March 1980
M 79 - 25

RE-RENEWED, SEE CORNER NO. #154