

Douglas County Surveyor's Record of
Government Corners Renewed

T 31 S T. S. R 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

By Howard W.
Johnstone
For Roseburg
Lumber Co.
May 1962
C.S. File
No. 51/163

1/4 Corner to Secs. 25, T31-7W. & Sec. 30, T31-6N
Found - Orig. Bearing Trees in good condition.
Set - 1" by 30" Iron pipe. **RE-RENEWED CORNER NO. #98** 18

1/4 Corner between Sections 22 and 27.
Found - 50" Fir N.54°E. 20.5 ft. (now 60" Snag, bark scribed) 19
16" Fir S.16°W. 15.8 ft. 15.8 ft. (now 38")
Set - 1" by 30" Iron Pipe.
Scribed - 12" D.Fir S.63 1/2°W. 28.2 ft.
19" D.Fir N.22 1/2°W. 63.0 ft.

Section Corner to Sections 7 - 8 - 17 - 18 20
Found - 4 BT's., scribe or rescribed by Geo. Wenderoth in 1961.
Bearing Trees do not fit Orig. Gov't field notes.
1" Iron Pipe set for Corner. **THIS CORNER RENEWED BY WENDEROTH - SEE C.S. FILE #52/29 FOUND BY LECKLIDER**
20" Fir N.55°E. 12.0 ft.
30" Fir S.44°E. 12.4 ft.
34" Fir N.48°W. 25.0 ft.
34" Fir S.82°W. 29.2 ft.

1/4 Corner to Sections 7 and 18. 21
Found - No evidence of Original Corner.
Set - 1" Iron Pipe for Corner by Prop. meas. **RE-RENEWED CORNER NO. #106**
28" Fir N. 69°E. 14.2 ft. mkd: 1/4 S17 RE 4079 BT
42" Fir S.43°W. 14.2 ft. mkd: 1/4 S18 RE 4079 BT.

1/4 Corner to Sections 17 and 18. 22
Found - No evidence of Orig. Gov't Corner. Controlled dep. by straight
line between sec. cors. Controlled lat. by call on R.R. 8.5 ch.
North of Corner.
Set - 1" Pipe with cap for Corner.
16" Fir S.32°E. 19.5 ft. mkd: 1/4 S17 RE 4079 BT.
22" Fir S. 1°W. 36.0 ft. mkd: 1/4 S18 RE 4079 BT.

Section Corner to Sections 17 - 18 - 19 - 20. 23
Found - 3 bark scribed BT's. BT's. did not fit Orig. Gov't field
notes so I set a Post at intersection of faces.
36" Fir S.26°W. 5.0 ft. (Rescribed)
14" Fir S.75°E. 5.7 ft. "
28" Fir N.65°E. 26.8 ft. "
Set - 10" Fir N.10°E. 14.0 ft.. **RE-RENEWED CORNER NO. 90**

1/4 Corner for Sections 27 and 34. 24
Found - 14" Pine S.70°W. 13.9 ft. (down). 26" Pine N.5°W. 45.5 ft. (Snag).
Set - 1" x 30" Iron Pipe
Scribed - 5" D.Fir N.43 1/2°W. 8.5 ft. & 32" Pine S.87°E. 54.6 ft.

1/4 Corner for Sections 27 and 26. 25
Found - 14" Pine S.18°E. 40.9 ft. (Snag) & 26" Pine S.12°W. 18.5 ft. (Stump Hole)
Set - 1" x 30" Iron Pipe. **RE-RENEWED CORNER NO. #128**
Scribed - 24" D.Fir N.2 1/2°W. 21.0 ft. - 6" Pine S.42°E. 5.6 ft.

Section Corner to Sections 22 - 23 - 26 - 27. 26
Found - 8" Fir N.36°E. 13.9 ft. (Dead) 12" Fir S.48°E. 16.5 ft. (Down)
12" Fir S.14°W. 19.1 ft. (Down) 10" Fir N.68°W. 21.8 ft. (Good)
Scribed - 12" D.Fir N.5 1/2°E. 11.3 ft.
18" D.Fir S.14°W. 25.5 ft. 11" D.Fir S.9°E. 50.0 ft.

Section Corner for Sections 13 - 14 - 23 - 24. 27
Found - 18" Fir N.20°W. 26.4 ft. (now 36", bark scribe visible)
14" Fir N.30°E. 25.7 ft. (now a windfall)
Set - 3/4" x 30" I. Pipe & Scribed - 28" D.Fir S.78°E. 16.2 ft.
14" D.Fir S.26 1/2°W. 68.0 ft. 36" D.Fir N.20°W. 26.4 ft. (O.B.T. rescribed)

G. Robert Lecklider
For C. & D. Lumber Co.
June 1962
Map File M 23 - 68

Howard W. Johnstone
For Roseburg Lumber Co.
August & September 1962
C. S. File No. 51/163