

Douglas County Surveyor's Record of
Government Corners Renewed

T 31 T.S. R 7 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

Howard Johnstone
L.S. #498
For: Roseburg Lbr.
Company
Sept. 1984
M 97- 50

Section corner for Secs. 32 and 33 only of T.30-7.
Found - Mound of stones but no brass cap and iron pipe. Ren. #54
30" pine, N.59°W., 75.2 ft. snag
6" oak, N.87°E., 130.0 ft. rotted
10" oak, N.25°E., 128.6 ft. good.
Set - 5/8" x 18" iron rod and alum. cap in stone mound. Cap mkd. "LS 498"

119

North 1/4 corner for Section 5 only.
Found - 1918 GLO brass cap and iron pipe. Ren. #53
26" oak, S.66°W., 26.4 ft. face scar.
14" oak, S.5°W., 26.2 ft. broken stump.
10" oak, S.38°E., 5.9 ft. down.
16" fir, S.24°E., 20.6 ft. down.
No good trees to the south.
New BT - 8" fir, N.38°E., 14.7 ft.

120

Section corner for Secs. 3 and 4; and Sec. 33 & 34 of T.30-7.
Found - 1918 GLO brass cap.
10" myrtle, N.10 1/2°W., 12.9 ft. face rotten.
12" madrone, N.41°E., 46.9 ft. face open
18" fir, S.70°E., 32.1 ft. snag
14" fir, S.86°W., 24.7 ft. down Ren. #63
8" oak, S.71°W., 42.8 ft.
New BT - 7" fir, S.57°E., 14.6 ft.

121

Center 1/4 Corner for Section 3
Set - 5/8" x 36" iron rod and alum. cap mkd. "LS 498".
BTs - 18" fir, S.74°W., 23.1 ft.
21" fir, S.58°E., 11.0 ft.
Found - 3/4" iron rod, N.85°39'21"E., 8.90 ft. (See C.S. file 46/38)
10/22/84

122

Howard Johnstone
For: Roseburg Lbr.
February 5, 1985
C. S. 58/296

1/4 Corner for Sections 34 and 35
Found - 1964 Cadastral brass cap.
16" D. fir, S.14°E., 58.1 ft. (1964)
New BT - 3 1/2" D. fir, S.41°W., 13.8 ft. scribed "1/4 S34 BT".
Corner is on east slope, partly buried, on the lower side of a dirt fill
from a cat fire trail road. Set steel fence post along side brass cap.
2/5/85

123

Center 1/4 Corner for Section 5
Set - 5/8" iron rod and alum. cap marked "LS 498"
BTs - 7" cedar bears N.24°W., 35.8 ft.
6" cedar bears N.17°E., 17.5 ft.

124

Center 1/4 Corner for Section 8
Set - 5/8" x 36" iron rod and alum. cap marked "LS 498"
BTs - 12" fir bears S.18°E., 71.5 ft.
22" fir bears N.8°W., 26.3 ft.

125

3/22/85

Township corner for Secs. 36; and Sec. 31 of T.31-6; Sec. 1 of T.32-7 and
Sec. 6 of T.32-6
Found - 5/8" iron rod with al. cap properly mkd. Ren. No. 74
9" D. fir now 15" bears N.57°W., 10.2 ft. has good scar and
is in good condition.
16" D. fir now 25" bears S.28°W., 42.2 ft. has a good scar and
is in good condition.
8" D. fir now 12" bears S.43°E., 44.6 ft. has a good scar and
is in good condition.
9" D. fir now a 13" stump with 10" above ground, bears N.72°E.,
56.2 ft.
New BT - 15" madrona bears N.15°E., 65.10 ft. mkd. T 31 S, R 6 W, S 31 BT.

126

John H. Markham Jr.
For: C & D Lbr.
Ray Brown, Party Chief
Jim Jenks, Witness
Jan. 6, 1986
C.S. 62/30