

Douglas County Surveyor's Record of
Government Corners Renewed

31 T. S. 8 R. W. W. M.

Section Corner to Sections 16, 17, 20, & 21. 8
 Found - Orig. 16", now 16" Fir Snag N.80°E. 6.6 ft. Shows faint
 scribing "16 BT 8".
 Orig. 10", now 26" Fir previously opened, shows good
 scribing "BT". Record bearing S.20°E., distance checks
 O.K. 15.8 ft.
 No trace of Corner Tree nor BT. to S.W. or BT. to N. W. 34
 Set Brass Cap at Corner Mkd: $\frac{S17}{S20} | \frac{S16}{S21}$ T31S R8W County Surveyor's
 Office, 1958
 New BT's: 34" R.Fir bears N.32½°W. 10.9 ft. scribed S17 T31S R8W CS BT.
 16" R.Fir bears S.53° W. 33.0 ft. scribed S20 T31S R8W CS BT.
 6" R.Fir bears N.35° E. 56.6 ft. scribed S16 CS BT.
 The Orig. S. E. BT. is O.K. I do not rescribe, bearing
 is S.11°E.

Fnd. O.K. by S. NESS DEC. 1981 MB9-65
 ¼ Section Corner to Sections 20 & 21. 9
 Found - Orig. 12", now 18" Fir West 14.5 ft., previously opened.
 Shows good scribing "¼ S".
 Now 20" Snag partly rotted, checks for Orig. bearing &
 distance, but I do not find scribing.
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1958,
 S20/S21 T31S R8W.
 New BT's: 8" Cedar bears S.10°E. 41.6 ft. scribed ¼ S21 CS BT.
 The Orig. S. E. BT. alive & in good condition.

FD OK, APR 1995, 1995-0046

Section Corner to Sections 28, 29, 32, & 33. *See 2002 BLM*
 Found - 18" x 10" x 14" Stone at Corner & 3 Orig. BT's: *Resurvey pg 2108*
 Orig. 10", now 14" Fir N.50°E. 9.9 ft., shows old scar. *2108*
 I do not open.
 Orig. 26", now 30" Fir S.45°E. 29.1 ft., shows faint but
 definite bark scribe "B T 33".
 Clump of Laurels that checks bearing & distance for S.W. BT.
 Orig. 8", now 15" Laurel N.45°W. 39.6 ft., shows good
 scar. I do not open.
 Set Brass Cap at Corner & Alongside Corner Stone, Marked Brass Cap:
 $\frac{S29}{S32} | \frac{S28}{S33}$ T31S R8W County Surveyor's office, 1958
 New BT's: Rescribe 14" R.Fir N.32°E. 10.7 ft. S28 T31S R8W CS BT.
 Rescribe 15" Laurel N.45°W. 36.7 ft. S29 T31S R8W CS BT.
 (Bark) Rescribe 30" R.Fir S.43°E. 30.2 ft. S33 T31S R8W CS BT.
 Bark Scribe 32" R.Fir S.83°W. 28.6 ft. S32 T31S R8W CS BT.

¼ Section Corner to Sections 32 & 33. 11
 Found - Both Orig. BT's.
 Orig. 15", now 30" R.Fir S.50°W. 32.3 ft. Shows good scar
 above & good bark scribe at base "BT".
 Orig. 15", now 30" Cedar N.35°E. 6.6 ft., shows good scars
 above & below. I do not open.
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1958
 ¼ S32 S33 T31S R8W.
 I rescribe 30" Cedar N.25°E. 7.0 ft. ¼ S33 CS BT.
 I rescribe 30" R.Fir S47°W. 29.1 ft. ¼ S32 CS BT.
 Note - - Byars apparently used slope distances to BT's. Byars
 measured to face of BT., we measure to center.

¼ Section Corner to Sections 29, & 32. *See 2002 BLM*
 Found - Both Orig. BT's & Stone at Corner. *Resurvey pg 2108*
 Orig. 56", now 60" Fir shows good bark scribing "¼ S",
 N.20°E. 11.2 ft. New BT 12
 Orig. 60", now 64" Sugar Pine shows good scar. I do not
 open. S.10°W. 27.7 ft.
 Set Brass Cap alongside Corner Stone Marked Cap: ¼ $\frac{S29}{S32}$ T31S R8W
 County Surveyor's Office, 1958
 New BT's; 6" R.Fir bears S.30°W. 53.0 ft. scribed ¼ S32 CS BT.
 16" R.Fir bears N.36°E. 47.7 ft. scribed ¼ S29 CS BT.

James W. Byron, Deputy
 M. Godfrey
 S. A. Blouw
 August, 1958
 C. S. File No. 49/109