

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 31 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

*FO. OK BY D. EDWARDS APR. 2004 M 144-32* **37**  
 $\frac{1}{4}$  Corner to Sections 19 and 30.  
 Found - 40" Fir, now down, N. 19° E. 15.9 ft., no trace of scribe marks.  
 40" Fir, now snag, S. 36° E. 19.1 ft., bark with old scribe marks.  
 Unrecorded 10" W. Fir S. 32° E. 15.0 ft. scribed with pocket  
 knife " $\frac{1}{4}$  1415 1957".  
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967  

T 31 S	R 8 W
$\frac{1}{4}$ S	19
S	30

 New BT's: 12" Cedar N. 82° E. 26.2 ft. mkd.  $\frac{1}{4}$  S19 CS BT.  
 10" W. Fir S. 65° W. 4.1 ft. mkd.  $\frac{1}{4}$  S 30 CS BT.

*See 2002 BLM Record* **38**  
 $\frac{1}{4}$  Corner to Sections 31 and 32.  
 Found - No trace of Corner Stone Monument nor N.E. BT. *lg 2108-7*  
 Orig. 12" Fir N. 80° W. 16.5 ft., now down, scribe " $\frac{1}{4}$ S",  
 previously opened.  
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967  

T 31 S	R 8 W
$\frac{1}{4}$ S	31
S	32

 New BT's: 14" D. Fir N. 42° W. 29.5 ft. mkd.  $\frac{1}{4}$  S31 CS BT.  
 19" D. Fir N. 57° E. 7.2 ft. mkd.  $\frac{1}{4}$  S32 CS BT.  
 Note - This corner lies approx. 100 ft. E. of Hayes Creek, on  
 steep, west slope.

*FO. OK BY D. EDWARDS APR. 2004 M 144-32* **39**  
 Sec. Corner to Sections 29 - 30 - 31 - 32.  
 Found - Orig. 30", now 38" D. Fir, N. 30° E. 29.6 ft., do not find scribe.  
 Orig. 36" D. Fir, now snag, S. 50° E. 26.4 ft.  
 Orig. 12", now 20" Laurel, S. 65° E. 29.0 ft., face is rotted out.  
 36", now 44" D. Fir, N. 73° W. 21.1 ft., shows faint but  
 definite bark scribe "S 8 S".  
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967  

T 31 S	R 8 W
S	30
S	29
S	31
S	32

 New BT's: 6" D. Fir N. 64° E. 21.9 ft. mkd. T31S R8W S29 CS BT.  
 16" D. Fir S. 11 $\frac{1}{2}$ ° W. 46.4 ft. mkd. T31S R8W S31 CS BT.  
 15" D. Fir S. 17° E. 49.4 ft. mkd. T31S R8W S32 CS BT.  
 Rescrbd: 44" D. Fir N. 73° W. 21.1 ft. mkd. T31S R8W S30 CS BT.  
 Note - This corner lies 100 ft. west & 248 ft. N. of Hayes Creek.

**40**  
 $\frac{1}{4}$  Corner to Sections 33 and 34.  
 Found - 24" D. Fir, now down, S. 70° E. 12.5 ft., faint bark  
 scribe "BT", other marks visible but not legible.  
 16" D. Fir, now down, west 18.5 ft. This tree previously  
 opened but lying on face.  
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967  

T 31 S	R 8 W
$\frac{1}{4}$ S	33
S	34

 New BT's: 24" Fir S. 1 $\frac{1}{2}$ ° W. 129.8 ft. mkd.  $\frac{1}{4}$  S33 CS BT.  
 46" Fir N. 47° E. 52.0 ft. mkd.  $\frac{1}{4}$  S34 CS BT.  
 Note - This cor. lies about 200 ft. S. & 60 ft. W. of ridge top.

**41**  
 Sec. Corner to Sections 23 - 24 - 25 - 26.  
 Found - No trace of Corner Stone.  
 Orig. 38", now 43" D. Fir S. 35° W. 16.5 ft., bark scribe visible.  
 Orig. 6", now 8" Live Oak, N. 20° E. 24.5 ft., shows scar.  
 Orig. 8", now 12" Maple S. 65° E. 23.1 ft., shows good scar.  
 Orig. 14", now 24" D. Fir N. 24° W. 25.7 ft., bark badly burnt.  
 Distances all meet at point, but would have had to use slope dist.  
 on the 8" Maple, S. 65° E. 23.1 ft., & 14" D. Fir N. 24° W. 30.3 ft.  
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967  

T 31 S	R 8 W
S	23
S	24
S	26
S	25

 Reblazed & Rescribed: 24" D. Fir N. 24° W. 25.7 ft. mkd. T31S R8W S23 CS BT.  
 8" Live Oak N. 20° E. 24.5 ft. mkd. T31SR8WS24 CS BT.  
 Note - This corner lies on steep, north slope about 300 ft. from  
 Cow Creek Road, yellow tag on road.

John M. Powell  
 Frank Jones & C. Stone  
 January, 1967  
 C. S. File No. 54/36

FO. B.C. &  
 7-BTS.  
 1972 ADMIN  
 SURVEY -  
 SEE GIS  
 FILES

RE-RENEWED CORNER