

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued)

New BT: 5" D. Fir S. $14\frac{1}{2}^\circ$ W. 19.8 ft. mkd. $\frac{1}{2}$ S 2 CS BT.
Reblzd. & Rescrbd: 8" Laurel N. 6° W. 17.2 ft. mkd. T30S R8W S35 CS BT.
12" Laurel S. $78\frac{1}{2}^\circ$ E. 13.2 ft. mkd. T31S R8W S1 CS BT.
9" Laurel N. 51° E. 17.9 ft. mkd. T30S R8W S36 CS BT.

RE-RENEWED SEE CORNER NO. #62 47

48

Sec. Cor. to Sections 10 - 11 - 14 - 15.
Found - GLO Brass Cap at Sec. Cor., properly mkd. in 1961.
11" W. Fir S. 35° W. 21.5 ft., shows good scar.
8" W. Fir S. 35° E. 16.2 ft., scribe visible, "T31S R8W".
12" W. Fir N. $20\frac{1}{2}^\circ$ E. 15.6 ft., scribe visible, "T31SR8W S11BT".
Orig. 10" Cedar, now down, N. 72° W. 21.1 ft., good scar.
New BT: 28" Hemlock N. 58° W. 40.0 ft. mkd. T31S R8W S10 CS BT.

49

$\frac{1}{4}$ Corner to Sections 11 and 14.
Found - Orig. 20" D. Fir S. 5° W. 5.9 ft., now stob, with bark scribe.
Orig. 8" Chinquapin, now 11", N. 70° W. 6.6 ft., good face.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 31 S R 8 W
Office S 11
1967 S 14 #77
New BT's: 24" W. Fir S. 42° W. 28.4 ft. mkd. $\frac{1}{4}$ S14 CS BT.
12" D. Fir N. 21° W. 12.4 ft. mkd. $\frac{1}{4}$ S11 CS BT.
Note - Corner lies on top spur, course E. & W.

RE-RENEWED SEE CORNER NO. #77

50

$\frac{1}{4}$ Corner to Sections 7 and 8.
Found - GLO Brass Cap at $\frac{1}{4}$ Corner, properly marked in 1962.
Orig. 19" Cedar N. 67° W. 14.1 ft., scribe visible but faint.
1962 - 34" D. Fir N. 48° W. 22.4 ft. Tree has about half of
top broken out, scribe visible " $\frac{1}{4}$ S7 BT".
12" D. Fir, S. 65° W. 27.7 ft., shows pitched over
scribing, not legible.
New BT: 31" D. Fir S. 59° W. 26.2 ft., mkd. $\frac{1}{4}$ S 7 CS BT.

51

$\frac{1}{4}$ Corner to Sections 13 and 14.
Found - Un recorded $\frac{3}{4}$ " Iron Pipe at corner.
Orig. 18" D. Fir, now down, East 17.2 ft., faint bark scribe.
No evidence of N.W. BT.
Set - Brass Cap at $\frac{1}{4}$ Cor. Mkd: County Surveyor's T 31 S R 8 W
Office, 1967 $\frac{1}{4}$ S 14/S 13
New BT's: 9" Cedar N. 36° W. 15.2 ft. mkd. $\frac{1}{4}$ S14 CS BT.
6" D. Fir N. 50° E. 9.5 ft. mkd. $\frac{1}{4}$ S13 CS BT.

52

$\frac{1}{4}$ Corner to Sections 25 and 36.
Found - Orig. 30" Cedar, now 56", S. 60° W. 37.0 ft., bark scribe
visible " $\frac{1}{4}$ S BT".
Orig. 36" Fir, now down & burned.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 31 S R 8 W
Office $\frac{1}{4}$ S 25
1967 S 36
New BT's: 7" D. Fir S. 50° W. 18.6 ft. mkd. $\frac{1}{4}$ S36 CS BT.
16" D. Fir N. 17° E. 44.0 ft.
This cor. lies on E. slope about 330 ft. from ridge top, yellow
tag on line west of corner.

53

$\frac{1}{4}$ Corner to Sec. 36, T31-⁹W. & Sec. 31, T31-⁸N. ^{JK 11/87}
Found - $\frac{7}{8}$ " Drill Steel at $\frac{1}{4}$ Corner. See Ren. No. 16.
Orig. 24" D. Fir, now 30", N. 42° E. 15.8 ft. orig. bark
scribe " $\frac{1}{4}$ " and rescribe " $\frac{1}{4}$ S BT". This BT. is leaning
badly with windfall againt it.
6", now 8" D. Fir, N. 61° W. 26.1 ft., shows good scar.
New BT; 6" D. Fir S. 68° E. 4.8 ft. mkd. $\frac{1}{4}$ S31 CS BT.

John M. Powell
Frank Jones & C. Stone
January, 1967
C. S. File No. 54/36