

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T.S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

65

1/4 Corner to Sec. 1, T31-8 and Sec. 6, T31-7.
Found - 1918 Gov't. Brass Cap under large Fir Windfall.
Bearing Trees per 1918 Retracement.
40" Pine S. 52° E. 39 lks., shows scribe.
44" Fir N. 33° W. 49 lks., shows scar.
This corner found by Don E. Garrett, July, 1972.
See Note in C. S. File No. 54/36.

66

Section corner to Secs. 13 & 24, T31-8 and Secs. 18 & 19, T31-7
Found - A diligent search was made yielding no acceptable evidence
of adequate corner monumentation.
Set - 36" Aluminum cap, iron pipe, 24" into the ground.
BT's - 8" Ponderosa pine, scribed on the wood bearing S23E, 21.5 ft.
8" Fir, scribed on the wood, bearing N.62°E., 19.5 ft.
No other acceptable accesories available.
SEE REN. #74

67

Section corner for Sections 14-13-23-24.
Found - A diligent search was made yielding no acceptable evidence
of adequate corner monumentation.
Set - 36" Aluminum cap, iron pipe, 24" into the ground.
BT's - 18" Fir, scribed on the wood bearing S.3°E., 28.5 ft.
11" Madrone, scribed on the wood bearing S.57°W., 2 ft.
13" Fir, scribed on the wood bearing N.35°W., 10 ft.
9" Madrone scribed on the wood bearing N.27½°E., 10.5 ft.

January, 1973

68

1/4 Cor. for Sec. 35 & 36. (not of record)
Found - 28" D.Fir with initials "F". Chopped into north
side of tree. We open & find no evidance of
scribing.
40" Sugar Pine with initials "BT" chopped into north fa
face, no scar visible, chopped initials not old.
A point can be located which causes both orig. bearings and
distances to fit reasonably well. Also stationing on compass
line from N sec. cor. indicates distance of 2640 + to location.
no trace of bark scribe on either tree. S.77°W., 5.3 ft. to
fir (orig. S.75°W., 5.3 ft.) S.73°E. 12.2 ft to pine (orig.
S.70°E., 11.9 ft.) Call to ravine to north misses by about
100 ft. I do not monument

1/21/74

69

1/4 Corner to Sec.22 and Sec.23
Found- A Rock 2'x1.5'x1.5' above ground. 1/4 on northerly face. Stone is
firmly in place and lies in Darby Creek.
A fir 24(now 37) inch dia. bears N42°E.,26.4 ft. Tree is bark scribed "1/4
S BT"
A fir 36(now 51) inch dia. bears N36°W.,28.3 ft.(rec.N40°W.,29.7 ft.) Tree
is bark scribed " 1/4 S BT T"
Renewal-Chisled "X" on flat surface of rock bears S43°E.,30.9ft. "X" is approx.
2 1/4" high. Flat surface on large boulder faces WNW and measures approx.
9" high by 32" long, and is approx. 14 ft. east of center of Darby CK.
A D. fir 6" dia. bears S58°W.,51.9 ft. Tree Double blazed and scribed
"1/4 S22 CS BT" Mag. Dec. 20° E., 12/24/75

70

1/4 Corner for Secs. 28 and 33
Found - Douglas County Surveyors Office brass cap 18" above ground and
loose, marked County Surveyors Office T31S R8W 1/4 S28, S33
1967. Ren. #27
From Which:
An orig. 57" now 63" D. Fir, bears N.55°E. 29.1 ft with visible
scribe "1/4 S33 CS BT in unhealed double blaze. BT alive and well.
9" now 12" Laurel bears South, 26.9 ft with visible scribe "1/4
S33 CS BT" in unhealed double blaze. BT alive and well
Note: Reset cap at corner point firm and 4" above ground.

3/11/76

U.S. Plywood Corporation
Dennis A. Crowe
M 47-60 C.S. File 55/279
January, 1973

G. Langlitz
P. Carle
Surveyors Office
C.S. 56/43
1/21/74

L.E. Monrean
P.L.E.
CS 57/39
12/24/75

M. Lenora Ladig
L.E. Monrean
Surveyors Office
March 11, 1976
C.S. 59/8

RE-RENEWED, SEE CORNER NO. #74
RE-RENEWED, SEE CORNER NO. #90
RE-RENEWED, SEE CORNER NO. #82